



1  
00:01:08,870 --> 00:01:05,000  
welcome I'm very pleased to introduce

2  
00:01:12,170 --> 00:01:08,880  
mr. rich Barrett and the fastener design

3  
00:01:14,570 --> 00:01:12,180  
course rich as you may well know it's a

4  
00:01:15,470 --> 00:01:14,580  
NASA engineer he has been an engineer

5  
00:01:18,200 --> 00:01:15,480  
for 40 years

6  
00:01:22,880 --> 00:01:18,210  
and up with the Lewis Research Center

7  
00:01:25,570 --> 00:01:22,890  
for 34 of those 40 years he's advised in

8  
00:01:30,950 --> 00:01:25,580  
the materials and the materials of

9  
00:01:33,859 --> 00:01:30,960  
fasteners and materials is well sought

10  
00:01:37,850 --> 00:01:33,869  
by industry and by other government

11  
00:01:41,050 --> 00:01:37,860  
agencies besides NASA he's faster design

12  
00:01:46,219 --> 00:01:41,060  
Manuel has received widespread acclaim

13  
00:01:48,800 --> 00:01:46,229

and distribution and it led to his

14

00:01:51,190 --> 00:01:48,810

earning of the federal laboratory

15

00:01:53,930 --> 00:01:51,200

consortium award for technology transfer

16

00:01:57,080 --> 00:01:53,940

all the awards that mr. Barrett has

17

00:02:00,590 --> 00:01:57,090

received our de NASA exceptional service

18

00:02:03,680 --> 00:02:00,600

medal and the Eldar statement of a VA

19

00:02:06,200 --> 00:02:03,690

ssin award with not much more to say

20

00:02:09,470 --> 00:02:06,210

here is mr. rich Barrett thank you very

21

00:02:12,949 --> 00:02:09,480

much thank you Mario for the nice

22

00:02:17,270 --> 00:02:12,959

introduction we will be presenting in

23

00:02:21,470 --> 00:02:17,280

this course one of the it will be the

24

00:02:23,840 --> 00:02:21,480

most extensive coverage is fastener

25

00:02:30,440 --> 00:02:23,850

design that I have done to date because

26

00:02:35,380 --> 00:02:30,450

it will be a about 385 pages of

27

00:02:37,940 --> 00:02:35,390

presentation so we will move into it and

28

00:02:40,430 --> 00:02:37,950

unless they say in the candy commercial

29

00:02:43,250 --> 00:02:40,440

you're not going anywhere for a while so

30

00:02:46,509 --> 00:02:43,260

relax and we'll cover everything we can

31

00:02:50,840 --> 00:02:46,519

on fasteners thank you

32

00:02:52,850 --> 00:02:50,850

so to start out with I'd like to give

33

00:02:56,750 --> 00:02:52,860

you some acknowledgments year of the

34

00:03:00,620 --> 00:02:56,760

people that had a hand in this will

35

00:03:03,350 --> 00:03:00,630

Harkins and Mario Castro Mario is my

36

00:03:07,730 --> 00:03:03,360

boss here at NASA Lewis will Harkins

37

00:03:10,160 --> 00:03:07,740

from NASA headquarters sponsored this

38

00:03:11,940 --> 00:03:10,170

course funded quite a bit of it

39

00:03:14,699 --> 00:03:11,950

so this will

40

00:03:18,300 --> 00:03:14,709

used by all of the different NASA

41

00:03:20,309 --> 00:03:18,310

centers Harold Casper from Analects

42

00:03:22,800 --> 00:03:20,319

corporation he wrote some of the

43

00:03:24,750 --> 00:03:22,810

sections and found some information for

44

00:03:28,260 --> 00:03:24,760

the others as well as editing the entire

45

00:03:30,600 --> 00:03:28,270

course John Bickford who is the leading

46

00:03:33,720 --> 00:03:30,610

author actually in the fastener field

47

00:03:35,670 --> 00:03:33,730

he is the editor-in-chief of a book

48

00:03:38,070 --> 00:03:35,680

which I was contributing author horribly

49

00:03:40,710 --> 00:03:38,080

published the end of the year I used a

50

00:03:44,100 --> 00:03:40,720

lot of John's stuff from his book on

51  
00:03:47,900 --> 00:03:44,110  
fastener design in this course being

52  
00:03:50,820 --> 00:03:47,910  
blend off from Clemson University and

53  
00:03:53,699 --> 00:03:50,830  
he's actually chairman of the bolting

54  
00:03:56,130 --> 00:03:53,709  
technology Council which is a council

55  
00:04:00,180 --> 00:03:56,140  
dedicated to furthering the knowledge on

56  
00:04:06,090 --> 00:04:00,190  
fastener design has contributed some and

57  
00:04:09,210 --> 00:04:06,100  
Betsy dela Cruz who did all of the

58  
00:04:11,160 --> 00:04:09,220  
typing retyping running someone to get

59  
00:04:13,740 --> 00:04:11,170  
this thing together and we just about

60  
00:04:15,150 --> 00:04:13,750  
ran out of time but that's why we did

61  
00:04:17,729 --> 00:04:15,160  
not give it before and I say it's

62  
00:04:20,340 --> 00:04:17,739  
approximately a two-day course then

63  
00:04:22,920 --> 00:04:20,350

rehomeing from atf corporation edited the

64

00:04:24,719 --> 00:04:22,930

entire course and had some very helpful

65

00:04:26,790 --> 00:04:24,729

comments so with that in mind we'll

66

00:04:31,110 --> 00:04:26,800

proceed with the little introductory

67

00:04:34,500 --> 00:04:31,120

material now there's a statement

68

00:04:37,380 --> 00:04:34,510

everybody knows about bolts and nuts but

69

00:04:40,529 --> 00:04:37,390

do they really know about bolts and nuts

70

00:04:41,969 --> 00:04:40,539

sometimes we oversimplify things because

71

00:04:44,580 --> 00:04:41,979

we think because it's something that a

72

00:04:50,900 --> 00:04:44,590

kid took off the wagon that it's simple

73

00:04:57,560 --> 00:04:54,460

the Joseph Dudley who is a

74

00:05:00,470 --> 00:04:57,570

vice-president of automotive marketing

75

00:05:03,950 --> 00:05:00,480

for nighlok passenger corporation gave

76  
00:05:06,350 --> 00:05:03,960  
these two quotes 75% of the assembly

77  
00:05:10,630 --> 00:05:06,360  
labor cost of an automobile is spent on

78  
00:05:13,400 --> 00:05:10,640  
fasteners and 80 to 85 percent of all

79  
00:05:15,200 --> 00:05:13,410  
automobile recalls or fastener related

80  
00:05:16,760 --> 00:05:15,210  
now that gives you an idea about the

81  
00:05:18,800 --> 00:05:16,770  
importance of fasteners and putting

82  
00:05:20,840 --> 00:05:18,810  
things together and of course some of

83  
00:05:22,730 --> 00:05:20,850  
you remember on the shuttle recently

84  
00:05:24,620 --> 00:05:22,740  
when they had to cancel a spacewalk

85  
00:05:26,810 --> 00:05:24,630  
because a couple screws came loose and

86  
00:05:27,470 --> 00:05:26,820  
fell out in the gears they couldn't get

87  
00:05:31,370 --> 00:05:27,480  
the door open

88  
00:05:34,610 --> 00:05:31,380



so things do go wrong like that here is

89

00:05:37,370 --> 00:05:34,620

a summary of the causes for joint

90

00:05:39,170 --> 00:05:37,380

failures and NASA's Skylab program some

91

00:05:42,250 --> 00:05:39,180

of you say Ron Roman Chuck would

92

00:05:46,790 --> 00:05:42,260

remember that he was here that that poem

93

00:05:50,120 --> 00:05:46,800

back when that happened and the thing

94

00:05:55,060 --> 00:05:50,130

that surprised me in this is the poor

95

00:05:59,000 --> 00:05:55,070

design improper assembly here

96

00:06:02,030 --> 00:05:59,010

24% poor design 28% for improper

97

00:06:05,330 --> 00:06:02,040

assembly and yet only 10% for bad parts

98

00:06:08,360 --> 00:06:05,340

and the 24% for parts damaged in

99

00:06:12,020 --> 00:06:08,370

handling and the wrong preload 14% now

100

00:06:16,460 --> 00:06:12,030

we have been hearing in the news for the

101  
00:06:19,700 --> 00:06:16,470  
past several years about the counterfeit

102  
00:06:21,440 --> 00:06:19,710  
fasteners and all of that and so it's

103  
00:06:25,100 --> 00:06:21,450  
gotten quite a bit of publicity and it

104  
00:06:28,520 --> 00:06:25,110  
should but it still boils down to the

105  
00:06:29,380 --> 00:06:28,530  
fact that the designer has more to do

106  
00:06:32,660 --> 00:06:29,390  
with it

107  
00:06:35,750 --> 00:06:32,670  
then the manufacture of the fasteners

108  
00:06:39,800 --> 00:06:35,760  
now here is a something from John

109  
00:06:42,200 --> 00:06:39,810  
Bickford book on a bolted joint just a

110  
00:06:44,780 --> 00:06:42,210  
spring concept because actually you

111  
00:06:47,120 --> 00:06:44,790  
don't think of it this way but a the

112  
00:06:49,580 --> 00:06:47,130  
joint material itself is a big heavy

113  
00:06:51,680 --> 00:06:49,590

spring and you're compressing it with

114

00:06:54,700 --> 00:06:51,690

small Springs which are fasteners and we

115

00:06:57,710 --> 00:06:54,710

even get into joint stiffness and

116

00:07:00,530 --> 00:06:57,720

stiffness ratios and so on now here is a

117

00:07:03,160 --> 00:07:00,540

summary of the different types of heads

118

00:07:09,820 --> 00:07:03,170

on fasteners just to

119

00:07:11,710 --> 00:07:09,830

for your reference and these this is use

120

00:07:13,390 --> 00:07:11,720

some in the aerospace field although

121

00:07:16,960 --> 00:07:13,400

it's not that common but of course the

122

00:07:21,820 --> 00:07:16,970

flat the socket head over here and the

123

00:07:24,490 --> 00:07:21,830

hex all of these are very common the

124

00:07:28,150 --> 00:07:24,500

carriage bolt of course that one is I

125

00:07:29,980 --> 00:07:28,160

guess dates back to the building wagons

126  
00:07:31,840 --> 00:07:29,990  
when you drilled a hole and you pounded

127  
00:07:34,270 --> 00:07:31,850  
that one in and the square part under

128  
00:07:36,640 --> 00:07:34,280  
the head there locked it in place where

129  
00:07:38,260 --> 00:07:36,650  
you put the nut on so Betsy that's how

130  
00:07:40,620 --> 00:07:38,270  
you build wagons in case you ever go

131  
00:07:45,280 --> 00:07:40,630  
into it

132  
00:07:49,750 --> 00:07:45,290  
here's one on the internal drive systems

133  
00:07:52,060 --> 00:07:49,760  
and you can't read it too well on on

134  
00:07:54,100 --> 00:07:52,070  
this one but over on the view graphs I

135  
00:07:57,730 --> 00:07:54,110  
think you can read them and a lot of

136  
00:08:01,120 --> 00:07:57,740  
these are common only to the aerospace

137  
00:08:05,740 --> 00:08:01,130  
world like for instance something like

138  
00:08:12,040 --> 00:08:05,750

this or something like the Tri wing type

139

00:08:15,520 --> 00:08:12,050

here these are used only by certain

140

00:08:19,180 --> 00:08:15,530

manufacturers the torques down here is

141

00:08:22,720 --> 00:08:19,190

very common in the automotive field that

142

00:08:26,590 --> 00:08:22,730

one I thought that I'm always looking at

143

00:08:29,920 --> 00:08:26,600

conspiracy theories of designers and I

144

00:08:32,890 --> 00:08:29,930

thought the torques was developed by the

145

00:08:34,900 --> 00:08:32,900

automotive people just to make things

146

00:08:37,450 --> 00:08:34,910

more difficult on working on your car

147

00:08:40,420 --> 00:08:37,460

but I found out that the reason they use

148

00:08:44,290 --> 00:08:40,430

it was that it centers better than the

149

00:08:48,190 --> 00:08:44,300

Philips which various types of Philips

150

00:08:51,060 --> 00:08:48,200

there and will not come out as much so

151

00:08:55,420 --> 00:08:51,070

therefore it will work better in

152

00:08:59,890 --> 00:08:55,430

automated assembly now getting into the

153

00:09:02,140 --> 00:08:59,900

agenda for this program see we have a

154

00:09:06,490 --> 00:09:02,150

lot of stuff and each one of these is a

155

00:09:08,710 --> 00:09:06,500

section number in your handout so we

156

00:09:13,150 --> 00:09:08,720

have a lot of stuff here to cover I

157

00:09:16,250 --> 00:09:13,160

won't go over all of these but I'll

158

00:09:17,900 --> 00:09:16,260

point out that at the end we have a do

159

00:09:20,960 --> 00:09:17,910

and don'ts and frequently asked

160

00:09:23,210 --> 00:09:20,970

questions sections that that will answer

161

00:09:25,310 --> 00:09:23,220

some of the various questions that I

162

00:09:30,850 --> 00:09:25,320

have been asked from time to time by

163

00:09:34,520 --> 00:09:30,860

people so we'll move on into materials

164

00:09:40,070 --> 00:09:34,530

and this this I feel is a very important

165

00:09:42,410 --> 00:09:40,080

section because you need to choose the

166

00:09:45,080 --> 00:09:42,420

right material to begin with or you're

167

00:09:47,330 --> 00:09:45,090

dead in the water on a design now

168

00:09:48,590 --> 00:09:47,340

fasteners can be made for many materials

169

00:09:51,110 --> 00:09:48,600

but most of them that we're familiar

170

00:09:54,860 --> 00:09:51,120

with are made out of steel the the

171

00:09:58,040 --> 00:09:54,870

hardware store tape that are made out of

172

00:10:01,400 --> 00:09:58,050

what's called low carbon steel then the

173

00:10:02,750 --> 00:10:01,410

alloy steel for the greatest fives and

174

00:10:05,180 --> 00:10:02,760

eights that we use around here in a

175

00:10:07,790 --> 00:10:05,190

socket head cap screw titanium and

176

00:10:09,860 --> 00:10:07,800

aluminum bolts have limited usage in the

177

00:10:14,840 --> 00:10:09,870

aerospace industry but on the other hand

178

00:10:18,770 --> 00:10:14,850

aluminum and titanium are used a lot on

179

00:10:20,600 --> 00:10:18,780

the aircraft design particularly since

180

00:10:25,880 --> 00:10:20,610

you have aluminum skins on most

181

00:10:29,260 --> 00:10:25,890

airplanes and you want the rivets to be

182

00:10:31,910 --> 00:10:29,270

of the same material because of the

183

00:10:35,680 --> 00:10:31,920

differential temperature giving you

184

00:10:39,740 --> 00:10:35,690

problems on expansion and contraction so

185

00:10:46,400 --> 00:10:39,750

now the alloy steel fasteners you can

186

00:10:48,230 --> 00:10:46,410

get them up to 300 ksi ksi being a

187

00:10:51,890 --> 00:10:48,240

thousand psi so it's three hundred

188

00:10:54,530 --> 00:10:51,900



thousand psi strength levels but I'll

189

00:10:56,630 --> 00:10:54,540

try to point out to you here that in

190

00:11:00,560 --> 00:10:56,640

most cases you really don't want to do

191

00:11:03,020 --> 00:11:00,570

that okay now carbon Steel's

192

00:11:04,880 --> 00:11:03,030

are not corrosion resistant so they

193

00:11:07,540 --> 00:11:04,890

usually have to have some kind of a

194

00:11:11,150 --> 00:11:07,550

coating to protect them from rusting and

195

00:11:14,750 --> 00:11:11,160

the stainless steels you can get in all

196

00:11:17,810 --> 00:11:14,760

all varieties of both heat treatable and

197

00:11:21,320 --> 00:11:17,820

non heat treatable alloys with the

198

00:11:23,600 --> 00:11:21,330

tensile strengths of 70 ksi to 260 the

199

00:11:25,660 --> 00:11:23,610

seventy being the ordinary 300 series

200

00:11:29,079 --> 00:11:25,670

stainless that we use here all the time

201  
00:11:33,790 --> 00:11:29,089  
and the 260 or

202  
00:11:37,449 --> 00:11:33,800  
talking work-hardened inconel 718 or

203  
00:11:42,280 --> 00:11:37,459  
eight to eighty six and note that the

204  
00:11:45,400 --> 00:11:42,290  
400 series materials contain only 12%

205  
00:11:48,280 --> 00:11:45,410  
chromium which will allow them to rust

206  
00:11:51,009 --> 00:11:48,290  
so if you're building something that you

207  
00:11:54,670 --> 00:11:51,019  
want it to look pretty the 400 series

208  
00:11:56,920 --> 00:11:54,680  
stainless would not be advisable and on

209  
00:12:00,910 --> 00:11:56,930  
some of these subsequent tables we will

210  
00:12:04,059 --> 00:12:00,920  
show various materials but just go on to

211  
00:12:09,460 --> 00:12:04,069  
the in order here on the selection and

212  
00:12:11,319 --> 00:12:09,470  
materials you should use common fastener

213  
00:12:14,379 --> 00:12:11,329

materials strength levels and coatings

214

00:12:17,619 --> 00:12:14,389

if you can there's no sense in over

215

00:12:19,720 --> 00:12:17,629

killing on any design because it can

216

00:12:22,840 --> 00:12:19,730

just cost you money and time usually

217

00:12:24,939 --> 00:12:22,850

weight savings versus cost must also be

218

00:12:26,499 --> 00:12:24,949

evaluated for flight articles and there

219

00:12:30,160 --> 00:12:26,509

you do spend a lot of money to save a

220

00:12:32,590 --> 00:12:30,170

little bit of weight galvanic and stress

221

00:12:35,559 --> 00:12:32,600

corrosion tolerance levels have to be

222

00:12:38,530 --> 00:12:35,569

established and checked out and of

223

00:12:40,329 --> 00:12:38,540

course the operating temperatures has to

224

00:12:44,829 --> 00:12:40,339

have to be determined before the

225

00:12:47,919 --> 00:12:44,839

material is chosen both the high and the

226

00:12:50,290 --> 00:12:47,929

low to make sure that the materials are

227

00:12:52,809 --> 00:12:50,300

compatible in the entire range and then

228

00:12:54,910 --> 00:12:52,819

the type of loading static or fatigue

229

00:13:01,509 --> 00:12:54,920

loading is also a factor in the material

230

00:13:05,739 --> 00:13:01,519

selection now as far as availability and

231

00:13:07,509 --> 00:13:05,749

materials the carbon steel fastener

232

00:13:11,230 --> 00:13:07,519

materials of course everybody's familiar

233

00:13:15,939 --> 00:13:11,240

with the 10 10 10 20 that we use around

234

00:13:18,449 --> 00:13:15,949

here and that is just a iron with carbon

235

00:13:24,129 --> 00:13:18,459

in it a few impurities and it's up to

236

00:13:27,220 --> 00:13:24,139

0.28 carbon now that's I'll explain this

237

00:13:30,369 --> 00:13:27,230

further in another chart but the carbon

238

00:13:33,059 --> 00:13:30,379

content is usually called out in points

239

00:13:37,030 --> 00:13:33,069

and it's actually hundreds of a percent

240

00:13:40,780 --> 00:13:37,040

so so this is 0.28 here it's hundreds of

241

00:13:43,490 --> 00:13:40,790

the percent of carbon and you need for

242

00:13:45,440 --> 00:13:43,500

heat treating unless you add

243

00:13:50,810 --> 00:13:45,450

something like boron to the material you

244

00:13:52,580 --> 00:13:50,820

need about 25 points of carbon really to

245

00:13:54,380 --> 00:13:52,590

get it the heat treat properly if you're

246

00:13:56,810 --> 00:13:54,390

going to heat treat a fastener now the

247

00:13:59,840 --> 00:13:56,820

the great files and great eights are in

248

00:14:01,430 --> 00:13:59,850

the 28 to 55 point

249

00:14:04,820 --> 00:14:01,440

carbon range so that their heat

250

00:14:07,670 --> 00:14:04,830

treatable and the the eights of course

251  
00:14:09,430 --> 00:14:07,680  
have other alloying elements in them in

252  
00:14:13,010 --> 00:14:09,440  
order that you can bring them up to the

253  
00:14:16,580 --> 00:14:13,020  
strengths that you want and 4037 is one

254  
00:14:17,900 --> 00:14:16,590  
of the common materials for grade 8 now

255  
00:14:20,900 --> 00:14:17,910  
here's something I just wanted to point

256  
00:14:22,580 --> 00:14:20,910  
out to you that the Charlie Wilson from

257  
00:14:24,440 --> 00:14:22,590  
the industrial fasteners Institute's

258  
00:14:27,710 --> 00:14:24,450  
been trying to get this change for years

259  
00:14:32,530 --> 00:14:27,720  
but it's still in there in jave SAE J

260  
00:14:38,290 --> 00:14:32,540  
429 spec which is for grade 8 fasteners

261  
00:14:43,010 --> 00:14:41,480  
manufacturer to furnish these and 1045

262  
00:14:46,910 --> 00:14:43,020  
plain carbon steel

263  
00:14:48,590 --> 00:14:46,920

if the buyer agrees to it well the only

264

00:14:51,170 --> 00:14:48,600

thing is if the buyer doesn't know he's

265

00:14:53,900 --> 00:14:51,180

agreeing to it he can get one that will

266

00:14:55,790 --> 00:14:53,910

not have very good impact resistance and

267

00:14:58,490 --> 00:14:55,800

we had a problem that we were in on one

268

00:15:01,579 --> 00:14:58,500

time with the Army on some Abrams tanks

269

00:15:03,470 --> 00:15:01,589

that when they fired the cannon on him

270

00:15:09,440 --> 00:15:03,480

it broke the bolts on the turret because

271

00:15:16,329 --> 00:15:09,450

it remained out 1045 steel okay moving

272

00:15:19,300 --> 00:15:16,339

on not the ASTM fasteners are used

273

00:15:23,060 --> 00:15:19,310

primarily in the construction industry

274

00:15:27,320 --> 00:15:23,070

so since a lot of you are not familiar

275

00:15:30,140 --> 00:15:27,330

with them and I'm not that familiar with

276

00:15:33,020 --> 00:15:30,150

them either I put in some equivalency

277

00:15:36,670 --> 00:15:33,030

here like the a 307 is a great one in

278

00:15:41,840 --> 00:15:36,680

the sae that we're familiar with and 449

279

00:15:45,410 --> 00:15:41,850

354 and now they the a 193 they're the

280

00:15:49,280 --> 00:15:45,420

the B five six seven sixteen and also

281

00:15:51,980 --> 00:15:49,290

the b 8 stainless steel those are used a

282

00:15:56,300 --> 00:15:51,990

lot for the pipe flanges that we design

283

00:15:57,350 --> 00:15:56,310

around here so so a lot of you are

284

00:16:01,040 --> 00:15:57,360

probably familiar with

285

00:16:06,889 --> 00:16:01,050

them the 320 is an alloy steel for low

286

00:16:09,710 --> 00:16:06,899

temperatures and 325 is a sort of

287

00:16:11,780 --> 00:16:09,720

equivalent to agreed agreed eight in

288

00:16:15,290 --> 00:16:11,790



strength and then the 490 is the highest

289

00:16:20,740 --> 00:16:15,300

strength of the construction type

290

00:16:23,540 --> 00:16:20,750

fasteners now

291

00:16:25,340 --> 00:16:23,550

stainless steel which is a crest you'll

292

00:16:27,560 --> 00:16:25,350

see that designation for it corrosion

293

00:16:31,490 --> 00:16:27,570

resisting steel stainless steel is the

294

00:16:34,970 --> 00:16:31,500

same generic terminology and the super

295

00:16:37,280 --> 00:16:34,980

alloy materials now the 300 series that

296

00:16:39,949 --> 00:16:37,290

we're familiar with around here you get

297

00:16:43,460 --> 00:16:39,959

it up to about 80 ksi because it's not a

298

00:16:44,990 --> 00:16:43,470

heat treatable material so the only way

299

00:16:47,180 --> 00:16:45,000

that you can get the strength opponent

300

00:16:48,769 --> 00:16:47,190

is by work hardening it and informing it

301

00:16:51,920 --> 00:16:48,779

that's about the strength that they get

302

00:16:53,810 --> 00:16:51,930

starting with annealed material eight to

303

00:16:58,360 --> 00:16:53,820

eighty six we use all the time in the

304

00:17:02,180 --> 00:16:58,370

aerospace world up to 160 ksi it is a

305

00:17:05,449 --> 00:17:02,190

very common aerospace material and you

306

00:17:09,220 --> 00:17:05,459

can you can get it in metric by special

307

00:17:13,610 --> 00:17:09,230

order in a 286 the 400 series is

308

00:17:18,169 --> 00:17:13,620

available in limited strengths up to 125

309

00:17:20,780 --> 00:17:18,179

ksi and it's also available in metric

310

00:17:24,079 --> 00:17:20,790

which I will show you further on now the

311

00:17:26,740 --> 00:17:24,089

super alloy is here these are the ones

312

00:17:29,120 --> 00:17:26,750

that you guys come around looking for

313

00:17:33,230 --> 00:17:29,130

when you want something for a

314

00:17:35,000 --> 00:17:33,240

particularly stringent environmental set

315

00:17:37,570 --> 00:17:35,010

of conditions like high temperature

316

00:17:43,760 --> 00:17:37,580

corrosion and so on these are all

317

00:17:45,260 --> 00:17:43,770

stainless --is here in well titanium of

318

00:17:50,990 --> 00:17:45,270

course is very corrosion resistant also

319

00:17:53,120 --> 00:17:51,000

the MP 35 n an MP 159 are made by SPS

320

00:17:56,030 --> 00:17:53,130

they have the patent on the material and

321

00:17:59,950 --> 00:17:56,040

they are super corrosion resistant and

322

00:18:02,659 --> 00:17:59,960

high-strength up to about 220 ksi

323

00:18:05,540 --> 00:18:02,669

inconel at 750 s used for high

324

00:18:09,680 --> 00:18:05,550

temperature and the Haines alloys and

325

00:18:11,400 --> 00:18:09,690

then the 80 to 86 above 160 ksi strength

326

00:18:14,580 --> 00:18:11,410

is a

327

00:18:18,180 --> 00:18:14,590

because in order to get it above about

328

00:18:22,500 --> 00:18:18,190

180 ksi you have to work harden it in

329

00:18:26,010 --> 00:18:22,510

addition to heat treating it now here's

330

00:18:27,690 --> 00:18:26,020

a here's a table of fastener materials I

331

00:18:30,060 --> 00:18:27,700

won't go through each one of these but

332

00:18:31,650 --> 00:18:30,070

one of the things I just wanted to point

333

00:18:37,200 --> 00:18:31,660

out to you and you'll have to go to this

334

00:18:40,890 --> 00:18:37,210

one over here on it is how to figure out

335

00:18:45,720 --> 00:18:40,900

what the designation is now the the aisi

336

00:18:49,169 --> 00:18:45,730

and SAE usually the the numbers are the

337

00:18:52,169 --> 00:18:49,179

same for the steel and in this case here

338

00:18:56,130 --> 00:18:52,179

we have the two as the class of

339

00:19:00,330 --> 00:18:56,140

materials over from over here which is a

340

00:19:02,549 --> 00:19:00,340

nickel steel in this case the three is

341

00:19:05,580 --> 00:19:02,559

the approximate percentage of the main

342

00:19:11,039 --> 00:19:05,590

alloying element which in this case is

343

00:19:16,110 --> 00:19:11,049

is nickel and then the 17 is the carbon

344

00:19:16,950 --> 00:19:16,120

content so this is a low carbon alloy

345

00:19:19,860 --> 00:19:16,960

steel

346

00:19:22,169 --> 00:19:19,870

2317 that has no special significance

347

00:19:26,070 --> 00:19:22,179

other than the fact that it's used to

348

00:19:29,430 --> 00:19:26,080

just illustrate the system now for the

349

00:19:32,970 --> 00:19:29,440

nickel chromium steels and molybdenum

350

00:19:35,730 --> 00:19:32,980

steels and so on here are the ones that

351

00:19:40,289 --> 00:19:35,740

are used mostly for fasteners in alloy

352

00:19:45,720 --> 00:19:40,299

steels the 4000 series you have 40 37 41

353

00:19:52,530 --> 00:19:45,730

40 43 40 that type of thing that is that

354

00:19:56,430 --> 00:19:54,930

now on chemical compositions I guess I

355

00:20:00,660 --> 00:19:56,440

better stay with this one over here for

356

00:20:03,720 --> 00:20:00,670

that also here you see here the the

357

00:20:05,970 --> 00:20:03,730

ordinary hardware store of varieties and

358

00:20:10,020 --> 00:20:05,980

you notice that all of these other

359

00:20:11,910 --> 00:20:10,030

elements are not listed one of the

360

00:20:15,270 --> 00:20:11,920

things you can run into if you if you're

361

00:20:17,730 --> 00:20:15,280

having a real problem sometimes you can

362

00:20:19,590 --> 00:20:17,740

get some of these steels that have

363

00:20:21,300 --> 00:20:19,600

things in them that you don't want the

364

00:20:23,370 --> 00:20:21,310

guy was pointing this out to me from

365

00:20:25,230 --> 00:20:23,380

Lincoln Electric that in welding they're

366

00:20:27,960 --> 00:20:25,240

running into that because a lot of Steel

367

00:20:30,630 --> 00:20:27,970

is made out of scrap so the scrap has

368

00:20:32,190 --> 00:20:30,640

most anything yet so they're getting a

369

00:20:34,620 --> 00:20:32,200

lot of impurities that they don't want

370

00:20:36,570 --> 00:20:34,630

in it and then then you get down here

371

00:20:38,790 --> 00:20:36,580

the standard alloy is the stainless

372

00:20:41,850 --> 00:20:38,800

steels one of the ones that I wanted to

373

00:20:46,310 --> 00:20:41,860

call to your attention on that is the in

374

00:20:49,100 --> 00:20:46,320

the 300 series stainless steel down here

375

00:20:52,740 --> 00:20:49,110

one of the ones that they left out here

376

00:20:57,330 --> 00:20:52,750

was the the L designations the

377

00:20:59,880 --> 00:20:57,340

low-carbon because a lot of the times

378

00:21:03,960 --> 00:20:59,890

you want to minimize the amount of

379

00:21:05,580 --> 00:21:03,970

carbon in it so you use a 304 L or 316 L

380

00:21:07,380 --> 00:21:05,590

or something like that and they did not

381

00:21:09,780 --> 00:21:07,390

put that one in that table so you might

382

00:21:16,280 --> 00:21:09,790

want to just flag it alright moving on

383

00:21:21,810 --> 00:21:16,290

now to operating temperatures here I

384

00:21:26,430 --> 00:21:21,820

have grouped this in categories and so

385

00:21:28,610 --> 00:21:26,440

the minus 65 and below that's your

386

00:21:31,410 --> 00:21:28,620

cryogenic temperatures now of course

387

00:21:33,620 --> 00:21:31,420

those of you who have been around long

388

00:21:38,490 --> 00:21:33,630



enough remember the Atlas and centaur

389

00:21:42,210 --> 00:21:38,500

and curse their liquid hydrogen fueled

390

00:21:47,030 --> 00:21:42,220

so the temperatures are running on that

391

00:21:53,720 --> 00:21:47,040

type of a vehicle or anywhere from about

392

00:21:57,180 --> 00:21:53,730

300 - 300 to minus 423 so you cannot use

393

00:22:02,820 --> 00:21:57,190

carbon steels at those temperatures

394

00:22:04,680 --> 00:22:02,830

because they will crack like glass even

395

00:22:07,010 --> 00:22:04,690

some of the stainless steels will go

396

00:22:12,810 --> 00:22:07,020

below about

397

00:22:18,540 --> 00:22:12,820

- 150 aluminum is good down to those

398

00:22:23,480 --> 00:22:18,550

temperatures then you go to the - 65 -

399

00:22:26,820 --> 00:22:23,490

450 which is a ordinary range for most

400

00:22:31,650 --> 00:22:26,830

engineering designs carbon steels are

401  
00:22:33,120 --> 00:22:31,660  
okay and stainless steels are okay but

402  
00:22:35,340 --> 00:22:33,130  
then you get into the business of

403  
00:22:37,260 --> 00:22:35,350  
needing corrosion protection for the

404  
00:22:38,970 --> 00:22:37,270  
carbon steel with the various types of

405  
00:22:41,670 --> 00:22:38,980  
plating like the Sanker cadmium or

406  
00:22:44,310 --> 00:22:41,680  
phosphate or black oxide or whatever and

407  
00:22:51,180 --> 00:22:44,320  
those will be covered of course later on

408  
00:22:54,720 --> 00:22:51,190  
in the platings encoding section now for

409  
00:22:54,720 --> 00:22:54,730  
the 450 and above

410  
00:22:59,880 --> 00:22:56,670  
believe it or not you can use unplayed

411  
00:23:01,470 --> 00:22:59,890  
carbon steel up to about 700 degrees

412  
00:23:05,760 --> 00:23:01,480  
because the only thing you're looking at

413  
00:23:07,710 --> 00:23:05,770

there is how much does the allowable

414

00:23:10,890 --> 00:23:07,720

drop on it for the temperature so if you

415

00:23:13,740 --> 00:23:10,900

go in one of the books like mill

416

00:23:17,160 --> 00:23:13,750

handbook five you can find the

417

00:23:19,260 --> 00:23:17,170

temperature curves for carbon steels and

418

00:23:21,840 --> 00:23:19,270

you find it use it but to see the reason

419

00:23:26,420 --> 00:23:21,850

I'm saying unplayed 'add is that an

420

00:23:28,470 --> 00:23:26,430

awful lot of the platings for Steel's

421

00:23:31,650 --> 00:23:28,480

burn up before you get to that

422

00:23:33,870 --> 00:23:31,660

temperature so these are some some of

423

00:23:37,260 --> 00:23:33,880

the ones that don't hurt you at least

424

00:23:38,730 --> 00:23:37,270

now and I'm just giving these because of

425

00:23:39,990 --> 00:23:38,740

their temperature range rather than the

426

00:23:42,360 --> 00:23:40,000

fact that you'd normally would not

427

00:23:45,420 --> 00:23:42,370

silver to plate a carbon steel but you

428

00:23:48,530 --> 00:23:45,430

do silver plate stainless steel but

429

00:23:54,110 --> 00:23:48,540

silver nickel chromium plating and

430

00:23:58,290 --> 00:23:54,120

chromium plating is used on some

431

00:24:01,800 --> 00:23:58,300

high-strength fasteners for aircraft

432

00:24:03,600 --> 00:24:01,810

landing gear that type of thing the

433

00:24:06,470 --> 00:24:03,610

black oxide coating that you're all

434

00:24:09,980 --> 00:24:06,480

familiar with from your hardware store

435

00:24:13,860 --> 00:24:09,990

bolts looks good and all that but it

436

00:24:16,680 --> 00:24:13,870

burns off then you have diffused nickel

437

00:24:18,420 --> 00:24:16,690

cadmium which is a special one that will

438

00:24:19,230 --> 00:24:18,430

be covered later and then of course you

439

00:24:28,820 --> 00:24:19,240

use the stain

440

00:24:37,080 --> 00:24:32,430

now we although we have a corrosion

441

00:24:37,740 --> 00:24:37,090

section I elected to put the oh sorry

442

00:24:40,799 --> 00:24:37,750

about that

443

00:24:44,549 --> 00:24:40,809

here's here's the table of summary of

444

00:24:46,290 --> 00:24:44,559

fastener materials and you can't read

445

00:24:49,140 --> 00:24:46,300

this one so I'll go over to this one one

446

00:24:52,230 --> 00:24:49,150

of the things that I wanted to point out

447

00:24:56,880 --> 00:24:52,240

to you here is that if you look at the

448

00:25:01,740 --> 00:24:56,890

useful design temperature on these you

449

00:25:06,060 --> 00:25:01,750

find that a 286 is one of the best - for

450

00:25:08,520 --> 00:25:06,070

23 to 1,200 but if you get down through

451  
00:25:13,260 --> 00:25:08,530  
all of these and you find that this

452  
00:25:16,490 --> 00:25:13,270  
Hanes 230 at the bottom is the only one

453  
00:25:20,340 --> 00:25:16,500  
that will carry you up to 1,800 degrees

454  
00:25:22,799 --> 00:25:20,350  
now the significance of this is that

455  
00:25:24,780 --> 00:25:22,809  
we've gone through on the NASA program

456  
00:25:28,919 --> 00:25:24,790  
the national air space plane and

457  
00:25:32,190 --> 00:25:28,929  
developing all of these super duper

458  
00:25:34,650 --> 00:25:32,200  
materials to build airplanes out of but

459  
00:25:36,660 --> 00:25:34,660  
we never did anything on developing

460  
00:25:42,930 --> 00:25:36,670  
fasteners to put them together because

461  
00:25:44,669 --> 00:25:42,940  
the regular metal fasteners there's what

462  
00:25:50,820 --> 00:25:44,679  
they the only thing they have to put

463  
00:25:52,980 --> 00:25:50,830

them together okay moving along now into

464

00:25:57,350 --> 00:25:52,990

the galvanic corrosion and stress

465

00:26:01,470 --> 00:25:57,360

corrosion area galvanic corrosion is

466

00:26:05,790 --> 00:26:01,480

something that we're all familiar with

467

00:26:09,630 --> 00:26:05,800

although we may not use that title for

468

00:26:13,430 --> 00:26:09,640

it if you get a scratch on the chromium

469

00:26:15,570 --> 00:26:13,440

plating on your car it will rust faster

470

00:26:17,580 --> 00:26:15,580

that it would if it didn't have any

471

00:26:21,960 --> 00:26:17,590

plating on it because you have a very

472

00:26:27,799 --> 00:26:21,970

small anode in a large cathode being the

473

00:26:30,510 --> 00:26:27,809

rest of the surface so the anode is

474

00:26:33,450 --> 00:26:30,520

deposited on the cathode which means

475

00:26:37,560 --> 00:26:33,460

that it rusts away so rusting is a

476  
00:26:40,740 --> 00:26:37,570  
galvanic corrosion and later on we have

477  
00:26:42,140 --> 00:26:40,750  
a table on the galvanic series that will

478  
00:26:47,090 --> 00:26:42,150  
give you

479  
00:26:48,920 --> 00:26:47,100  
the location in the table of these and

480  
00:26:52,160 --> 00:26:48,930  
the farther apart they are in the table

481  
00:26:59,480 --> 00:26:52,170  
the bigger galvanic corrosion cell you

482  
00:27:01,670 --> 00:26:59,490  
developed between the two of them and of

483  
00:27:03,440 --> 00:27:01,680  
course cadmium and zinc are adjacent to

484  
00:27:05,720 --> 00:27:03,450  
the aluminum in that table which makes

485  
00:27:10,670 --> 00:27:05,730  
them compatible as coatings for steel

486  
00:27:12,710 --> 00:27:10,680  
fasteners used in aluminum then and to

487  
00:27:15,520 --> 00:27:12,720  
further protect mating surfaces from

488  
00:27:20,390 --> 00:27:15,530



galvanic corrosion you particularly

489

00:27:23,150 --> 00:27:20,400

where you're putting in rivets and you

490

00:27:27,530 --> 00:27:23,160

drill you pilot drill one piece and and

491

00:27:29,690 --> 00:27:27,540

then drill it through you have raw raw

492

00:27:32,600 --> 00:27:29,700

surfaces that are not plated with

493

00:27:37,420 --> 00:27:32,610

anything so you either use a zinc

494

00:27:42,800 --> 00:27:37,430

chromate paste or there's a mill 8802

495

00:27:50,180 --> 00:27:42,810

sealer that will deter galvanic

496

00:27:52,340 --> 00:27:50,190

corrosion now here is the table or the

497

00:27:54,680 --> 00:27:52,350

galvanic series and this is something

498

00:27:58,730 --> 00:27:54,690

you can find I think marks handbook and

499

00:28:00,530 --> 00:27:58,740

various places have it and one of the

500

00:28:04,790 --> 00:28:00,540

things that I wanted to point out in

501  
00:28:08,870 --> 00:28:04,800  
this is that if you look at cadmium over

502  
00:28:12,350 --> 00:28:08,880  
here see it is right in the aluminum's

503  
00:28:15,770 --> 00:28:12,360  
also zinc is there so if you use a

504  
00:28:17,840 --> 00:28:15,780  
cadmium plated fastener and aluminum you

505  
00:28:22,430 --> 00:28:17,850  
will get less galvanic corrosion than

506  
00:28:28,010 --> 00:28:22,440  
you would say if you used a one of these

507  
00:28:30,160 --> 00:28:28,020  
down here like a brass or or copper

508  
00:28:33,230 --> 00:28:30,170  
inconel or something something like that

509  
00:28:36,500 --> 00:28:33,240  
now notice that there are two different

510  
00:28:41,620 --> 00:28:36,510  
designations for the stainless steel

511  
00:28:44,420 --> 00:28:41,630  
that have active and passive normally

512  
00:28:48,350 --> 00:28:44,430  
stainless steels are passivated which

513  
00:28:52,880 --> 00:28:48,360

they're treated with an acid dip to

514

00:28:54,920 --> 00:28:52,890

remove the any kind of scale they had on

515

00:28:57,740 --> 00:28:54,930

them from processing

516

00:28:59,750 --> 00:28:57,750

and to form a protective oxide on the

517

00:29:03,890 --> 00:28:59,760

surface the passivation of Steel

518

00:29:07,610 --> 00:29:03,900

corresponds to anodizing of aluminum so

519

00:29:10,150 --> 00:29:07,620

that's why that they have it shown

520

00:29:14,270 --> 00:29:10,160

differently here passive and active

521

00:29:17,450 --> 00:29:14,280

because the the passive is much less

522

00:29:20,360 --> 00:29:17,460

corrosion a much more corrosion

523

00:29:22,250 --> 00:29:20,370

resistant okay now going to stress

524

00:29:26,360 --> 00:29:22,260

corrosion that is something that we're

525

00:29:30,050 --> 00:29:26,370

all familiar with in a sense but there's

526

00:29:32,660 --> 00:29:30,060

not much available in textbooks on it

527

00:29:37,280 --> 00:29:32,670

because it the the study of it is a

528

00:29:39,320 --> 00:29:37,290

fairly recent thing now stress corrosion

529

00:29:40,910 --> 00:29:39,330

of course occurs when our sensitive

530

00:29:42,590 --> 00:29:40,920

material is loaded in tension in a

531

00:29:45,140 --> 00:29:42,600

corrosive environment now that sounds

532

00:29:47,690 --> 00:29:45,150

pretty easy and what happens the surface

533

00:29:50,450 --> 00:29:47,700

develops pits or cracks from exposure

534

00:29:53,750 --> 00:29:50,460

and this of course gives you stress

535

00:29:59,360 --> 00:29:53,760

risers which will cause the component to

536

00:30:03,850 --> 00:29:59,370

fail at as little as twenty percent of

537

00:30:06,650 --> 00:30:03,860

us calculated load capacity now the

538

00:30:08,840 --> 00:30:06,660

thing about it one of the reasons why I

539

00:30:11,300 --> 00:30:08,850

don't propose using the super high

540

00:30:14,270 --> 00:30:11,310

strength alloy steel fasteners if you

541

00:30:17,030 --> 00:30:14,280

can avoid it is the higher the strength

542

00:30:22,550 --> 00:30:17,040

the more sensitive it is to stress

543

00:30:27,350 --> 00:30:22,560

corrosion so so you try to steer clear

544

00:30:30,560 --> 00:30:27,360

of using super high strength fasteners

545

00:30:34,250 --> 00:30:30,570

in alloy steel for that reason the

546

00:30:36,500 --> 00:30:34,260

stainless steels most of them are not

547

00:30:38,840 --> 00:30:36,510

stress corrosion susceptible other than

548

00:30:41,810 --> 00:30:38,850

the precipitation hardening 17:4 and

549

00:30:43,790 --> 00:30:41,820

17-7 so you ought to look at that before

550

00:30:48,770 --> 00:30:43,800

you select the fasteners that you're

551  
00:30:53,200 --> 00:30:48,780  
going to use here's another one that you

552  
00:30:57,490 --> 00:30:53,210  
can run into although it's it's not a

553  
00:31:01,820 --> 00:30:57,500  
that common as decarburization when you

554  
00:31:04,160 --> 00:31:01,830  
heat treat a carbon steel you can

555  
00:31:07,730 --> 00:31:04,170  
actually precipitate carbon out on the

556  
00:31:08,590 --> 00:31:07,740  
surface and i would compare this to like

557  
00:31:10,419 --> 00:31:08,600  
charred whew

558  
00:31:13,480 --> 00:31:10,429  
or something like that you know charred

559  
00:31:14,950 --> 00:31:13,490  
wood is how it's very soft on the

560  
00:31:15,999 --> 00:31:14,960  
surface because that this is essentially

561  
00:31:19,269 --> 00:31:16,009  
what you're getting you're getting a

562  
00:31:21,370 --> 00:31:19,279  
heavy carbon coat in the outer surface

563  
00:31:23,590 --> 00:31:21,380

and of course it's not as strong as the

564

00:31:27,570 --> 00:31:23,600

parent material and on machine parts

565

00:31:30,070 --> 00:31:27,580

they sometimes just machine that off and

566

00:31:31,450 --> 00:31:30,080

and go ahead and and they can use the

567

00:31:33,310 --> 00:31:31,460

part but of course on a fastener you

568

00:31:35,710 --> 00:31:33,320

can't do that so you have to be careful

569

00:31:40,180 --> 00:31:35,720

about decarburization and once again

570

00:31:42,249 --> 00:31:40,190

it's on the strength above 180 ksi now

571

00:31:43,779 --> 00:31:42,259

tempered brittleness is another thing

572

00:31:46,590 --> 00:31:43,789

you can run into on the high strength

573

00:31:50,649 --> 00:31:46,600

fasteners after you have clenched them

574

00:31:53,619 --> 00:31:50,659

then you need to go back and tempura

575

00:31:57,190 --> 00:31:53,629

much means holding a mat at a fairly low

576  
00:31:59,740 --> 00:31:57,200  
temperature to get the strength that you

577  
00:32:04,180 --> 00:31:59,750  
need but that also causes the material

578  
00:32:10,869 --> 00:32:04,190  
to be brittle so carbon steel fasteners

579  
00:32:16,990 --> 00:32:10,879  
above 190 ksi are a real risk as far as

580  
00:32:19,810 --> 00:32:17,000  
having brittle failure now you can use

581  
00:32:21,070 --> 00:32:19,820  
some of the the super alloys and

582  
00:32:23,740 --> 00:32:21,080  
strengths higher than that but not the

583  
00:32:27,249 --> 00:32:23,750  
ordinary carbon steel now going to

584  
00:32:29,830 --> 00:32:27,259  
carbide precipitation this is something

585  
00:32:33,190 --> 00:32:29,840  
that gets people in trouble a lot where

586  
00:32:36,779 --> 00:32:33,200  
they don't want a stainless steel to

587  
00:32:41,560 --> 00:32:36,789  
rest and believe it or not this is

588  
00:32:46,210 --> 00:32:41,570



fairly recent least recent for me maybe

589

00:32:47,680 --> 00:32:46,220

for you guys it's ancient but we ran

590

00:32:50,080 --> 00:32:47,690

into this on the Atlas and centaur

591

00:32:51,909 --> 00:32:50,090

programs in which we had joints rusting

592

00:32:54,490 --> 00:32:51,919

down at the Cape with this thing sitting

593

00:32:56,950 --> 00:32:54,500

on the pad and this is stainless steel

594

00:32:58,990 --> 00:32:56,960

it's not supposed to rest but what they

595

00:33:01,659 --> 00:32:59,000

had on that some of these sections were

596

00:33:04,060 --> 00:33:01,669

put together by fusion welding and of

597

00:33:07,810 --> 00:33:04,070

course the only way that you can prevent

598

00:33:14,110 --> 00:33:07,820

it from resting on the 300 these were

599

00:33:15,850 --> 00:33:14,120

301 is to solution treat it after

600

00:33:18,460 --> 00:33:15,860

welding which means you take it up to

601  
00:33:20,200 --> 00:33:18,470  
about 1800 degrees or something like

602  
00:33:21,450 --> 00:33:20,210  
that and get the chromium back in

603  
00:33:24,000 --> 00:33:21,460  
solution

604  
00:33:25,590 --> 00:33:24,010  
what happens the carbon will combine

605  
00:33:27,840 --> 00:33:25,600  
with the chromium the form chromium

606  
00:33:29,669 --> 00:33:27,850  
carbide in the well join and of course

607  
00:33:34,019 --> 00:33:29,679  
that pulls the chromium out so if you

608  
00:33:36,600 --> 00:33:34,029  
had your regular 301 is an 18 8 18

609  
00:33:38,669 --> 00:33:36,610  
chromium 8 nickel so you pull the

610  
00:33:43,350 --> 00:33:38,679  
chromium out if it falls below about 12

611  
00:33:45,750 --> 00:33:43,360  
percent the steel rest so this is why

612  
00:33:48,480 --> 00:33:45,760  
that normally if you're going to have

613  
00:33:50,730 --> 00:33:48,490

welded joints you try to use a 300

614

00:33:53,970 --> 00:33:50,740

series with the L designation which is

615

00:33:58,620 --> 00:33:53,980

low carbon and even use a low carbon

616

00:34:01,649 --> 00:33:58,630

well dried or better yet and this is

617

00:34:05,580 --> 00:34:01,659

what we did it mark marquette on the

618

00:34:08,430 --> 00:34:05,590

titan you use 321 stainless because it

619

00:34:12,210 --> 00:34:08,440

has titanium in it the titan or are you

620

00:34:14,550 --> 00:34:12,220

use 347 which has columbium and the

621

00:34:17,099 --> 00:34:14,560

titanium and columbium will combine with

622

00:34:18,750 --> 00:34:17,109

the carbon before the chromium will so

623

00:34:22,109 --> 00:34:18,760

that will leave the chromium in solution

624

00:34:26,520 --> 00:34:22,119

so that you still have the corrosion

625

00:34:28,859 --> 00:34:26,530

resistance so keep that in mind when

626

00:34:30,839 --> 00:34:28,869

selecting fasteners for anything above

627

00:34:34,919 --> 00:34:30,849

about 800 degrees in the stainless steel

628

00:34:39,329 --> 00:34:34,929

to use 321 or 347 now in material

629

00:34:40,649 --> 00:34:39,339

strengths after the temperature and

630

00:34:42,599 --> 00:34:40,659

corrosion requirements have been

631

00:34:46,349 --> 00:34:42,609

determined then you've got a look at the

632

00:34:47,730 --> 00:34:46,359

material strength and once again keep in

633

00:34:49,919 --> 00:34:47,740

mind it's the higher the strength of the

634

00:34:51,300 --> 00:34:49,929

material the more stringent to

635

00:34:55,470 --> 00:34:51,310

manufacturing and quality requirements

636

00:34:58,050 --> 00:34:55,480

become because it's more sensitive to

637

00:35:01,320 --> 00:34:58,060

imperfections if weight is not critical

638

00:35:04,410 --> 00:35:01,330

it's better to use a lot of fasteners of

639

00:35:06,510 --> 00:35:04,420

lower strengths than to use a few high

640

00:35:07,260 --> 00:35:06,520

strength fasteners you use those old

641

00:35:09,810 --> 00:35:07,270

grade eights

642

00:35:12,050 --> 00:35:09,820

if you can use them and you don't have

643

00:35:18,720 --> 00:35:12,060

to worry about weight

644

00:35:21,720 --> 00:35:18,730

now here's metric fasteners and that is

645

00:35:26,750 --> 00:35:21,730

one of the least understood I think

646

00:35:29,400 --> 00:35:26,760

between most design engineers and and

647

00:35:32,430 --> 00:35:29,410

I'll have to admit it's confusing to me

648

00:35:35,280 --> 00:35:32,440

although my my buddy Ben Glenn Dolf who

649

00:35:37,110 --> 00:35:35,290

came from Sweden says that metric is

650

00:35:40,350 --> 00:35:37,120

way of the world he thinks it's great

651  
00:35:45,170 --> 00:35:40,360  
but I still have trouble with it so go

652  
00:35:48,780 --> 00:35:45,180  
through some of the peculiarities of

653  
00:35:51,000 --> 00:35:48,790  
metric fasteners on the property classes

654  
00:35:54,000 --> 00:35:51,010  
is the way that they specify the

655  
00:35:56,580 --> 00:35:54,010  
strength and which is a tensile element

656  
00:35:59,430 --> 00:35:56,590  
in a then yield as a percent of the

657  
00:36:01,230 --> 00:35:59,440  
ultimate in mega Pascal's and somewhere

658  
00:36:03,690 --> 00:36:01,240  
here at mega Pascal is one hundred and

659  
00:36:08,400 --> 00:36:03,700  
forty five point oh four or psi for any

660  
00:36:11,160 --> 00:36:08,410  
of those you need to convert now the

661  
00:36:13,950 --> 00:36:11,170  
material is not specified in the

662  
00:36:16,260 --> 00:36:13,960  
call-out so you have to specify the

663  
00:36:18,360 --> 00:36:16,270

material yourself or otherwise you don't

664

00:36:20,670 --> 00:36:18,370

know what you're getting so if you have

665

00:36:24,960 --> 00:36:20,680

like a property class six point eight

666

00:36:26,520 --> 00:36:24,970

it's a carbon steel of some kind with an

667

00:36:29,130 --> 00:36:26,530

ultimate strength of six hundred mega

668

00:36:31,290 --> 00:36:29,140

Pascal's and a yield of eight tenths

669

00:36:35,130 --> 00:36:31,300

times that because that's where the

670

00:36:37,200 --> 00:36:35,140

point eight comes from now for for some

671

00:36:41,790 --> 00:36:37,210

stainless steels they don't use those

672

00:36:44,010 --> 00:36:41,800

rules and so I have a table further down

673

00:36:45,930 --> 00:36:44,020

the line here that shows the peculiar

674

00:36:49,320 --> 00:36:45,940

type stainless steels the way they're

675

00:36:50,790 --> 00:36:49,330

called out the metric system now here's

676

00:36:53,370 --> 00:36:50,800

something I had a little trouble with

677

00:36:56,610 --> 00:36:53,380

getting people to understand around here

678

00:37:06,840 --> 00:36:56,620

because when we had a government decree

679

00:37:11,130 --> 00:37:06,850

to go to the metric fasteners for the CM

680

00:37:13,740 --> 00:37:11,140

one project or for all new projects the

681

00:37:16,890 --> 00:37:13,750

metric aerospace fasteners are not

682

00:37:19,350 --> 00:37:16,900

available in the European market they

683

00:37:23,070 --> 00:37:19,360

use American inch bound fasteners on

684

00:37:25,080 --> 00:37:23,080

their airplanes and I toured the Huck's

685

00:37:26,940 --> 00:37:25,090

rivet plant and to sign a couple years

686

00:37:29,460 --> 00:37:26,950

ago and the chief engineer told me at

687

00:37:31,340 --> 00:37:29,470

the time that it that the a300 people

688

00:37:35,000 --> 00:37:31,350



were their biggest customer at that time

689

00:37:37,950 --> 00:37:35,010

on fasteners because there aren't any

690

00:37:41,700 --> 00:37:37,960

aerospace fasteners available in the

691

00:37:44,910 --> 00:37:41,710

European market so you can get them in

692

00:37:49,080 --> 00:37:44,920

this country on special order and due to

693

00:37:53,810 --> 00:37:49,090

the fact that the property class is

694

00:38:00,750 --> 00:37:53,820

not enough to define the fasteners the

695

00:38:02,970 --> 00:38:00,760

Naas committee and our agency fastener

696

00:38:06,840 --> 00:38:02,980

committee came up with doing it this way

697

00:38:09,570 --> 00:38:06,850

you put out these AIA it's actually na s

698

00:38:11,010 --> 00:38:09,580

specifications that are for metric

699

00:38:13,170 --> 00:38:11,020

fasteners only and this is a very

700

00:38:15,660 --> 00:38:13,180

similar to the m/s or na s sheets that

701  
00:38:18,330 --> 00:38:15,670  
you see all the time for the inch stuff

702  
00:38:20,160 --> 00:38:18,340  
but you actually cover everything on

703  
00:38:24,740 --> 00:38:20,170  
there the heat treat the material

704  
00:38:26,850 --> 00:38:24,750  
everything and all the dimensions

705  
00:38:29,850 --> 00:38:26,860  
coatings and so on so that you're

706  
00:38:32,400 --> 00:38:29,860  
completely covered and you can also

707  
00:38:38,400 --> 00:38:32,410  
order a metric fasteners from ansi

708  
00:38:42,810 --> 00:38:38,410  
specifications now here's here's that

709  
00:38:49,640 --> 00:38:42,820  
kind of a weird duck type table here for

710  
00:38:54,690 --> 00:38:49,650  
the stainless steel metric fasteners and

711  
00:39:00,480 --> 00:38:54,700  
these different classes here the a1 a2

712  
00:39:03,960 --> 00:39:00,490  
a4 and so on and then the 50 70 80 45 60

713  
00:39:07,490 --> 00:39:03,970

50 70 80 and so on for some reason or

714

00:39:10,320 --> 00:39:07,500

other you need to add a zero to those in

715

00:39:13,830 --> 00:39:10,330

order to get the actual strength of the

716

00:39:16,560 --> 00:39:13,840

material they made them a class like

717

00:39:20,670 --> 00:39:16,570

that with a that so in other words the

718

00:39:23,940 --> 00:39:20,680

50 here is a 500 mega Pascal ultimate

719

00:39:27,270 --> 00:39:23,950

strength and so so the only way to

720

00:39:28,620 --> 00:39:27,280

identify them is to put them in a table

721

00:39:35,870 --> 00:39:28,630

like that where you can refer back to

722

00:39:39,090 --> 00:39:35,880

them now the next table covers the

723

00:39:41,880 --> 00:39:39,100

different classes and the type of alloys

724

00:39:46,890 --> 00:39:41,890

that are normally used for them the se

725

00:39:50,520 --> 00:39:46,900

here is an S & S II as S is for sulfur

726

00:39:52,740 --> 00:39:50,530

that's an S es for selenium that's

727

00:39:57,690 --> 00:39:52,750

normally added to the 300 series to make

728

00:39:59,910 --> 00:39:57,700

it more machinable so presumably on this

729

00:40:01,020 --> 00:39:59,920

one if you wanted to make your own and

730

00:40:01,470 --> 00:40:01,030

you wanted to cut them out of stainless

731

00:40:02,560 --> 00:40:01,480

steel

732

00:40:05,080 --> 00:40:02,570

then you

733

00:40:09,340 --> 00:40:05,090

use those materials here you have the

734

00:40:12,820 --> 00:40:09,350

304 L and the 321 and 347 which are the

735

00:40:15,910 --> 00:40:12,830

titanium columbium stabilized and then

736

00:40:19,210 --> 00:40:15,920

here the 400 series which are only 25 12

737

00:40:21,310 --> 00:40:19,220

percent chromium and there's another

738

00:40:26,650 --> 00:40:21,320

table further over here that will show

739

00:40:30,070 --> 00:40:26,660

some of that now going to the figure 2 I

740

00:40:33,550 --> 00:40:30,080

will not go through all of this stuff

741

00:40:36,900 --> 00:40:33,560

but this is from the metals handbook it

742

00:40:41,020 --> 00:40:36,910

just gives you a good overall view of

743

00:40:45,940 --> 00:40:41,030

the 300 series and the things that you

744

00:40:48,150 --> 00:40:45,950

do to it to tailor it to your your needs

745

00:40:51,730 --> 00:40:48,160

in fact you probably can't read that

746

00:40:54,250 --> 00:40:51,740

even here at all so it is in your

747

00:40:55,720 --> 00:40:54,260

handout so you can go through it and you

748

00:40:59,530 --> 00:40:55,730

can refer back to it at least when

749

00:41:03,130 --> 00:40:59,540

you're picking a material the figure 3

750

00:41:10,050 --> 00:41:03,140

shows the tailoring of the martensitic

751

00:41:14,070 --> 00:41:10,060

400 series and for those of you who

752

00:41:17,200 --> 00:41:14,080

always wonder what you should what your

753

00:41:19,030 --> 00:41:17,210

Scout knife is made out of it's 440 C

754

00:41:21,700 --> 00:41:19,040

which is down there in the corner

755

00:41:24,280 --> 00:41:21,710

someplace and that's the one that has

756

00:41:28,200 --> 00:41:24,290

the highest except in the upper right

757

00:41:32,130 --> 00:41:28,210

hand corner there has the highest carbon

758

00:41:34,630 --> 00:41:32,140

and a lot of chromium so that it will

759

00:41:38,260 --> 00:41:34,640

give you a high strength you can go up

760

00:41:40,150 --> 00:41:38,270

to about a Rockwell 55 with it C 55 but

761

00:41:46,600 --> 00:41:40,160

it will Nick a lot more readily it's not

762

00:41:49,330 --> 00:41:46,610

as ductile s carbon steel figure-four is

763

00:41:52,290 --> 00:41:49,340

once again this is the standard ferritic

764

00:41:55,210 --> 00:41:52,300

stainless steels of the 430 series and

765

00:41:59,440 --> 00:41:55,220

the different ways of tailoring them so

766

00:42:03,730 --> 00:41:59,450

I won't go through that then we go into

767

00:42:06,640 --> 00:42:03,740

a glossary of terms for materials and

768

00:42:09,910 --> 00:42:06,650

once again there's there's more here

769

00:42:12,310 --> 00:42:09,920

than then I will cover in this

770

00:42:14,440 --> 00:42:12,320

presentation but some of the things I

771

00:42:16,180 --> 00:42:14,450

wanted to call to your attention here

772

00:42:20,680 --> 00:42:16,190

about the the

773

00:42:24,579 --> 00:42:20,690

steals that normally we use the 4000

774

00:42:28,299 --> 00:42:24,589

series then on aluminum's which a cover

775

00:42:31,770 --> 00:42:28,309

here if you want more information on

776

00:42:33,819 --> 00:42:31,780

those you can go to the aluminum

777

00:42:36,370 --> 00:42:33,829

handbook which is put out by the

778

00:42:39,880 --> 00:42:36,380

aluminum association and will give you

779

00:42:43,529 --> 00:42:39,890

more information there the if you look

780

00:42:46,750 --> 00:42:43,539

in the under aluminum alloy is the 2024

781

00:42:52,059 --> 00:42:46,760

2000 series is heat treatable the 3000

782

00:42:54,430 --> 00:42:52,069

series isn't the 5000 series is not heat

783

00:42:57,130 --> 00:42:54,440

treatable but some of them are crows

784

00:42:59,920 --> 00:42:57,140

corrosion stress corrosion sensitive and

785

00:43:02,140 --> 00:42:59,930

the curve the six and seven thousand are

786

00:43:07,990 --> 00:43:02,150

we use all the time they are heat

787

00:43:10,270 --> 00:43:08,000

treatable the down there the leaded

788

00:43:12,579 --> 00:43:10,280



Steel's there are you sometimes I guess

789

00:43:15,160 --> 00:43:12,589

for making one-of-a-kind types crews

790

00:43:19,000 --> 00:43:15,170

they'll add once again is added to steel

791

00:43:21,849 --> 00:43:19,010

to make it easier to machine okay going

792

00:43:25,089 --> 00:43:21,859

over to the next one there

793

00:43:28,180 --> 00:43:25,099

the stainless steels once again there's

794

00:43:33,700 --> 00:43:28,190

there's also a 200 series stainless

795

00:43:36,940 --> 00:43:33,710

steel is very similar than 300 and the

796

00:43:38,500 --> 00:43:36,950

other thing we had a problem down at the

797

00:43:41,559 --> 00:43:38,510

cake one time that they couldn't

798

00:43:44,950 --> 00:43:41,569

determine whether they had used 300 or

799

00:43:47,260 --> 00:43:44,960

400 series fasteners so the way you

800

00:43:52,630 --> 00:43:47,270

check is with a magnet 400 series is

801  
00:43:58,109 --> 00:43:52,640  
magnetic 300 series is not okay moving

802  
00:44:02,500 --> 00:43:58,119  
on to the mechanical definitions part

803  
00:44:07,120 --> 00:44:02,510  
you get into cold working plain carbon

804  
00:44:12,970 --> 00:44:07,130  
Steel's with cold work can you read that

805  
00:44:13,900 --> 00:44:12,980  
one over there or not the the plain

806  
00:44:16,660 --> 00:44:13,910  
carbon Steel's

807  
00:44:18,880 --> 00:44:16,670  
you can you can cold work them during

808  
00:44:21,039 --> 00:44:18,890  
deformation in fact one of the reasons

809  
00:44:25,059 --> 00:44:21,049  
that they start out with the so cold

810  
00:44:26,680 --> 00:44:25,069  
wire if you will know where somehow

811  
00:44:28,359 --> 00:44:26,690  
three-quarter inch wire doesn't strike

812  
00:44:29,140 --> 00:44:28,369  
me as being wire because with the collet

813  
00:44:35,249 --> 00:44:29,150

in the

814

00:44:38,319 --> 00:44:35,259

faster plants they run it through and

815

00:44:39,789 --> 00:44:38,329

they but before they run it through they

816

00:44:41,650 --> 00:44:39,799

run it through an annealing furnace to

817

00:44:42,220 --> 00:44:41,660

get it to soft as possible before they

818

00:44:47,380 --> 00:44:42,230

start

819

00:44:50,859 --> 00:44:47,390

and so the fasteners are actually formed

820

00:44:55,150 --> 00:44:50,869

out of this annealed wire and they are

821

00:44:59,559 --> 00:44:55,160

cold worked during the farming in fact

822

00:45:03,759 --> 00:44:59,569

we had I was involved in a quick case on

823

00:45:07,329 --> 00:45:03,769

a product liability thing that the the

824

00:45:09,759 --> 00:45:07,339

nut was actually harder than the bolt in

825

00:45:11,980 --> 00:45:09,769

this case because the nut had been cold

826

00:45:15,099 --> 00:45:11,990

worked more than the boat and it

827

00:45:17,079 --> 00:45:15,109

stripped the threads off the Pope had

828

00:45:20,620 --> 00:45:17,089

caused a chair to fail and a guy got

829

00:45:26,230 --> 00:45:20,630

hurt so just wanted to point those out

830

00:45:28,720 --> 00:45:26,240

to you now going on over to this next

831

00:45:32,980 --> 00:45:28,730

glossary of terms on the process

832

00:45:34,839 --> 00:45:32,990

definitions on one of the things I

833

00:45:37,660 --> 00:45:34,849

wanted to point out there killed steel

834

00:45:39,130 --> 00:45:37,670

is something that is defined here which

835

00:45:41,170 --> 00:45:39,140

normally you don't don't find and that

836

00:45:43,029 --> 00:45:41,180

is important because it it makes the

837

00:45:45,960 --> 00:45:43,039

steel chemically stable so that you

838

00:45:48,700 --> 00:45:45,970

won't get into troubles on it and I

839

00:45:51,099 --> 00:45:48,710

always point out defects that have

840

00:45:54,009 --> 00:45:51,109

happened along the line and one of the

841

00:45:56,079 --> 00:45:54,019

things you remember the cars I believe

842

00:45:59,769 --> 00:45:56,089

it was the Fords and Lincoln's that had

843

00:46:02,079 --> 00:45:59,779

the bumper beam that disintegrated on

844

00:46:04,210 --> 00:46:02,089

them that was because the steel was not

845

00:46:07,989 --> 00:46:04,220

killed killed properly as I understand

846

00:46:11,319 --> 00:46:07,999

it and so you can get disastrous effects

847

00:46:14,620 --> 00:46:11,329

from it the pickling is also the removal

848

00:46:17,470 --> 00:46:14,630

of oxide scale by dipping a steel in a

849

00:46:22,900 --> 00:46:17,480

bath and these are important to have to

850

00:46:24,880 --> 00:46:22,910

prevent corrosion on the material during

851  
00:46:31,019 --> 00:46:24,890  
the manufacturing process whether it be

852  
00:46:32,470 --> 00:46:31,029  
fasteners or or general Hardware now the

853  
00:46:35,529 --> 00:46:32,480  
carburizing

854  
00:46:40,630 --> 00:46:35,539  
covered so will will not go night

855  
00:46:42,910 --> 00:46:40,640  
trading and and case hardening actually

856  
00:46:45,039 --> 00:46:42,920  
in cases like that it's where

857  
00:46:46,839 --> 00:46:45,049  
you have a material that you want it to

858  
00:46:49,539 --> 00:46:46,849  
remain ductile because it's some sort of

859  
00:46:51,730 --> 00:46:49,549  
an impact type thing and so you

860  
00:46:54,430 --> 00:46:51,740  
case-hardened the surface of it by put

861  
00:46:56,410 --> 00:46:54,440  
it putting enough carbon on it that you

862  
00:47:06,490 --> 00:46:56,420  
can harden the surface just to get it

863  
00:47:12,280 --> 00:47:06,500

slightly hard okay now moving to

864

00:47:15,400 --> 00:47:12,290

platings and coatings nearly all

865

00:47:17,500 --> 00:47:15,410

commercial fasteners are made of sensors

866

00:47:19,990 --> 00:47:17,510

made of plain carbon or alloy carbon

867

00:47:23,319 --> 00:47:20,000

steel you need some sort of a protection

868

00:47:28,120 --> 00:47:23,329

on them to keep them from rusting so you

869

00:47:30,520 --> 00:47:28,130

can go from putting good old 10w30 oil on

870

00:47:32,500 --> 00:47:30,530

them down all the way to gold plating

871

00:47:35,460 --> 00:47:32,510

now gold plating is not used on

872

00:47:37,809 --> 00:47:35,470

fasteners usually but other than pins on

873

00:47:40,000 --> 00:47:37,819

tubes or something like that in the

874

00:47:41,829 --> 00:47:40,010

electrical field electrical contacts and

875

00:47:43,660 --> 00:47:41,839

so on but if something is small enough

876

00:47:49,690 --> 00:47:43,670

gold plating does not become that

877

00:47:52,420 --> 00:47:49,700

expensive to coat it but usually we go

878

00:47:55,210 --> 00:47:52,430

with something that is less expensive so

879

00:47:57,309 --> 00:47:55,220

but what you're looking for is a coating

880

00:48:00,490 --> 00:47:57,319

that will give you the protection at the

881

00:48:03,640 --> 00:48:00,500

lowest cost so the other thing is with

882

00:48:08,859 --> 00:48:03,650

fasteners you got to have a thin coating

883

00:48:11,620 --> 00:48:08,869

because the fastener threads have to be

884

00:48:15,609 --> 00:48:11,630

within tolerance after the coating which

885

00:48:17,470 --> 00:48:15,619

is important now I know that if you get

886

00:48:20,859 --> 00:48:17,480

nails or something like that

887

00:48:23,260 --> 00:48:20,869

Ron Roman Chuck drives nails all the

888

00:48:25,180 --> 00:48:23,270



time they've been galvanized and that's

889

00:48:28,030 --> 00:48:25,190

a dipping process but it's not used on

890

00:48:33,150 --> 00:48:28,040

normally on threaded fasteners now on on

891

00:48:37,359 --> 00:48:33,160

temperature limitations the coating is

892

00:48:41,770 --> 00:48:37,369

more likely to set the temperature limit

893

00:48:44,680 --> 00:48:41,780

in the fastener material itself and some

894

00:48:46,809 --> 00:48:44,690

coatings can be a disaster when they

895

00:48:49,990 --> 00:48:46,819

decompose like cadmium you get hydrogen

896

00:48:52,990 --> 00:48:50,000

embrittlement from a decomposition of

897

00:48:55,359 --> 00:48:53,000

cadmium and others like the good old

898

00:48:59,020 --> 00:48:55,369

familiar black oxide baked off without

899

00:49:08,660 --> 00:49:04,190

now cadmium plating is although people

900

00:49:12,410 --> 00:49:08,670

say that it is going away because of

901  
00:49:16,160 --> 00:49:12,420  
environmental problems that's really not

902  
00:49:19,670 --> 00:49:16,170  
true in fact when I talk to a guy at

903  
00:49:22,580 --> 00:49:19,680  
Boeing about their development of

904  
00:49:23,930 --> 00:49:22,590  
replacements for cadmium he said as far

905  
00:49:25,400 --> 00:49:23,940  
as we're concerned there isn't a

906  
00:49:28,040 --> 00:49:25,410  
replacement for cadmium we're going to

907  
00:49:32,630 --> 00:49:28,050  
go ahead using it so it's just the idea

908  
00:49:36,800 --> 00:49:32,640  
that you have to control the process in

909  
00:49:42,500 --> 00:49:36,810  
order to keep a PA off your back but it

910  
00:49:46,640 --> 00:49:42,510  
can used for electro depositing alloy

911  
00:49:49,760 --> 00:49:46,650  
steel up to 190 ksi if you get above 190

912  
00:49:51,590 --> 00:49:49,770  
ksi then you can't prevent hydrogen

913  
00:49:53,480 --> 00:49:51,600

embrittlement and you have to go to a

914

00:49:55,880 --> 00:49:53,490

vacuum deposit which runs the cost way

915

00:50:00,170 --> 00:49:55,890

up now here's something that is

916

00:50:03,190 --> 00:50:00,180

overlooked a lot and causes lots of

917

00:50:06,560 --> 00:50:03,200

problems when parts are cadmium plated

918

00:50:09,290 --> 00:50:06,570

they have to be baked within two hours

919

00:50:11,210 --> 00:50:09,300

after plating and this the reason I said

920

00:50:14,030 --> 00:50:11,220

eight to twenty three hours it depends

921

00:50:16,430 --> 00:50:14,040

on who's baking them or if any baking is

922

00:50:19,130 --> 00:50:16,440

done because some I have heard of cases

923

00:50:22,330 --> 00:50:19,140

in which no baking had always done to

924

00:50:25,070 --> 00:50:22,340

bake the hydrogen out whenever you do a

925

00:50:29,330 --> 00:50:25,080

electroplating process it's done in a

926

00:50:31,700 --> 00:50:29,340

some sort of an aqueous environment so

927

00:50:35,270 --> 00:50:31,710

as you know from charging your battery

928

00:50:39,170 --> 00:50:35,280

you get free hydrogen whenever you put

929

00:50:42,650 --> 00:50:39,180

electrodes in water so you have free

930

00:50:46,070 --> 00:50:42,660

hydrogen ions and of course hydrogen can

931

00:50:49,280 --> 00:50:46,080

go where anything else can't go so you

932

00:50:51,680 --> 00:50:49,290

get hydrogen given off during the

933

00:50:53,600 --> 00:50:51,690

process so unless you bake the material

934

00:50:56,900 --> 00:50:53,610

right after it you're in trouble now

935

00:51:02,290 --> 00:50:56,910

cadmium melts at 610 degrees so it's

936

00:51:07,750 --> 00:51:05,470

now the advantages of cadmium it's good

937

00:51:11,500 --> 00:51:07,760

salt spray resistance so it's very good

938

00:51:13,630 --> 00:51:11,510

and marine environment for airplanes

939

00:51:15,700 --> 00:51:13,640

where they're exposed to salt all the

940

00:51:18,700 --> 00:51:15,710

time in the wintertime it's consistent

941

00:51:21,700 --> 00:51:18,710

on the torque friction properties it has

942

00:51:24,160 --> 00:51:21,710

a good Taliban ik corrosion location and

943

00:51:27,580 --> 00:51:24,170

it doesn't decrease the base material

944

00:51:30,190 --> 00:51:27,590

fatigue strength but the disadvantage is

945

00:51:32,740 --> 00:51:30,200

it generates cyanide during the plating

946

00:51:36,010 --> 00:51:32,750

process which is nasty stuff that the

947

00:51:39,880 --> 00:51:36,020

EPA watches very closely and of course I

948

00:51:42,130 --> 00:51:39,890

mentioned the plating and baking has to

949

00:51:44,740 --> 00:51:42,140

be closely controlled and void hydrogen

950

00:51:47,260 --> 00:51:44,750

embrittlement and it causes

951  
00:51:49,600 --> 00:51:47,270  
embrittlement of titanium it's very

952  
00:51:51,550 --> 00:51:49,610  
expensive and it has to be vacuum

953  
00:51:55,630 --> 00:51:51,560  
deposited on high-strength parts to

954  
00:51:57,700 --> 00:51:55,640  
avoid hydrogen embrittlement so but one

955  
00:52:00,330 --> 00:51:57,710  
of the other advantages of it that I

956  
00:52:03,760 --> 00:52:00,340  
didn't list there it does not support

957  
00:52:09,250 --> 00:52:03,770  
fungus growth whereas a lot of platings

958  
00:52:12,070 --> 00:52:09,260  
will since cadmium is kind of a toxic

959  
00:52:13,780 --> 00:52:12,080  
type thing your moles and stuff like

960  
00:52:18,400 --> 00:52:13,790  
that in a marine environment can't grill

961  
00:52:19,300 --> 00:52:18,410  
on it now zinc plating zinc is very

962  
00:52:22,300 --> 00:52:19,310  
common

963  
00:52:25,270 --> 00:52:22,310

most of the fasteners that you buy that

964

00:52:28,450 --> 00:52:25,280

are plated or probably zinc plated and

965

00:52:31,990 --> 00:52:28,460

of course hot dip zinc plating is called

966

00:52:37,420 --> 00:52:32,000

galvanizing you get roofing nails that

967

00:52:39,520 --> 00:52:37,430

type of thing our galvanized the roof

968

00:52:41,890 --> 00:52:39,530

that corrugated roof and so on is

969

00:52:43,630 --> 00:52:41,900

galvanized now the zinc plating doesn't

970

00:52:46,000 --> 00:52:43,640

generate the toxic byproducts the

971

00:52:49,300 --> 00:52:46,010

cadmium generates there's a lot cheaper

972

00:52:51,910 --> 00:52:49,310

than cadmium but it will heal itself

973

00:52:55,720 --> 00:52:51,920

over by migrating over scratch there is

974

00:52:58,180 --> 00:52:55,730

if you scratch an area in fact down at

975

00:53:02,500 --> 00:52:58,190

the keep they did a study on how far a

976  
00:53:05,770 --> 00:53:02,510  
zinc would migrate and it would go over

977  
00:53:09,490 --> 00:53:05,780  
a scratch about an eighth of inch wide

978  
00:53:12,760 --> 00:53:09,500  
and go back and and heal it will kind of

979  
00:53:16,059 --> 00:53:12,770  
heal itself desert extent and it has a

980  
00:53:18,579 --> 00:53:16,069  
good galvanic location

981  
00:53:20,589 --> 00:53:18,589  
but it's not as good as cadmium for

982  
00:53:22,449 --> 00:53:20,599  
corrosion resistance and the Turk

983  
00:53:23,620 --> 00:53:22,459  
tension friction characteristics in

984  
00:53:26,439 --> 00:53:23,630  
other words when you're talking up a

985  
00:53:28,449 --> 00:53:26,449  
fastener you can get such a variation in

986  
00:53:31,989 --> 00:53:28,459  
the coefficient of friction that you can

987  
00:53:35,769 --> 00:53:31,999  
get in real trouble on knowing what load

988  
00:53:37,660 --> 00:53:35,779



you're putting on it and but it can

989

00:53:39,279 --> 00:53:37,670

adhere here's one of the other bad

990

00:53:41,380 --> 00:53:39,289

things about it it has a useful

991

00:53:43,439 --> 00:53:41,390

temperature limit of only about 250

992

00:53:46,839 --> 00:53:43,449

degrees so you can't use it at all or

993

00:53:48,099 --> 00:53:46,849

your have elevated temperatures and it

994

00:53:50,229 --> 00:53:48,109

can cause hydrogen embrittlement

995

00:53:53,469 --> 00:53:50,239

although it's not a serious a problem as

996

00:53:55,089 --> 00:53:53,479

it is with the cadmium now the phosphate

997

00:53:56,799 --> 00:53:55,099

coatings this is used a lot in the

998

00:54:02,049 --> 00:53:56,809

automotive business because it's cheap

999

00:54:03,789 --> 00:54:02,059

you throw a a cup of phosphate in a

1000

00:54:06,430 --> 00:54:03,799

barrel and put a bunch of fasteners in

1001

00:54:08,949 --> 00:54:06,440

and shake them a few times and you have

1002

00:54:17,229 --> 00:54:08,959

phosphate coated passengers more or less

1003

00:54:20,939 --> 00:54:17,239

and so the mildly protective layer of

1004

00:54:23,439 --> 00:54:20,949

phosphate is formed on the surface and

1005

00:54:26,559 --> 00:54:23,449

there's three different ones or zinc

1006

00:54:28,150 --> 00:54:26,569

iron and manganese and the ones usually

1007

00:54:37,230 --> 00:54:28,160

used for fasteners is the zinc or

1008

00:54:43,450 --> 00:54:40,090

now the advantages of phosphate coatings

1009

00:54:45,300 --> 00:54:43,460

they're cheap you can coat them with oil

1010

00:54:49,150 --> 00:54:45,310

or wax to increase the corrosion

1011

00:54:50,770 --> 00:54:49,160

resistance and the phosphate is a good

1012

00:54:52,840 --> 00:54:50,780

primer for painting so if you're going

1013

00:54:55,600 --> 00:54:52,850

to paint something after you've possibly

1014

00:54:57,990 --> 00:54:55,610

coated it that's great and you don't get

1015

00:54:59,980 --> 00:54:58,000

hydrogen embrittlement from it but

1016

00:55:02,830 --> 00:54:59,990

disadvantage it's not very good in

1017

00:55:04,990 --> 00:55:02,840

corrosion you get in consistent tension

1018

00:55:07,830 --> 00:55:05,000

friction properties which means if you

1019

00:55:13,960 --> 00:55:07,840

are supposed to torque ahead bolt to

1020

00:55:15,250 --> 00:55:13,970

exactly 2,000 pounds tensile load you

1021

00:55:17,550 --> 00:55:15,260

don't know what torque it will take to

1022

00:55:19,810 --> 00:55:17,560

do it if you have different fasteners

1023

00:55:22,840 --> 00:55:19,820

that were in a different location in the

1024

00:55:30,820 --> 00:55:22,850

barrel and they have a limited

1025

00:55:35,680 --> 00:55:30,830

temperature of 225 to 400 degrees now

1026

00:55:37,660 --> 00:55:35,690

nickel plating nickel with or without a

1027

00:55:40,390 --> 00:55:37,670

copper strike is one of the oldest

1028

00:55:44,950 --> 00:55:40,400

methods of preventing corrosion and

1029

00:55:48,400 --> 00:55:44,960

improving the appearance of steel and

1030

00:55:52,110 --> 00:55:48,410

brass it it'll tarnish unless it's

1031

00:55:56,590 --> 00:55:52,120

chromium plated but it has a fairly high

1032

00:55:59,710 --> 00:55:56,600

allowable temperature and good corrosion

1033

00:56:02,770 --> 00:55:59,720

resistance the disadvantage it's more

1034

00:56:04,900 --> 00:56:02,780

expensive than cadmium or zinc that

1035

00:56:07,180 --> 00:56:04,910

requires baking after plating to prevent

1036

00:56:12,300 --> 00:56:07,190

hydrogen embrittlement and it doesn't

1037

00:56:19,090 --> 00:56:15,100

now moving on to chromium plating

1038

00:56:21,340 --> 00:56:19,100

chromium plating of course I thought you

1039

00:56:27,250 --> 00:56:21,350

all know is used for automotive and

1040

00:56:29,770 --> 00:56:27,260

appliance decoration and very thin coats

1041

00:56:33,690 --> 00:56:29,780

but it can be used for fasteners as I

1042

00:56:39,220 --> 00:56:33,700

mentioned earlier it's used for coating

1043

00:56:41,740 --> 00:56:39,230

fasteners for landing gear this type of

1044

00:56:46,390 --> 00:56:41,750

thing where you require the super

1045

00:56:52,930 --> 00:56:46,400

high-strength fasteners or components

1046

00:56:55,240 --> 00:56:52,940

and so you can't use something else that

1047

00:56:59,820 --> 00:56:55,250

would be like in a stainless steel so

1048

00:57:03,130 --> 00:56:59,830

you go to the the very high strength

1049

00:57:07,480 --> 00:57:03,140

carbon steel alloy steel and then you

1050

00:57:09,340 --> 00:57:07,490

chrome plate it but you've got to put to

1051  
00:57:11,800 --> 00:57:09,350  
get a good chrome plate you got to put a

1052  
00:57:13,540 --> 00:57:11,810  
copper strike on first and then a nickel

1053  
00:57:17,290 --> 00:57:13,550  
over that and then the chromium goes

1054  
00:57:21,610 --> 00:57:17,300  
over the two of them otherwise the

1055  
00:57:25,210 --> 00:57:21,620  
chromium is porous to a certain extent

1056  
00:57:28,570 --> 00:57:25,220  
so if you have unless you have something

1057  
00:57:30,400 --> 00:57:28,580  
under it to help it it doesn't work out

1058  
00:57:34,480 --> 00:57:30,410  
too well or you have to go with a fairly

1059  
00:57:37,180 --> 00:57:34,490  
thick coat so and it can be used up to

1060  
00:57:37,930 --> 00:57:37,190  
about 1,200 degrees and of course it

1061  
00:57:40,300 --> 00:57:37,940  
looks good

1062  
00:57:42,250 --> 00:57:40,310  
but your the thing you run into it's

1063  
00:57:45,010 --> 00:57:42,260

just expensive a stainless steel so you

1064

00:57:46,870 --> 00:57:45,020

only use it for the special cases and it

1065

00:57:49,450 --> 00:57:46,880

requires very stringent quality control

1066

00:57:51,910 --> 00:57:49,460

because you know what a disaster it

1067

00:57:55,630 --> 00:57:51,920

would be if you get a hole through it

1068

00:57:58,090 --> 00:57:55,640

and the salt gets in it then you have

1069

00:57:59,650 --> 00:57:58,100

something rusting very fast and of

1070

00:58:01,360 --> 00:57:59,660

course you have to do the baking to

1071

00:58:04,770 --> 00:58:01,370

prevent hydrogen embrittlement with that

1072

00:58:08,400 --> 00:58:04,780

same as you do with the cadmium plating

1073

00:58:10,960 --> 00:58:08,410

now here's the ion vapor deposited

1074

00:58:13,720 --> 00:58:10,970

aluminum plating this is a special one

1075

00:58:16,150 --> 00:58:13,730

that was developed I believe yeah by

1076

00:58:19,780 --> 00:58:16,160

McDonnell Douglas for coating of

1077

00:58:23,010 --> 00:58:19,790

aircraft parts and it was going to be

1078

00:58:25,930 --> 00:58:23,020

used as an alternate to cadmium plating

1079

00:58:29,110 --> 00:58:25,940

well it doesn't give you hydrogen

1080

00:58:31,210 --> 00:58:29,120

embrittlement and it insulates to deter

1081

00:58:32,470 --> 00:58:31,220

the galvanic corrosion and can be used

1082

00:58:36,370 --> 00:58:32,480

up to nine hundred and twenty-five

1083

00:58:39,760 --> 00:58:36,380

degrees and is and doesn't give off any

1084

00:58:42,700 --> 00:58:39,770

toxic byproducts but it's expensive and

1085

00:58:45,700 --> 00:58:42,710

has to be done in a vacuum so you can

1086

00:58:48,460 --> 00:58:45,710

send it out to Joe Dokes plating outfit

1087

00:58:51,430 --> 00:58:48,470

to get it done and it's not as good as

1088

00:58:56,040 --> 00:58:51,440



cadmium in a salt spray test so it has

1089

00:58:59,260 --> 00:58:56,050

not had that wide usage that I know of

1090

00:59:00,040 --> 00:58:59,270

diffused nickel cadmium is another one

1091

00:59:03,630 --> 00:59:00,050

that was the

1092

00:59:08,200 --> 00:59:03,640

by the aerospace industry as a

1093

00:59:10,750 --> 00:59:08,210

high-temperature cadmium plating and you

1094

00:59:13,780 --> 00:59:10,760

put a nickel coating on first and then

1095

00:59:16,780 --> 00:59:13,790

put capping on over it and bake it for

1096

00:59:18,730 --> 00:59:16,790

one hour at 645 degrees now the

1097

00:59:21,760 --> 00:59:18,740

advantage you get up to about a thousand

1098

00:59:24,250 --> 00:59:21,770

degrees exposure temperature which is

1099

00:59:26,500 --> 00:59:24,260

good versus 450 for plane cadmium

1100

00:59:30,000 --> 00:59:26,510

plating but once again it's expensive

1101  
00:59:33,090 --> 00:59:30,010  
you you have to have extremely close

1102  
00:59:35,800 --> 00:59:33,100  
process controls and the nickel plate

1103  
00:59:37,930 --> 00:59:35,810  
has to cover the fastener at all times

1104  
00:59:40,450 --> 00:59:37,940  
to avoid cadmium damage to the fastener

1105  
00:59:50,250 --> 00:59:40,460  
material so and it's not recommended for

1106  
00:59:53,680 --> 00:59:50,260  
parts above 200 KS is strength okay

1107  
00:59:55,990 --> 00:59:53,690  
silver plating silver plating is used to

1108  
00:59:58,270 --> 00:59:56,000  
prevent corrosion and as a solid

1109  
01:00:01,330 --> 00:59:58,280  
lubricant for fasteners for instance

1110  
01:00:05,050 --> 01:00:01,340  
it's customary to silver plate a

1111  
01:00:09,310 --> 01:00:05,060  
stainless steel nut for a stainless

1112  
01:00:13,540 --> 01:00:09,320  
steel bolt in order to prevent galling

1113  
01:00:15,490 --> 01:00:13,550

and serve as a lubricant now silver

1114

01:00:20,800 --> 01:00:15,500

plating can be used up to about 1600

1115

01:00:25,420 --> 01:00:20,810

degrees and its disadvantages though

1116

01:00:27,359 --> 01:00:25,430

it's expensive it tarnishes and it

1117

01:00:30,400 --> 01:00:27,369

shouldn't be used in direct contact with

1118

01:00:35,109 --> 01:00:30,410

titanium so its primary use in their

1119

01:00:37,810 --> 01:00:35,119

aerospace field is just to coat

1120

01:00:40,290 --> 01:00:37,820

stainless steel parts on stainless steel

1121

01:00:46,290 --> 01:00:40,300

to prevent the thing from galling

1122

01:00:49,390 --> 01:00:46,300

okay we will take a break now and resume