


## Locking Methods

### NylokPellet (cont'd)

If a nut is used, the pellet will be in the nut.  
pellet is 250 °F.

If a bolt is installed in a tapped hole, the pellet will be in the bolt.  
pellet melts quickly during assembly/disassembly cycles.



1  
00:00:00,000 --> 00:00:18,749

I

2  
00:00:25,150 --> 00:00:22,419

okay continuing with platings and

3  
00:00:28,540 --> 00:00:25,160

coatings in the passivation and pre

4  
00:00:35,939 --> 00:00:28,550

oxidation and right now perspiration so

5  
00:00:38,590 --> 00:00:35,949

we'll get rid of the coat and proceed

6  
00:00:41,860 --> 00:00:38,600

now stainless steel fasteners are

7  
00:00:44,020 --> 00:00:41,870

normally passivated or pre oxidized

8  
00:00:47,170 --> 00:00:44,030

during a manufacturing process to make

9  
00:00:49,749 --> 00:00:47,180

them more inert and of course I

10  
00:00:52,299 --> 00:00:49,759

mentioned earlier is done with the acid

11  
00:00:54,280 --> 00:00:52,309

treatment and then of course the pre

12  
00:00:56,410 --> 00:00:54,290

oxidation is just done simply by putting

13  
00:00:59,530 --> 00:00:56,420

them in a furnace and run them up to

14

00:01:02,350 --> 00:00:59,540

about 1300 degrees and cooling them to

15

00:01:04,600 --> 00:01:02,360

form an oxide coating on the surface the

16

00:01:06,969 --> 00:01:04,610

advantages are that it deters galling

17

00:01:09,969 --> 00:01:06,979

and it's a relatively inexpensive

18

00:01:12,069 --> 00:01:09,979

process the disadvantage is that making

19

00:01:18,340 --> 00:01:12,079

parts still need to be lubricated for

20

00:01:21,640 --> 00:01:18,350

torque coefficient consistency and

21

00:01:25,600 --> 00:01:21,650

here's the old familiar black oxide

22

00:01:27,760 --> 00:01:25,610

coating with oil and it's nice and

23

00:01:31,719 --> 00:01:27,770

pretty in black and you put oil on it

24

00:01:35,070 --> 00:01:31,729

and it glistens and looks good but once

25

00:01:40,960 --> 00:01:35,080

the oil is gone black oxide is worthless

26

00:01:43,330 --> 00:01:40,970

it's real cheap no baking required after

27

00:01:46,539 --> 00:01:43,340

plating it this the material strength is

28

00:01:47,980 --> 00:01:46,549

less than 200 k SI and its disadvantages

29

00:01:50,680 --> 00:01:47,990

it's worthless for corrosion prevention

30

00:01:57,700 --> 00:01:50,690

once the oil is gone and the coating

31

00:02:00,190 --> 00:01:57,710

doesn't adhere well to steel now here's

32

00:02:03,820 --> 00:02:00,200

a bunch of miscellaneous platings and

33

00:02:07,600 --> 00:02:03,830

coatings and electric lyst nickel is one

34

00:02:10,600 --> 00:02:07,610

of them and it is used a lot on just

35

00:02:16,240 --> 00:02:10,610

coating of steel where you don't have

36

00:02:19,390 --> 00:02:16,250

threads but on threads it creates some

37

00:02:21,369 --> 00:02:19,400

problems in that you can get uneven

38

00:02:24,070 --> 00:02:21,379

plating on the threads so that they're

39

00:02:30,369 --> 00:02:24,080

kind of out of tolerance this sir Mattel

40

00:02:31,030 --> 00:02:30,379

sir Malloy is a aluminum inorganic

41

00:02:34,449 --> 00:02:31,040

material

42

00:02:36,640 --> 00:02:34,459

all that is used for corrosion

43

00:02:40,199 --> 00:02:36,650

protection of both unthreaded and

44

00:02:43,509 --> 00:02:40,209

threaded parts but once again if you

45

00:02:46,300 --> 00:02:43,519

assemble reassemble very many times it

46

00:02:48,339 --> 00:02:46,310

will come off synergistic because

47

00:02:52,780 --> 00:02:48,349

another one is a combination of surface

48

00:02:56,080 --> 00:02:52,790

oxidation and a fluoropolymer used for

49

00:02:59,229 --> 00:02:56,090

corrosion protection and lubricity but

50

00:03:02,920 --> 00:02:59,239

these are assembly reassembly none of

51  
00:03:05,640 --> 00:03:02,930  
these work that well on proposed

52  
00:03:10,240 --> 00:03:05,650  
replacements for cadmium of course the

53  
00:03:12,659 --> 00:03:10,250  
there's been a big push to do away with

54  
00:03:16,569 --> 00:03:12,669  
cadmium because it is such a bad thing

55  
00:03:18,610 --> 00:03:16,579  
environmentally so there's not fit over

56  
00:03:22,149 --> 00:03:18,620  
in chardon came up with this dr. Matt

57  
00:03:24,399 --> 00:03:22,159  
320 with the plus a ol sealer as a

58  
00:03:29,949 --> 00:03:24,409  
proprietary thing for the automotive

59  
00:03:32,619 --> 00:03:29,959  
companies and it has metal oxide zinc

60  
00:03:35,379 --> 00:03:32,629  
and aluminum and a clear sealer it's

61  
00:03:37,869 --> 00:03:35,389  
good up to 600 degrees but the coating

62  
00:03:40,899 --> 00:03:37,879  
is damaged by assembly disassembly

63  
00:03:45,339 --> 00:03:40,909

cycles and it will support fungus growth

64

00:03:48,460 --> 00:03:45,349

and it costs about the same as cadmium

65

00:03:50,979 --> 00:03:48,470

so the cost savings isn't there the only

66

00:03:55,000 --> 00:03:50,989

thing that it's kinder to the

67

00:03:57,250 --> 00:03:55,010

environment zinc nickel coating is one

68

00:04:00,099 --> 00:03:57,260

that is used some there's about ninety

69

00:04:02,589 --> 00:04:00,109

percent ten percent nickel but it

70

00:04:04,649 --> 00:04:02,599

doesn't work very well on fasteners it

71

00:04:07,569 --> 00:04:04,659

works on rods and things of this nature

72

00:04:15,180 --> 00:04:07,579

now here is a summary of pleadings and

73

00:04:21,370 --> 00:04:18,849

important here is the useful design

74

00:04:25,990 --> 00:04:21,380

temperature limit you will notice that

75

00:04:28,930 --> 00:04:26,000

most of these don't go that high and the

76

00:04:30,909 --> 00:04:28,940

a here is for the black oxide with oil

77

00:04:33,370 --> 00:04:30,919

as soon as the oil boils off your

78

00:04:38,200 --> 00:04:33,380

corrosion resistance it's gone so you

79

00:04:40,330 --> 00:04:38,210

see when you get down to it about 1,200

80

00:04:43,540 --> 00:04:40,340

degrees is the best that any of these

81

00:04:44,770 --> 00:04:43,550

will do so that's why that in a lot of

82

00:04:48,129 --> 00:04:44,780

cases where you

83

00:04:50,770 --> 00:04:48,139

super high temperatures you have to use

84

00:04:53,890 --> 00:04:50,780

a material that doesn't require coding

85

00:04:56,650 --> 00:04:53,900

like wasp a lawyer Hanes or inconel or

86

00:04:59,820 --> 00:04:56,660

something of that nature because you

87

00:05:04,240 --> 00:04:59,830

can't rely on the coatings now here's a

88

00:05:08,680 --> 00:05:04,250

table that just gives various

89

00:05:10,210 --> 00:05:08,690

characteristics of the coatings and

90

00:05:15,090 --> 00:05:10,220

plated there's a couple here that i

91

00:05:18,940 --> 00:05:15,100

wanted to mention era date is a common

92

00:05:22,650 --> 00:05:18,950

coating in fact we used it on the CM one

93

00:05:26,800 --> 00:05:22,660

chamber for it is electrically

94

00:05:30,640 --> 00:05:26,810

conductive whereas anodized isn't and it

95

00:05:32,680 --> 00:05:30,650

is a type of chromate conversion coating

96

00:05:36,520 --> 00:05:32,690

in which you actually treat the surface

97

00:05:40,350 --> 00:05:36,530

with an acid to form a real thin layer

98

00:05:44,350 --> 00:05:40,360

that is somewhat corrosion resistant so

99

00:05:48,010 --> 00:05:44,360

what we had to do in in on CM one you

100

00:05:50,020 --> 00:05:48,020

mask it in the irritated areas where you

101  
00:05:52,330 --> 00:05:50,030  
have electrical conductivity required

102  
00:05:54,070 --> 00:05:52,340  
and then the anodized which is actually

103  
00:05:57,310 --> 00:05:54,080  
used although it's used on other

104  
00:06:02,830 --> 00:05:57,320  
materials as we know it as being used on

105  
00:06:06,130 --> 00:06:02,840  
aluminum it is a acid etch using

106  
00:06:10,600 --> 00:06:06,140  
sulfuric acid I believe that forms a

107  
00:06:14,800 --> 00:06:10,610  
fairly heavy oxide coating and fact you

108  
00:06:17,200 --> 00:06:14,810  
can't anodized a fastener because the

109  
00:06:19,090 --> 00:06:17,210  
anodized is thick and well you can

110  
00:06:20,740 --> 00:06:19,100  
anodized it physically but it doesn't

111  
00:06:22,719 --> 00:06:20,750  
work out very well on the threaded areas

112  
00:06:24,400 --> 00:06:22,729  
because you will have a to heavier

113  
00:06:29,230 --> 00:06:24,410

coating and the threads where it doesn't

114

00:06:32,170 --> 00:06:29,240

work too well now moving on to thread

115

00:06:34,450 --> 00:06:32,180

lubricants there's all kinds of

116

00:06:40,830 --> 00:06:34,460

lubricants available and of course all

117

00:06:45,190 --> 00:06:40,840

of us have used the old 10w30 oil and

118

00:06:49,990 --> 00:06:45,200

for our cars to lubricate stuff the oil

119

00:06:53,230 --> 00:06:50,000

grease wax graphite silver molybdenum

120

00:06:55,290 --> 00:06:53,240

disulphide and prep proprietary types

121

00:06:57,600 --> 00:06:55,300

such as never sees silver goop

122

00:06:59,820 --> 00:06:57,610

synergistic can ever lube and so

123

00:07:01,740 --> 00:06:59,830

on some of these are applied at

124

00:07:09,929 --> 00:07:01,750

installation and some are cured on the

125

00:07:13,770 --> 00:07:09,939

fastener by the manufacturer I'm having

126  
00:07:17,760 --> 00:07:13,780  
trouble turning my page okay for oil and

127  
00:07:19,409 --> 00:07:17,770  
grease you have good lubrication up to

128  
00:07:22,499 --> 00:07:19,419  
the boiling point of the oil or grease

129  
00:07:23,850 --> 00:07:22,509  
which is usually around 250 degrees and

130  
00:07:27,920 --> 00:07:23,860  
of course you can't use any of this

131  
00:07:32,309 --> 00:07:27,930  
stuff in vacuum now graphite graphite

132  
00:07:36,230 --> 00:07:32,319  
drag graphite is not dry it's a fine

133  
00:07:40,140 --> 00:07:38,429  
usually oil or water to become a

134  
00:07:42,480 --> 00:07:40,150  
lubricant and then when the moisture

135  
00:07:45,390 --> 00:07:42,490  
evaporates it becomes an abrasive powder

136  
00:07:54,300 --> 00:07:45,400  
and of course it can't be using a vacuum

137  
00:07:59,330 --> 00:07:54,310  
either silver plating as I mentioned

138  
00:08:02,640 --> 00:07:59,340

earlier it is normally used on stainless

139

00:08:05,010 --> 00:08:02,650

nuts stainless bolts as both a lubricant

140

00:08:07,350 --> 00:08:05,020

and I Colleen coating and it's good up

141

00:08:10,430 --> 00:08:07,360

to about 1600 degrees it can be used in

142

00:08:13,050 --> 00:08:10,440

a vacuum but it is very expensive

143

00:08:15,059 --> 00:08:13,060

molybdenum disulfide is kind of a

144

00:08:18,360 --> 00:08:15,069

universal tape that's used in the

145

00:08:20,939 --> 00:08:18,370

aerospace industry because it's a can be

146

00:08:23,790 --> 00:08:20,949

put on us a dry film lubricant it's good

147

00:08:26,879 --> 00:08:23,800

up to 750 degrees it can be used in a

148

00:08:32,730 --> 00:08:26,889

vacuum and it can be applied to both

149

00:08:36,959 --> 00:08:32,740

alloy steel and stainless steel now

150

00:08:41,310 --> 00:08:36,969

never sees is a proprietary petroleum

151

00:08:45,960 --> 00:08:41,320

based lubricant and it contains metal

152

00:08:49,250 --> 00:08:45,970

oxide usually copper or nickel depending

153

00:08:51,900 --> 00:08:49,260

on what temperature you want because the

154

00:08:54,689 --> 00:08:51,910

copper of course has a lower melting

155

00:08:58,290 --> 00:08:54,699

point than the nickel and it's good up

156

00:09:00,449 --> 00:08:58,300

to 2,200 degrees because what you wind

157

00:09:04,860 --> 00:09:00,459

up with is the metal flakes between the

158

00:09:07,260 --> 00:09:04,870

threads as the oil it boils off and so

159

00:09:09,780 --> 00:09:07,270

this means that you have to reapply each

160

00:09:11,310 --> 00:09:09,790

time you reassemble it and it can't be

161

00:09:13,350 --> 00:09:11,320

using a vacuum either but

162

00:09:14,960 --> 00:09:13,360

you have the the flakes in between the

163

00:09:21,600 --> 00:09:14,970

threads making them easier to

164

00:09:25,190 --> 00:09:21,610

disassemble silver goop which is made by

165

00:09:30,750 --> 00:09:25,200

some company here in Cleveland I believe

166

00:09:33,540 --> 00:09:30,760

is a proprietary paste that contains

167

00:09:36,420 --> 00:09:33,550

twenty to thirty percent silver and it's

168

00:09:40,550 --> 00:09:36,430

good up to about 1500 degrees but of

169

00:09:44,130 --> 00:09:40,560

course silver does not is corrosive to

170

00:09:48,480 --> 00:09:44,140

aluminum magnesium so you don't don't

171

00:09:50,550 --> 00:09:48,490

use it on them it's curse the silver

172

00:09:55,770 --> 00:09:50,560

goop is very expensive and it can't be

173

00:09:59,730 --> 00:09:55,780

using a vacuum either the fluorocarbon

174

00:10:02,760 --> 00:09:59,740

coatings there's a lot of them available

175

00:10:05,460 --> 00:10:02,770

the I'm just listing a few of them here

176

00:10:08,670 --> 00:10:05,470

the synergistic span coke style garden

177

00:10:12,420 --> 00:10:08,680

ever lube and they're only good for a

178

00:10:16,610 --> 00:10:12,430

few assemblies because they flake off if

179

00:10:19,890 --> 00:10:16,620

you assemble and disassemble a fastener

180

00:10:22,980 --> 00:10:19,900

nut bolt very much and there are only

181

00:10:25,980 --> 00:10:22,990

good up to about 400 degrees they can be

182

00:10:29,520 --> 00:10:25,990

used in a vacuum and here was one that I

183

00:10:32,160 --> 00:10:29,530

learned when I was looking for different

184

00:10:35,630 --> 00:10:32,170

types of lubricants for high temperature

185

00:10:39,750 --> 00:10:35,640

applications plain oil of magnesia

186

00:10:42,840 --> 00:10:39,760

is used by the turbine engine companies

187

00:10:45,180 --> 00:10:42,850

for engine assembly because anything

188

00:10:46,910 --> 00:10:45,190

that you use in a jet engine for

189

00:10:49,170 --> 00:10:46,920

lubricants going to burn off anyway

190

00:10:52,400 --> 00:10:49,180

after the things operating but in

191

00:10:54,390 --> 00:10:52,410

putting it together this is a suitable

192

00:10:59,030 --> 00:10:54,400

lubricant and it doesn't harm anything

193

00:11:05,550 --> 00:10:59,040

when it burns up now here's a summary of

194

00:11:08,610 --> 00:11:05,560

the thread lubricants and most of stuff

195

00:11:11,670 --> 00:11:08,620

we have covered here there this is

196

00:11:15,300 --> 00:11:11,680

doesn't necessarily include all of them

197

00:11:19,560 --> 00:11:15,310

but these are the the common ones and

198

00:11:22,260 --> 00:11:19,570

once again there's very few that are

199

00:11:23,520 --> 00:11:22,270

good for high temperatures here are the

200

00:11:24,840 --> 00:11:23,530

three that are good for the high

201  
00:11:25,920 --> 00:11:24,850  
temperatures so

202  
00:11:27,949 --> 00:11:25,930  
this is something you have to keep in

203  
00:11:31,170 --> 00:11:27,959  
mind that going back to that original

204  
00:11:33,090 --> 00:11:31,180  
principle that the first thing you want

205  
00:11:36,050 --> 00:11:33,100  
to do is establish the environment that

206  
00:11:39,569 --> 00:11:36,060  
you're going to have your fasteners in

207  
00:11:42,900 --> 00:11:39,579  
now going into the subject of corrosion

208  
00:11:45,809 --> 00:11:42,910  
of course this is a major field so we

209  
00:11:48,720 --> 00:11:45,819  
just try to hit it a little here in the

210  
00:11:50,610 --> 00:11:48,730  
way of fastener corrosion galvanic and

211  
00:11:55,110 --> 00:11:50,620  
stress corrosion we've already covered

212  
00:11:57,600 --> 00:11:55,120  
and the corrosion resistance of a

213  
00:12:01,350 --> 00:11:57,610

particular metal to occur rodent can be

214

00:12:03,269 --> 00:12:01,360

found in a book of tables which I will

215

00:12:06,870 --> 00:12:03,279

be leaving behind when I retire there is

216

00:12:10,350 --> 00:12:06,880

a two-volume set that actually gives for

217

00:12:12,569 --> 00:12:10,360

the different percentages of different

218

00:12:17,939 --> 00:12:12,579

types of corrodens it gives the effect

219

00:12:19,559 --> 00:12:17,949

on the various materials and hydrogen

220

00:12:21,840 --> 00:12:19,569

embrittlement and graphite corrosion

221

00:12:28,949 --> 00:12:21,850

will be covered in the corrosion section

222

00:12:33,329 --> 00:12:28,959

here hydrogen embrittlement it's talked

223

00:12:35,490 --> 00:12:33,339

about a lot in recent years and yet you

224

00:12:40,370 --> 00:12:35,500

can test for it but it's kind of UFO

225

00:12:47,879 --> 00:12:45,509

it's caused by having free hydrogen ions

226

00:12:50,100 --> 00:12:47,889

in the presence of the metal which in

227

00:12:53,189 --> 00:12:50,110

most of the time it's steel it causes

228

00:12:55,740 --> 00:12:53,199

problems in during the manufacturing or

229

00:12:57,569 --> 00:12:55,750

plating process the higher the strength

230

00:13:00,329 --> 00:12:57,579

of the material the more sensitive it is

231

00:13:03,569 --> 00:13:00,339

the hydrogen embrittlement you can get a

232

00:13:06,179 --> 00:13:03,579

hydrogen chemical reaction in which it

233

00:13:12,900 --> 00:13:06,189

combines with the carbon in the steel to

234

00:13:15,300 --> 00:13:12,910

form methane gas or are hydrogen niobium

235

00:13:17,670 --> 00:13:15,310

columbium same thing the English call it

236

00:13:22,110 --> 00:13:17,680

niobium the Americans call it Colombian

237

00:13:26,069 --> 00:13:22,120

or tantalum to form hydrides the methane

238

00:13:29,220 --> 00:13:26,079

gas can cause cracks and the hydrides

239

00:13:32,100 --> 00:13:29,230

are weaker than the parent material so

240

00:13:34,740 --> 00:13:32,110

they can weaken the material then you

241

00:13:37,019 --> 00:13:34,750

can get hydrogen blistering where the

242

00:13:38,500 --> 00:13:37,029

atomic hydrogen fuses into the material

243

00:13:40,750 --> 00:13:38,510

and combines in the moloch

244

00:13:43,210 --> 00:13:40,760

tools and then the molecule is bigger so

245

00:13:45,610 --> 00:13:43,220

it can't get back out so it will build

246

00:13:48,700 --> 00:13:45,620

up pressure to create blisters that will

247

00:13:52,330 --> 00:13:48,710

eventually cause cracks and here's the

248

00:13:54,160 --> 00:13:52,340

problem there's no external indication

249

00:13:56,470 --> 00:13:54,170

that hydrogen is present you can't look

250

00:13:59,770 --> 00:13:56,480

at it you can't run it through x-ray

251  
00:14:04,210 --> 00:13:59,780  
machine anything like that and find out

252  
00:14:08,050 --> 00:14:04,220  
that it's there so the only thing that

253  
00:14:10,480 --> 00:14:08,060  
you can do is test for it enjoy they

254  
00:14:13,590 --> 00:14:10,490  
test fasteners for hydrogen

255  
00:14:17,230 --> 00:14:13,600  
embrittlement they put them on a fixture

256  
00:14:19,060 --> 00:14:17,240  
there's an ASTM spec which I'm not don't

257  
00:14:24,870 --> 00:14:19,070  
remember the number of it you actually

258  
00:14:28,240 --> 00:14:24,880  
put them on with a wedge type washer and

259  
00:14:30,460 --> 00:14:28,250  
take them down and leave them for I

260  
00:14:34,270 --> 00:14:30,470  
think it's 48 hours or something like

261  
00:14:38,590 --> 00:14:34,280  
that if the head didn't pop off it

262  
00:14:41,470 --> 00:14:38,600  
passed the test and that's that's so

263  
00:14:42,730 --> 00:14:41,480

what they do on testing for hydrogen

264

00:14:45,480 --> 00:14:42,740

embrittlement is just take a bunch of

265

00:14:48,490 --> 00:14:45,490

samples and test them that way to see if

266

00:14:50,790 --> 00:14:48,500

if they can find where any of them have

267

00:14:54,370 --> 00:14:50,800

embrittlement now on hydrogen

268

00:14:55,900 --> 00:14:54,380

environment embrittlement usually you

269

00:14:59,800 --> 00:14:55,910

wouldn't run into that because it takes

270

00:15:02,170 --> 00:14:59,810

high-pressure hydrogen to cause that so

271

00:15:03,790 --> 00:15:02,180

if you had a tank of some kind of high

272

00:15:06,430 --> 00:15:03,800

pressure tank that you had fasteners

273

00:15:11,230 --> 00:15:06,440

holding something together inside then

274

00:15:13,270 --> 00:15:11,240

you could actually get hydrogen into the

275

00:15:14,920 --> 00:15:13,280

fasteners just from the high pressure in

276

00:15:16,720 --> 00:15:14,930

other words we're assuming there there

277

00:15:18,790 --> 00:15:16,730

was no hydrogen embrittlement in the

278

00:15:21,640 --> 00:15:18,800

fastener before it was installed then

279

00:15:23,800 --> 00:15:21,650

you need about 2,000 psi hydrogen in

280

00:15:28,090 --> 00:15:23,810

order for it to go in the material after

281

00:15:29,920 --> 00:15:28,100

it's installed so that's not likely to

282

00:15:34,270 --> 00:15:29,930

happen but hydrogen embrittlement is

283

00:15:37,620 --> 00:15:34,280

always a problem because it depends on

284

00:15:41,790 --> 00:15:37,630

how good the manufacturer was at making

285

00:15:46,690 --> 00:15:41,800

the part so here are some percussions

286

00:15:48,910 --> 00:15:46,700

use the killed steels coat and plate the

287

00:15:51,640 --> 00:15:48,920

fasteners bake the hydrogen out within

288

00:15:52,060 --> 00:15:51,650

two hours after plating otherwise you

289

00:15:56,380 --> 00:15:52,070

can't

290

00:16:00,010 --> 00:15:56,390

take it out Taylor the plating bath to

291

00:16:02,740 --> 00:16:00,020

minimize free hydrogen ions and avoid

292

00:16:05,860 --> 00:16:02,750

the use of alloy steel fasteners above

293

00:16:07,630 --> 00:16:05,870

190 KSA because the only way you can

294

00:16:09,580 --> 00:16:07,640

plate without getting hydrogen

295

00:16:13,930 --> 00:16:09,590

embrittlement is to do it in a vacuum

296

00:16:16,030 --> 00:16:13,940

atmosphere then use stainless steels

297

00:16:20,110 --> 00:16:16,040

that are not sensitive to hydrogen

298

00:16:21,730 --> 00:16:20,120

embrittlement and run the tests to see

299

00:16:28,170 --> 00:16:21,740

if you can find any evidence of any

300

00:16:34,090 --> 00:16:28,180

embrittlement here's one that is

301  
00:16:38,470 --> 00:16:34,100  
slightly different in your book that had

302  
00:16:41,430 --> 00:16:38,480  
had a revised it at the last minute the

303  
00:16:45,100 --> 00:16:41,440  
definition of the graphite here just to

304  
00:16:48,340 --> 00:16:45,110  
indicate what it is it's a actually

305  
00:16:50,230 --> 00:16:48,350  
to drive dry film carbon lubricant which

306  
00:16:56,320 --> 00:16:50,240  
can cause corrosion when exposed to

307  
00:17:00,160 --> 00:16:56,330  
moisture because the on some materials

308  
00:17:04,150 --> 00:17:00,170  
and it can cause you problems and I

309  
00:17:08,949 --> 00:17:04,160  
realize that they put out a la keys or

310  
00:17:12,730 --> 00:17:08,959  
used to put it up which is a graphite in

311  
00:17:17,110 --> 00:17:12,740  
oil to use for locks but yet it will

312  
00:17:19,090 --> 00:17:17,120  
corrode some types of locks so a guy but

313  
00:17:21,130 --> 00:17:19,100

the name of Gilbert gave a course on

314

00:17:23,140 --> 00:17:21,140

corrosion here several years back and he

315

00:17:26,050 --> 00:17:23,150

pointed that out that graphite was a

316

00:17:27,520 --> 00:17:26,060

no-no for lubrication of locks for that

317

00:17:30,400 --> 00:17:27,530

reason because it'll actually corrode a

318

00:17:31,930 --> 00:17:30,410

lot and one of the things then this

319

00:17:36,370 --> 00:17:31,940

happened to us on one of the turbine

320

00:17:41,740 --> 00:17:36,380

engine programs around here is dry

321

00:17:46,360 --> 00:17:41,750

graphite is an abrasive so if you cook

322

00:17:50,380 --> 00:17:46,370

it and dry it out now you have a carbon

323

00:17:52,570 --> 00:17:50,390

powder abrasive which is does a lot more

324

00:17:54,400 --> 00:17:52,580

harm than good and here's something I

325

00:17:57,160 --> 00:17:54,410

threw in just just for your information

326

00:18:00,100 --> 00:17:57,170

I had run into this in a failure course

327

00:18:04,480 --> 00:18:00,110

that I took d zinc tification it's kind

328

00:18:06,720 --> 00:18:04,490

of an odd word but you can actually get

329

00:18:11,230 --> 00:18:06,730

in a material that has

330

00:18:13,090 --> 00:18:11,240

it's even used for just removal of a

331

00:18:17,500 --> 00:18:13,100

particular element from a material by

332

00:18:20,160 --> 00:18:17,510

corrosion but usually it's the removal

333

00:18:24,220 --> 00:18:20,170

of zinc from brass by chemical action

334

00:18:26,860 --> 00:18:24,230

leaves a brittle shell of copper and I

335

00:18:30,690 --> 00:18:26,870

saw on the samples the guy had and you

336

00:18:33,610 --> 00:18:30,700

could compare it to what happens to a

337

00:18:35,920 --> 00:18:33,620

wet piece of wood once the carpenter

338

00:18:40,810 --> 00:18:35,930

ants get done with it it's just a shell

339

00:18:42,610 --> 00:18:40,820

that you can crush and rather rather

340

00:18:45,730 --> 00:18:42,620

striking to look at a failed piece like

341

00:18:48,120 --> 00:18:45,740

that so here's the the galvanic series

342

00:18:51,300 --> 00:18:48,130

which I had been talking about earlier

343

00:18:53,830 --> 00:18:51,310

in fact I believe we showed it earlier

344

00:18:56,050 --> 00:18:53,840

that shows the different materials now

345

00:19:04,060 --> 00:18:56,060

of course magnesium is right at the top

346

00:19:08,980 --> 00:19:04,070

and magnesium is a disaster in a

347

00:19:13,950 --> 00:19:08,990

corrosive environment in fact this guy

348

00:19:16,690 --> 00:19:13,960

who taught a course on failure analysis

349

00:19:20,830 --> 00:19:16,700

pointed out that when an airplane goes

350

00:19:23,500 --> 00:19:20,840

down in the ocean one of the ways if it

351

00:19:26,500 --> 00:19:23,510

that they look for it is if it had zinc

352

00:19:28,570 --> 00:19:26,510

components in it the zinc will decompose

353

00:19:30,700 --> 00:19:28,580

so fast in the saltwater that you will

354

00:19:34,560 --> 00:19:30,710

have bubbles coming up out of the ocean

355

00:19:37,510 --> 00:19:34,570

and they can look for it so magnesium

356

00:19:40,390 --> 00:19:37,520

I'm a member of the mill handbook five

357

00:19:41,680 --> 00:19:40,400

committee I don't know whether some of

358

00:19:43,240 --> 00:19:41,690

you are familiar with it or not but

359

00:19:47,890 --> 00:19:43,250

anyway it is kind of the Bible the

360

00:19:53,410 --> 00:19:47,900

aerospace materials world and magnesium

361

00:19:55,900 --> 00:19:53,420

is kinda out of usage by the aircraft

362

00:19:57,430 --> 00:19:55,910

manufacturers for this reason because it

363

00:20:02,230 --> 00:19:57,440

is so hard to protect it from corrosion

364

00:20:04,540 --> 00:20:02,240

and it's it's not used in any primary

365

00:20:08,230 --> 00:20:04,550

structure that I know of on any of the

366

00:20:16,060 --> 00:20:08,240

airplanes okay going on to locking

367

00:20:18,610 --> 00:20:16,070

methods in most any application some

368

00:20:19,890 --> 00:20:18,620

type of locking must be used prevent the

369

00:20:24,990 --> 00:20:19,900

fastener from loosening

370

00:20:27,000 --> 00:20:25,000

underload and without a locking device

371

00:20:29,610 --> 00:20:27,010

of course the only resistance you have

372

00:20:34,710 --> 00:20:29,620

is just head friction and the nut

373

00:20:37,740 --> 00:20:34,720

friction which if you are vibrating it

374

00:20:39,480 --> 00:20:37,750

very much at all is not enough now find

375

00:20:41,640 --> 00:20:39,490

threads give you slightly better

376

00:20:44,720 --> 00:20:41,650

resistance to loosening from vibration

377

00:20:47,160 --> 00:20:44,730

than coarse threads but it's not a lot

378

00:20:50,820 --> 00:20:47,170

due to the flatter angle of the threads

379

00:20:52,860 --> 00:20:50,830

and one of the things that you try to do

380

00:20:55,260 --> 00:20:52,870

and this'll this'll help you once in a

381

00:20:59,460 --> 00:20:55,270

while is to mount bolts with the heads

382

00:21:01,080 --> 00:20:59,470

up to lessen the loss of loose bolts

383

00:21:03,000 --> 00:21:01,090

because sometimes maybe you'll find

384

00:21:04,350 --> 00:21:03,010

something on your car that the nuts gone

385

00:21:06,150 --> 00:21:04,360

but the bolts still hanging there

386

00:21:12,540 --> 00:21:06,160

flopping back and forth and you can go

387

00:21:17,390 --> 00:21:12,550

ahead and put lock that on it now here's

388

00:21:25,710 --> 00:21:21,380

locking methods is deformed thread and

389

00:21:30,270 --> 00:21:25,720

what you do with the nut it's usually on

390

00:21:32,730 --> 00:21:30,280

the net after you have formed it the

391

00:21:38,580 --> 00:21:32,740

last operation you actually hit it from

392

00:21:41,580 --> 00:21:38,590

two sides and make it slightly oval then

393

00:21:43,560 --> 00:21:41,590

when you put it on and this this hits

394

00:21:48,230 --> 00:21:43,570

got to be controlled to because

395

00:21:53,130 --> 00:21:48,240

otherwise you can be in heap of trouble

396

00:21:55,860 --> 00:21:53,140

it will kind of go back to circular

397

00:21:58,350 --> 00:21:55,870

again so let's see initially here it is

398

00:22:01,230 --> 00:21:58,360

oval then when you put the thing on it

399

00:22:03,540 --> 00:22:01,240

goes the circular it will actually be

400

00:22:06,650 --> 00:22:03,550

for them enough and of course when it

401  
00:22:10,590 --> 00:22:06,660  
does that the threads will lock up on

402  
00:22:14,250 --> 00:22:10,600  
the bolt then when you take it off it

403  
00:22:18,210 --> 00:22:14,260  
will go back to oval again so you can

404  
00:22:20,430 --> 00:22:18,220  
use this one all around ten times before

405  
00:22:22,290 --> 00:22:20,440  
it loses its locking capability because

406  
00:22:26,690 --> 00:22:22,300  
eventually putting it on and off you're

407  
00:22:30,210 --> 00:22:26,700  
going to yield it back to the circular

408  
00:22:32,250 --> 00:22:30,220  
condition and it will no longer lock but

409  
00:22:33,180 --> 00:22:32,260  
that's one of the good ones and you can

410  
00:22:36,540 --> 00:22:33,190  
buy

411  
00:22:43,350 --> 00:22:36,550  
the forum thread lock nut set your

412  
00:22:46,590 --> 00:22:43,360  
hardware store now here is the locking

413  
00:22:49,470 --> 00:22:46,600

collar tight and although I didn't call

414

00:22:51,870 --> 00:22:49,480

it out your elastic stop net is one of

415

00:22:54,990 --> 00:22:51,880

the biggest manufacturers of these what

416

00:22:59,730 --> 00:22:55,000

you have is you have a fiber or nylon

417

00:23:04,080 --> 00:22:59,740

collar here in the top of it the caller

418

00:23:07,020 --> 00:23:04,090

has a smaller diameter then the the bolt

419

00:23:10,890 --> 00:23:07,030

thread so when you run the bolt in it

420

00:23:12,990 --> 00:23:10,900

will interfere on that collar and it'll

421

00:23:15,720 --> 00:23:13,000

also provide a little bit of sealing if

422

00:23:17,280 --> 00:23:15,730

you kind of seal from getting water in

423

00:23:18,990 --> 00:23:17,290

there to give you that much ceiling

424

00:23:21,060 --> 00:23:19,000

although it's not for pressure or

425

00:23:23,280 --> 00:23:21,070

anything like that but the only problem

426

00:23:26,070 --> 00:23:23,290

is this collar area is usually only good

427

00:23:27,930 --> 00:23:26,080

for about 250 degrees to where it will

428

00:23:32,640 --> 00:23:27,940

start softening up to where to become

429

00:23:37,080 --> 00:23:32,650

ineffective now here's the split beam

430

00:23:40,260 --> 00:23:37,090

lock nut this is one that works quite

431

00:23:43,590 --> 00:23:40,270

well and what you have you have a

432

00:23:48,600 --> 00:23:43,600

smaller diameter at the top of it and

433

00:23:51,030 --> 00:23:48,610

its salt cut so that when you put it on

434

00:23:55,500 --> 00:23:51,040

it'll spin freely till it gets up to

435

00:23:58,880 --> 00:23:55,510

that area then as you tighten it up the

436

00:24:02,310 --> 00:23:58,890

beams if you will these six beams on it

437

00:24:05,100 --> 00:24:02,320

have to deflect outward in order for the

438

00:24:07,410 --> 00:24:05,110

bolt to go through so once again this

439

00:24:10,170 --> 00:24:07,420

gives you a pretty heavy friction load

440

00:24:13,830 --> 00:24:10,180

on the threads and will lock it in place

441

00:24:15,990 --> 00:24:13,840

I had a personal experience with the one

442

00:24:17,490 --> 00:24:16,000

of these on a car that I had that the

443

00:24:20,340 --> 00:24:17,500

shock absorbers didn't want to stay on

444

00:24:24,420 --> 00:24:20,350

it and I put these split beam lock nuts

445

00:24:27,600 --> 00:24:24,430

on it and that held versus the the jam

446

00:24:30,780 --> 00:24:27,610

nut to which I'll cover later now here's

447

00:24:32,850 --> 00:24:30,790

a nighlok pellet nighlok is the biggest

448

00:24:37,110 --> 00:24:32,860

manufacturer of this type of thing

449

00:24:39,450 --> 00:24:37,120

although it's even covered by a milspec

450

00:24:41,370 --> 00:24:39,460

so there's a lot of people in on the act

451  
00:24:43,530 --> 00:24:41,380  
on making it this way but what do you do

452  
00:24:47,010 --> 00:24:43,540  
is you you cut a little hole in the

453  
00:24:50,760 --> 00:24:47,020  
thread and stick a nighlok plug in it

454  
00:24:53,940 --> 00:24:50,770  
and this plug sticks up past the thread

455  
00:24:58,350 --> 00:24:53,950  
so when you when you put it on the nylon

456  
00:25:02,160 --> 00:24:58,360  
will bind up in the threads and cause it

457  
00:25:05,780 --> 00:25:02,170  
to lock this one is a fairly good cheap

458  
00:25:07,920 --> 00:25:05,790  
way of locking stuff using on a bicycle

459  
00:25:12,360 --> 00:25:07,930  
lawnmower or something like that it'll

460  
00:25:14,250 --> 00:25:12,370  
hold up but once again the temperature

461  
00:25:18,090 --> 00:25:14,260  
range on it is kind of low because nylon

462  
00:25:20,820 --> 00:25:18,100  
as starts getting soft about 250 degrees

463  
00:25:24,120 --> 00:25:20,830

and of course the threads will chew it

464

00:25:25,920 --> 00:25:24,130

up so you can't put the thing on take it

465

00:25:32,430 --> 00:25:25,930

off very many times without run into

466

00:25:33,780 --> 00:25:32,440

trouble now here's luck tight which we

467

00:25:35,900 --> 00:25:33,790

use around here all the time that's

468

00:25:41,030 --> 00:25:35,910

actually a trade name but different

469

00:25:44,040 --> 00:25:41,040

people make this it's actually a a one

470

00:25:46,640 --> 00:25:44,050

one component type adhesive that you

471

00:25:50,100 --> 00:25:46,650

just smear on the fastener before you

472

00:25:53,400 --> 00:25:50,110

assemble it and it's made in different

473

00:25:55,830 --> 00:25:53,410

grades so that if you want to remove the

474

00:25:58,640 --> 00:25:55,840

fastener you use the volesse sticky tape

475

00:26:01,890 --> 00:25:58,650

like an in Lafayette I think 242 is

476  
00:26:05,040 --> 00:26:01,900  
removable and 271 as the tamper-proof

477  
00:26:06,930 --> 00:26:05,050  
fasteners and there's another one in but

478  
00:26:08,940 --> 00:26:06,940  
to another one or two in between there

479  
00:26:12,480 --> 00:26:08,950  
four bolts that you just want to make

480  
00:26:14,760 --> 00:26:12,490  
difficult to get off but some of the

481  
00:26:17,220 --> 00:26:14,770  
manufacturers other manufacturers of

482  
00:26:20,570 --> 00:26:17,230  
this are Bostick in the industry's

483  
00:26:23,130 --> 00:26:20,580  
nighlok 3m velcro and perma bond and

484  
00:26:31,740 --> 00:26:23,140  
lock tight is good up to about 400

485  
00:26:34,980 --> 00:26:31,750  
degrees now a poxy ribbon this is used a

486  
00:26:38,280 --> 00:26:34,990  
lot on bolts you get them and they have

487  
00:26:40,860 --> 00:26:38,290  
to to ribbons of epoxy so that you have

488  
00:26:43,830 --> 00:26:40,870

the main one and then you have the

489

00:26:46,520 --> 00:26:43,840

hardener that goes with it and this way

490

00:26:51,480 --> 00:26:46,530

you can store them it has a shelf life

491

00:26:54,600 --> 00:26:51,490

at least that you can keep them for I

492

00:26:59,010 --> 00:26:54,610

think up the years like that and the

493

00:27:00,690 --> 00:26:59,020

epoxy is mixed when you install it so it

494

00:27:03,180 --> 00:27:00,700

will combine in

495

00:27:04,710 --> 00:27:03,190

a hardon to hold the fastener in place

496

00:27:08,340 --> 00:27:04,720

now of course this type once you would

497

00:27:10,110 --> 00:27:08,350

remove it it would have to be replaced

498

00:27:12,450 --> 00:27:10,120

because if you destroyed the seal

499

00:27:14,970 --> 00:27:12,460

because it's a one-time type thing and

500

00:27:21,870 --> 00:27:14,980

the maximum operating temperature on

501  
00:27:24,480 --> 00:27:21,880  
these is also about 400 degrees here is

502  
00:27:26,970 --> 00:27:24,490  
another type of thread as a special

503  
00:27:29,820 --> 00:27:26,980  
thread spiral lock I think Detroit

504  
00:27:32,610 --> 00:27:29,830  
tappan dies the holder the patent on

505  
00:27:37,980 --> 00:27:32,620  
this one and this is a cross section

506  
00:27:41,910 --> 00:27:37,990  
here of a kept thread and a fastener now

507  
00:27:45,420 --> 00:27:41,920  
the problem with this when you install

508  
00:27:47,700 --> 00:27:45,430  
it is you have to have spiral locks tap

509  
00:27:51,290 --> 00:27:47,710  
because this is an oddball see the

510  
00:27:54,150 --> 00:27:51,300  
thread the tap cold is not fit the

511  
00:27:58,860 --> 00:27:54,160  
thread and you get your locking action

512  
00:28:04,530 --> 00:27:58,870  
by actually wedging the ramp of the

513  
00:28:08,160 --> 00:28:04,540

thread up against the oddball tape tap

514

00:28:11,700 --> 00:28:08,170

and but you can distribute over several

515

00:28:14,850 --> 00:28:11,710

threads so it offers better locking

516

00:28:18,450 --> 00:28:14,860

capability than ordinary thread would

517

00:28:20,430 --> 00:28:18,460

and some people have used it and run

518

00:28:23,520 --> 00:28:20,440

vibration tests and it holds up fairly

519

00:28:28,410 --> 00:28:23,530

well but of course the the disadvantage

520

00:28:31,850 --> 00:28:28,420

is that you can't you have to get their

521

00:28:34,620 --> 00:28:31,860

tap to tap the whole initially and and

522

00:28:38,070 --> 00:28:34,630

so that creates a problem sometimes for

523

00:28:42,210 --> 00:28:38,080

people on universal type of sembly on

524

00:28:45,960 --> 00:28:42,220

the direct interfering thread in this

525

00:28:51,690 --> 00:28:45,970

case you just have a fastener that is

526  
00:28:56,520 --> 00:28:51,700  
made deliberately with an oversized root

527  
00:29:00,210 --> 00:28:56,530  
diameter to give a slight interference

528  
00:29:02,610 --> 00:29:00,220  
fit to lock now some studs that you have

529  
00:29:04,470 --> 00:29:02,620  
where you have a stud that is installed

530  
00:29:08,070 --> 00:29:04,480  
in something and you want to leave it in

531  
00:29:11,280 --> 00:29:08,080  
place you use this type of thread so

532  
00:29:13,860 --> 00:29:11,290  
that it will not come out when you take

533  
00:29:14,580 --> 00:29:13,870  
the nut off the other end the tapered

534  
00:29:16,409 --> 00:29:14,590  
thread

535  
00:29:18,180 --> 00:29:16,419  
is kind of a variation of this and what

536  
00:29:22,250 --> 00:29:18,190  
you actually tapert this is a smaller

537  
00:29:26,460 --> 00:29:22,260  
diameter up in here and then when you

538  
00:29:30,840 --> 00:29:26,470

put it together it has to push the

539

00:29:39,930 --> 00:29:30,850

threads out here and that gives you a

540

00:29:42,659 --> 00:29:39,940

locking force on it now here's one that

541

00:29:45,659 --> 00:29:42,669

we covered in the drafting room manual

542

00:29:47,610 --> 00:29:45,669

stuff run Roman check that we we fought

543

00:29:50,810 --> 00:29:47,620

semantics on that one a lot whether it's

544

00:29:53,519 --> 00:29:50,820

a castle nut or a castellated nut so

545

00:29:57,630 --> 00:29:53,529

since I wrote this I put my preferences

546

00:30:03,600 --> 00:29:57,640

castellated nut with a cotter pin this

547

00:30:05,399 --> 00:30:03,610

is used a lot for installing bearings

548

00:30:07,710 --> 00:30:05,409

and things like that where you don't

549

00:30:10,100 --> 00:30:07,720

want to tighten it very tight but you

550

00:30:16,950 --> 00:30:10,110

want it to stay put once you tighten it

551  
00:30:20,130 --> 00:30:16,960  
so you can take the nut up then to the

552  
00:30:22,320 --> 00:30:20,140  
to the Turk you want then back it off or

553  
00:30:24,539 --> 00:30:22,330  
taking it to the next next spot on it to

554  
00:30:26,490 --> 00:30:24,549  
get you a slot because you only have a

555  
00:30:28,500 --> 00:30:26,500  
single hole drilled in the end of the

556  
00:30:31,409 --> 00:30:28,510  
fastener so you line up one of these

557  
00:30:35,090 --> 00:30:31,419  
with that hole then put a cotter

558  
00:30:40,700 --> 00:30:35,100  
pin in it and it will hold it in place

559  
00:30:45,240 --> 00:30:40,710  
at the exact spot that you said it and

560  
00:30:47,100 --> 00:30:45,250  
this way when your for instance a lot of

561  
00:30:48,720 --> 00:30:47,110  
the cars are made this way there's

562  
00:30:52,980 --> 00:30:48,730  
another way that would be my next slide

563  
00:30:54,810 --> 00:30:52,990

I think but on wheel bearing when you

564

00:30:57,539 --> 00:30:54,820

tighten it up usually you tighten it up

565

00:31:00,630 --> 00:30:57,549

tight seek the bearings then back it off

566

00:31:04,590 --> 00:31:00,640

enough to let it spin so the nut is a

567

00:31:06,299 --> 00:31:04,600

little more than finger tight now here's

568

00:31:09,269 --> 00:31:06,309

a nut here's another one that is used

569

00:31:12,360 --> 00:31:09,279

for the same reason evidently this is

570

00:31:16,440 --> 00:31:12,370

cheaper because you're doing the same

571

00:31:18,690 --> 00:31:16,450

thing with a regular nut then you're

572

00:31:21,870 --> 00:31:18,700

taking this nut cap which is a sheet

573

00:31:24,450 --> 00:31:21,880

metal stamp sheet metal piece but it has

574

00:31:26,450 --> 00:31:24,460

the serrations here with the slot senate

575

00:31:31,070 --> 00:31:26,460

that you can put the cotter pin in

576  
00:31:35,600 --> 00:31:31,080  
so you Turk the nut to the spot you want

577  
00:31:39,340 --> 00:31:35,610  
it then slip this thing over it then put

578  
00:31:43,340 --> 00:31:39,350  
the cotter pin through the hole in the

579  
00:31:44,930 --> 00:31:43,350  
axle or shaft whatever it is and fasten

580  
00:31:46,580 --> 00:31:44,940  
it the same way as we did on the other

581  
00:31:49,940 --> 00:31:46,590  
one and of course the reason that grease

582  
00:31:52,730 --> 00:31:49,950  
cap is on there is i got this diagram

583  
00:31:54,380 --> 00:31:52,740  
from a truck manual and i didn't

584  
00:31:55,220 --> 00:31:54,390  
separate the grease cap from it that

585  
00:31:59,780 --> 00:31:55,230  
goes on after you've installed

586  
00:32:03,560 --> 00:31:59,790  
everything else now here is luck wearing

587  
00:32:06,620 --> 00:32:03,570  
which is normally used just by the

588  
00:32:12,440 --> 00:32:06,630

aerospace industry because of the cost

589

00:32:16,460 --> 00:32:12,450

and labor involved because you are

590

00:32:20,690 --> 00:32:16,470

winding these wires on here through

591

00:32:24,260 --> 00:32:20,700

either holes straight through the top of

592

00:32:25,910 --> 00:32:24,270

the heads or in the case of the nut

593

00:32:28,610 --> 00:32:25,920

holes through the corners of the nuts

594

00:32:30,890 --> 00:32:28,620

you put these on in such a pattern that

595

00:32:33,290 --> 00:32:30,900

if you try to loosen one fastener it

596

00:32:34,820 --> 00:32:33,300

tightens the other one this way they

597

00:32:40,550 --> 00:32:34,830

can't loosen because they're all tied

598

00:32:45,320 --> 00:32:40,560

together and this is a method that is

599

00:32:49,100 --> 00:32:45,330

covered by an MS spec 30 35 40 you can

600

00:32:51,350 --> 00:32:49,110

use it quite well where you have a

601  
00:32:53,960 --> 00:32:51,360  
circular pattern of fasteners on a

602  
00:32:57,860 --> 00:32:53,970  
flange or something like that but the

603  
00:33:02,000 --> 00:32:57,870  
only people that use it in normal cases

604  
00:33:07,160 --> 00:33:02,010  
as the aerospace industry here is an

605  
00:33:10,130 --> 00:33:07,170  
alternative method to the lock wearing

606  
00:33:12,650 --> 00:33:10,140  
this is a similar thing in which you

607  
00:33:15,910 --> 00:33:12,660  
start out with a piece of cable by the

608  
00:33:18,680 --> 00:33:15,920  
Bergen cable company here that has a

609  
00:33:21,920 --> 00:33:18,690  
barrel already switched in place on it

610  
00:33:23,810 --> 00:33:21,930  
so you just feed it through you run the

611  
00:33:25,490 --> 00:33:23,820  
wire through the heads to wind them the

612  
00:33:27,050 --> 00:33:25,500  
same way so that one can't loosen

613  
00:33:28,460 --> 00:33:27,060

without tightening the other one then

614

00:33:32,780 --> 00:33:28,470

when you get to the end you have a

615

00:33:36,440 --> 00:33:32,790

machine similar to a rivet gun or

616

00:33:39,240 --> 00:33:36,450

something that actually puts a barrel on

617

00:33:41,300 --> 00:33:39,250

here pulls the right tension on the wire

618

00:33:44,370 --> 00:33:41,310

and closes it off so that this is

619

00:33:46,260 --> 00:33:44,380

actually a faster and cheaper way of

620

00:33:50,120 --> 00:33:46,270

luck wearing than the standard luck

621

00:33:58,110 --> 00:33:54,290

this is the disc lock washer it is a

622

00:34:01,200 --> 00:33:58,120

little bit cumbersome in that you have a

623

00:34:06,930 --> 00:34:01,210

pair of washers together and these lines

624

00:34:08,610 --> 00:34:06,940

here represent the angles on them where

625

00:34:10,830 --> 00:34:08,620

you put the two together and turn them

626  
00:34:13,530 --> 00:34:10,840  
together now as long as you keep them

627  
00:34:18,629 --> 00:34:13,540  
together they can't rotate with with

628  
00:34:21,000 --> 00:34:18,639  
respect to each other so the angle of

629  
00:34:24,060 --> 00:34:21,010  
this ramp is steeper than the angle of

630  
00:34:27,659 --> 00:34:24,070  
the thread so it will keep it from

631  
00:34:29,389 --> 00:34:27,669  
turning however the bottom and top of

632  
00:34:31,619 --> 00:34:29,399  
those two washers have to have

633  
00:34:36,810 --> 00:34:31,629  
serrations on them that bite in the

634  
00:34:39,389 --> 00:34:36,820  
joint material and also the bottom of

635  
00:34:41,760 --> 00:34:39,399  
the nut in order to keep it from

636  
00:34:45,480 --> 00:34:41,770  
slipping with respect to the nut or the

637  
00:34:49,350 --> 00:34:45,490  
joint otherwise the washer will spend as

638  
00:34:52,379 --> 00:34:49,360

a unit and doesn't help you any so so

639

00:34:54,119 --> 00:34:52,389

that one will work if you are not

640

00:35:01,860 --> 00:34:54,129

concerned with carrying the coating

641

00:35:04,710 --> 00:35:01,870

loose on the surfaces here is a kind of

642

00:35:08,130 --> 00:35:04,720

a take-off on the disc lock washers in

643

00:35:12,300 --> 00:35:08,140

that you have a nut assembly now this

644

00:35:14,220 --> 00:35:12,310

one has the ramp cheer and the lower

645

00:35:16,350 --> 00:35:14,230

part of it from here down is not

646

00:35:17,730 --> 00:35:16,360

threaded just the upper parts threaded

647

00:35:20,810 --> 00:35:17,740

well to see you put the two of them

648

00:35:24,030 --> 00:35:20,820

together you put them on with a socket

649

00:35:27,450 --> 00:35:24,040

extends down over both of them now this

650

00:35:30,330 --> 00:35:27,460

will hold the thing while you twerk it

651  
00:35:32,580 --> 00:35:30,340  
up and then of course the bottom surface

652  
00:35:36,650 --> 00:35:32,590  
of it has in serrations on it that bite

653  
00:35:39,690 --> 00:35:36,660  
into the attaching plane of the joint so

654  
00:35:43,530 --> 00:35:39,700  
once again you're scratching the surface

655  
00:35:46,400 --> 00:35:43,540  
you're attaching to however a company on

656  
00:35:48,540 --> 00:35:46,410  
the west coast makes these and the

657  
00:35:51,360 --> 00:35:48,550  
president of it told me that they had

658  
00:35:53,070 --> 00:35:51,370  
they were selling millions of these for

659  
00:35:55,080 --> 00:35:53,080  
the heavy truck industry

660  
00:35:56,880 --> 00:35:55,090  
because the heavy truck industries had a

661  
00:36:00,140 --> 00:35:56,890  
lot of trouble through the years with

662  
00:36:03,870 --> 00:36:00,150  
nuts coming off and wheels coming off so

663  
00:36:05,490 --> 00:36:03,880

so they're paying for this type of nut

664

00:36:10,830 --> 00:36:05,500

in order to hold them on because they do

665

00:36:14,580 --> 00:36:10,840

work on holding truck wheels on here is

666

00:36:18,780 --> 00:36:14,590

a another method this is a durar lock

667

00:36:20,730 --> 00:36:18,790

nut which is a trademark of SPS which

668

00:36:24,780 --> 00:36:20,740

one of the one of the big manufacturers

669

00:36:28,410 --> 00:36:24,790

of fasteners it has serrations on it

670

00:36:32,220 --> 00:36:28,420

here that bite into the surface so that

671

00:36:34,680 --> 00:36:32,230

it will not slip and start loosening up

672

00:36:36,570 --> 00:36:34,690

once you get it tight now you have to

673

00:36:38,730 --> 00:36:36,580

depend on this embedment of the

674

00:36:40,950 --> 00:36:38,740

serrations in the contact surfaces and

675

00:36:44,880 --> 00:36:40,960

so it will scratch up the surface if you

676

00:36:50,580 --> 00:36:44,890

can live with that this one will do a

677

00:36:54,260 --> 00:36:50,590

pretty good job of locking here are two

678

00:36:57,410 --> 00:36:54,270

flock washers which are common in the

679

00:37:00,990 --> 00:36:57,420

electrical and automotive industry

680

00:37:03,060 --> 00:37:01,000

because they do afford locking oh and

681

00:37:07,800 --> 00:37:03,070

but once again they do it by gouging

682

00:37:09,540 --> 00:37:07,810

into things they these teeth are twisted

683

00:37:12,180 --> 00:37:09,550

although this doesn't show it they're

684

00:37:16,500 --> 00:37:12,190

actually twisted so that you have one

685

00:37:18,240 --> 00:37:16,510

surface bites into the fastener the

686

00:37:24,450 --> 00:37:18,250

other one bites into the surface that

687

00:37:26,340 --> 00:37:24,460

it's up against so that it will get

688

00:37:31,130 --> 00:37:26,350

enough bite on both of them to hold them

689

00:37:34,320 --> 00:37:31,140

in place and prevent rotation however

690

00:37:36,720 --> 00:37:34,330

you damage the surface quite a bit now

691

00:37:39,900 --> 00:37:36,730

this one is also available with teeth on

692

00:37:41,610 --> 00:37:39,910

the inside so that the outside is smooth

693

00:37:44,820 --> 00:37:41,620

in areas where you don't have room

694

00:37:46,200 --> 00:37:44,830

enough to have it stick out that much

695

00:37:51,140 --> 00:37:46,210

you can you can get them with the teeth

696

00:37:59,250 --> 00:37:56,600

here is the old famous jam nut which is

697

00:38:03,480 --> 00:37:59,260

one that if I polled the people in the

698

00:38:05,370 --> 00:38:03,490

audience neither one would be able to

699

00:38:07,140 --> 00:38:05,380

give me a positive answer on which side

700

00:38:08,670 --> 00:38:07,150

you put this and whether you put it here

701  
00:38:10,380 --> 00:38:08,680  
where it's showing or you've already put

702  
00:38:12,810 --> 00:38:10,390  
the big one on the inside and the little

703  
00:38:16,230 --> 00:38:12,820  
one on the outside because the experts

704  
00:38:18,000 --> 00:38:16,240  
can agree on that it's difficult to load

705  
00:38:21,330 --> 00:38:18,010  
each one of these so that it'll carry

706  
00:38:23,610 --> 00:38:21,340  
any load compared to the other ones

707  
00:38:28,890 --> 00:38:23,620  
because if you if you tighten this one

708  
00:38:32,760 --> 00:38:28,900  
tight it will unload this one and if you

709  
00:38:34,920 --> 00:38:32,770  
don't tighten it enough then the two of

710  
00:38:36,900 --> 00:38:34,930  
them will not work together so it's very

711  
00:38:40,620 --> 00:38:36,910  
difficult to get both of these loaded to

712  
00:38:42,450 --> 00:38:40,630  
where they would carry a load so jam

713  
00:38:45,810 --> 00:38:42,460

nuts in my opinion are not to be used

714

00:38:49,160 --> 00:38:45,820

for critical designs unless it's

715

00:38:52,170 --> 00:38:49,170

something like locking a turnbuckle or

716

00:38:53,700 --> 00:38:52,180

some sort of a rod where something else

717

00:38:55,830 --> 00:38:53,710

carries all the load and you're just

718

00:39:00,840 --> 00:38:55,840

pushing this up against it to keep it

719

00:39:05,700 --> 00:39:00,850

from working loose and here is the good

720

00:39:08,630 --> 00:39:05,710

old split helical up were sure which is

721

00:39:12,990 --> 00:39:08,640

a misnomer because once you compress it

722

00:39:15,300 --> 00:39:13,000

under normal bolt torque it will flatten

723

00:39:16,920 --> 00:39:15,310

out and then this is the flat washer

724

00:39:20,940 --> 00:39:16,930

anyway which doesn't do anything for you

725

00:39:23,610 --> 00:39:20,950

and vibration testing of the split lock

726

00:39:25,440 --> 00:39:23,620

washers assemblies indicate that they're

727

00:39:29,580 --> 00:39:25,450

about us the same as a flat 4shared

728

00:39:32,460 --> 00:39:29,590

resist vibration and I don't recommend

729

00:39:36,450 --> 00:39:32,470

them for any kind of a locking situation

730

00:39:38,990 --> 00:39:36,460

although I was sharply criticized for

731

00:39:41,580 --> 00:39:39,000

writing this in a fastener magazine

732

00:39:45,030 --> 00:39:41,590

because the person who wrote in the

733

00:39:46,650 --> 00:39:45,040

criticism was a manufacturer of split

734

00:39:49,110 --> 00:39:46,660

lock washers so he didn't like it

735

00:39:52,410 --> 00:39:49,120

because I said his his product was

736

00:39:57,660 --> 00:39:52,420

worthless for locking now here is a

737

00:40:00,930 --> 00:39:57,670

method that is used some but it's kind

738

00:40:04,440 --> 00:40:00,940

of a going a long ways to do your

739

00:40:06,390 --> 00:40:04,450

locking as I see it it

740

00:40:09,540 --> 00:40:06,400

this is a trademark of some company on

741

00:40:16,740 --> 00:40:09,550

the west coast age 8 and you see what

742

00:40:18,750 --> 00:40:16,750

you have is a special boat that has a

743

00:40:21,390 --> 00:40:18,760

kind of the double-headed one with a

744

00:40:24,599 --> 00:40:21,400

groove machined in it which creates the

745

00:40:28,319 --> 00:40:24,609

little problem on initial manufacturing

746

00:40:32,339 --> 00:40:28,329

then you have a retainer plate that

747

00:40:38,280 --> 00:40:32,349

slides down over this outer head on to

748

00:40:41,460 --> 00:40:38,290

the bottom one then you use this snap

749

00:40:45,750 --> 00:40:41,470

ring to put in that groove to lock the

750

00:40:48,990 --> 00:40:45,760

thing in place now you do this after

751  
00:40:51,930 --> 00:40:49,000  
you've already took the bolt to the spot

752  
00:40:56,099 --> 00:40:51,940  
that you want it now the only thing is

753  
00:41:01,680 --> 00:40:56,109  
you have to have something for this to

754  
00:41:04,800 --> 00:41:01,690  
brace against to keep the bolt from

755  
00:41:07,440 --> 00:41:04,810  
backing off so it has to be a special

756  
00:41:11,460 --> 00:41:07,450  
design in that respect and then the

757  
00:41:15,930 --> 00:41:11,470  
other problem that I had on the control

758  
00:41:19,740 --> 00:41:15,940  
arms on a Ford wagon this retainer plate

759  
00:41:22,650 --> 00:41:19,750  
is made out of sheet metal over a period

760  
00:41:24,750 --> 00:41:22,660  
of time it will rust up on you and then

761  
00:41:27,150 --> 00:41:24,760  
you go to loosen this thing for a front

762  
00:41:30,470 --> 00:41:27,160  
end alignment and the retainer plate

763  
00:41:33,930 --> 00:41:30,480

comes off and you can't get in there to

764

00:41:37,200 --> 00:41:33,940

get anything else on it loosen it so

765

00:41:39,569 --> 00:41:37,210

that one is one that I would not

766

00:41:46,400 --> 00:41:39,579

recommend in any environment where you

767

00:41:48,690 --> 00:41:46,410

would have corrosion now getting into

768

00:41:53,520 --> 00:41:48,700

washers and out some of them we've

769

00:41:57,150 --> 00:41:53,530

already covered so we won't do a lot on

770

00:41:58,829 --> 00:41:57,160

summon the most of them are flat they're

771

00:42:00,809 --> 00:41:58,839

used to provide a hardened smooth

772

00:42:02,970 --> 00:42:00,819

surface for the contact of a fastener

773

00:42:04,740 --> 00:42:02,980

header nut and that's that's really one

774

00:42:06,839 --> 00:42:04,750

of the the main reasons for using

775

00:42:09,770 --> 00:42:06,849

worships both under the head and the nut

776

00:42:13,260 --> 00:42:09,780

is if you are rotating either one

777

00:42:15,450 --> 00:42:13,270

usually the joint surface is not as

778

00:42:17,450 --> 00:42:15,460

strong as the fastener so therefore you

779

00:42:22,820 --> 00:42:17,460

you have to have that too

780

00:42:25,820 --> 00:42:22,830

avoid embedment and then here's another

781

00:42:29,570 --> 00:42:25,830

one for shade tree mechanics if you have

782

00:42:33,050 --> 00:42:29,580

a washer under a bolt and it's rusted in

783

00:42:34,880 --> 00:42:33,060

place usually you can take a cold chisel

784

00:42:37,280 --> 00:42:34,890

and a hammer and not the washer

785

00:42:40,400 --> 00:42:37,290

laterally and get it get it loosened

786

00:42:46,190 --> 00:42:40,410

some so that you can loosen the bolt and

787

00:42:50,270 --> 00:42:46,200

washer now here's the plain flat and

788

00:42:52,490 --> 00:42:50,280

countersunk type for sure the here this

789

00:42:55,460 --> 00:42:52,500

is the ordinary hardware store variety

790

00:42:59,180 --> 00:42:55,470

and they're covered by all kinds of

791

00:43:01,609 --> 00:42:59,190

standards there's msan antsy so on which

792

00:43:03,560 --> 00:43:01,619

defines the outside diameter inside

793

00:43:06,620 --> 00:43:03,570

diameter and thickness for a given size

794

00:43:08,810 --> 00:43:06,630

so so normally you can just call out a

795

00:43:13,370 --> 00:43:08,820

dash number from one of these specs and

796

00:43:15,290 --> 00:43:13,380

your your cupboard the counter sunk

797

00:43:18,020 --> 00:43:15,300

counters are made with the countersink

798

00:43:21,829 --> 00:43:18,030

in them we're on a high-strength boat

799

00:43:25,820 --> 00:43:21,839

you have a larger radius under the head

800

00:43:27,710 --> 00:43:25,830

so you don't want point contact if it is

801

00:43:30,800 --> 00:43:27,720

this diameter is tight you could get

802

00:43:33,560 --> 00:43:30,810

point contact on the head radius so you

803

00:43:35,359 --> 00:43:33,570

want to counter sunk so that it will now

804

00:43:38,540 --> 00:43:35,369

distribute the load better under the

805

00:43:44,210 --> 00:43:38,550

head and you won't have that high stress

806

00:43:47,180 --> 00:43:44,220

concentration at the radius now on the

807

00:43:49,280 --> 00:43:47,190

course we covered the split lock washer

808

00:43:50,960 --> 00:43:49,290

the tooth lock washer and the disc lock

809

00:43:52,550 --> 00:43:50,970

washer I just wanted to point out that

810

00:43:54,730 --> 00:43:52,560

we'd already covered those in case

811

00:43:59,870 --> 00:43:54,740

somebody would wonder if why we hadn't

812

00:44:01,609 --> 00:43:59,880

then we go on to a another unique type

813

00:44:04,370 --> 00:44:01,619

and this is used a lot in the

814

00:44:09,220 --> 00:44:04,380

construction business the DTI of worship

815

00:44:12,560 --> 00:44:09,230

the direct tension indicating it is a

816

00:44:18,160 --> 00:44:12,570

flat ground washer that has these bumps

817

00:44:22,760 --> 00:44:18,170

stamped on it and but you have to use

818

00:44:24,790 --> 00:44:22,770

regular washers in addition to these in

819

00:44:27,260 --> 00:44:24,800

order to distribute the load properly

820

00:44:31,069 --> 00:44:27,270

because you don't want these grinding

821

00:44:34,940 --> 00:44:31,079

against the head or not of your boat

822

00:44:37,880 --> 00:44:34,950

and actually these are manufactured and

823

00:44:40,190 --> 00:44:37,890

they do tests to determine the loads on

824

00:44:45,109 --> 00:44:40,200

them if we're the amount of compression

825

00:44:47,959 --> 00:44:45,119

that you get on the bumps determines the

826

00:44:51,920 --> 00:44:47,969

axial load in the bolt so you took the

827

00:44:54,489 --> 00:44:51,930

thing with a torque wrench without

828

00:44:56,839 --> 00:44:54,499

reading the torque unless you want to

829

00:45:01,160 --> 00:44:56,849

down to the point that you have a

830

00:45:04,069 --> 00:45:01,170

certain gap left and underneath the

831

00:45:05,989 --> 00:45:04,079

washer and the bumps and you measure it

832

00:45:09,859 --> 00:45:05,999

with a feeler gauge so this way

833

00:45:11,959 --> 00:45:09,869

regardless of the coefficients of

834

00:45:13,880 --> 00:45:11,969

friction on the threads or the head or

835

00:45:17,479 --> 00:45:13,890

anything you can actually torque it down

836

00:45:24,910 --> 00:45:17,489

to where the gap you get will tell you

837

00:45:33,410 --> 00:45:28,160

now here's our old familiar belleville

838

00:45:36,439 --> 00:45:33,420

washers that named after the inventor

839

00:45:40,459 --> 00:45:36,449

who invented them way back in 1867 so

840

00:45:43,130 --> 00:45:40,469

they've been around a while it's also

841

00:45:51,880 --> 00:45:43,140

known as a comb washer or spring washer

842

00:45:55,219 --> 00:45:51,890

and these are designed with a load

843

00:45:57,650 --> 00:45:55,229

preload determination for a given washer

844

00:46:00,529 --> 00:45:57,660

or how much it takes the platen it and

845

00:46:02,719 --> 00:46:00,539

it will flatten elastically so a lot of

846

00:46:06,979 --> 00:46:02,729

times you can use them in a critical

847

00:46:09,319 --> 00:46:06,989

application where you want to limit the

848

00:46:12,049 --> 00:46:09,329

amount of axial load you have if you put

849

00:46:14,479 --> 00:46:12,059

a Belleville washer on and tell the

850

00:46:16,370 --> 00:46:14,489

mechanic okay just perk this thing until

851  
00:46:17,809 --> 00:46:16,380  
the washer starts to go flat and then

852  
00:46:23,439 --> 00:46:17,819  
quit regardless of what your torque

853  
00:46:26,449 --> 00:46:23,449  
wrench says it also can be used for

854  
00:46:30,079 --> 00:46:26,459  
absorbing differential thermal expansion

855  
00:46:32,239 --> 00:46:30,089  
between fastener and joint material for

856  
00:46:35,180 --> 00:46:32,249  
instance if you're holding big joints

857  
00:46:36,529 --> 00:46:35,190  
with of aluminum with steel bolts so you

858  
00:46:40,209 --> 00:46:36,539  
have a different coefficient of

859  
00:46:43,269 --> 00:46:40,219  
expansion and contraction you can put

860  
00:46:47,529 --> 00:46:43,279  
belleville washers on to absorb

861  
00:46:49,839 --> 00:46:47,539  
some of this a thermal expansion to keep

862  
00:46:53,729 --> 00:46:49,849  
from overloading or under loading the

863  
00:46:57,849 --> 00:46:53,739

joint you can use them in stacks in

864

00:47:08,559 --> 00:46:57,859

series or parallel in order to an in

865

00:47:10,329 --> 00:47:08,569

effect use them to become a spring now

866

00:47:12,669 --> 00:47:10,339

here's another one is that is kind of an

867

00:47:14,669 --> 00:47:12,679

oddball you don't see them around very

868

00:47:17,819 --> 00:47:14,679

much because they're expensive a

869

00:47:22,359 --> 00:47:17,829

self-aligning moisture you can use these

870

00:47:24,689 --> 00:47:22,369

on a structural shaped flange which is

871

00:47:27,759 --> 00:47:24,699

used usually has some taper to it and

872

00:47:29,380 --> 00:47:27,769

the reason they're so expensive is the

873

00:47:31,179 --> 00:47:29,390

washer and nut ermichine that's an

874

00:47:33,669 --> 00:47:31,189

assembly so you actually have a cone

875

00:47:36,999 --> 00:47:33,679

here two cousins that are rotating

876

00:47:39,939 --> 00:47:37,009

together to give you the proper

877

00:47:43,929 --> 00:47:39,949

alignment so that you still get axial

878

00:47:46,539 --> 00:47:43,939

loading on your boat instead of putting

879

00:47:49,899 --> 00:47:46,549

bending on it and this will take up to

880

00:47:52,449 --> 00:47:49,909

eight degrees maximum misalignment I

881

00:47:55,269 --> 00:47:52,459

don't remember now what the angle is on

882

00:47:56,679 --> 00:47:55,279

the i-beams and stuff like that I think

883

00:48:00,029 --> 00:47:56,689

it's less than that i believe it's like

884

00:48:04,569 --> 00:48:00,039

a 325 degree or something like that

885

00:48:08,729 --> 00:48:04,579

paper on the flange at seven now this is

886

00:48:16,029 --> 00:48:08,739

this is another one that gives you a

887

00:48:22,719 --> 00:48:16,039

axial reading without using a torque

888

00:48:25,569 --> 00:48:22,729

wrench and this is a PL PL I preload

889

00:48:28,779 --> 00:48:25,579

indicating that SPS has the patent on

890

00:48:34,719 --> 00:48:28,789

and on this one you have a regular

891

00:48:36,759 --> 00:48:34,729

washer a soft inner ring and then a ring

892

00:48:39,039 --> 00:48:36,769

that goes around that it has capstan

893

00:48:42,519 --> 00:48:39,049

holes in it and then a regular washer

894

00:48:47,289 --> 00:48:42,529

and you put all this assembly on you

895

00:48:52,120 --> 00:48:47,299

tighten it down and the this inner ring

896

00:48:56,300 --> 00:48:52,130

is actually a load cell if you will in

897

00:48:59,840 --> 00:48:56,310

that for a given amount of compression

898

00:49:01,370 --> 00:48:59,850

it has been pre calculated the amount of

899

00:49:04,880 --> 00:49:01,380

load that it takes to give you that

900

00:49:10,010 --> 00:49:04,890

compression so you can press it down to

901  
00:49:13,630 --> 00:49:10,020  
where this outer washer the cap span

902  
00:49:15,830 --> 00:49:13,640  
ring and the regular were sure are

903  
00:49:17,510 --> 00:49:15,840  
grinding against each other and we'll

904  
00:49:19,820 --> 00:49:17,520  
turn that means that this thing is

905  
00:49:22,760 --> 00:49:19,830  
compressed down to where you bottom

906  
00:49:24,830 --> 00:49:22,770  
doubt on this so you check the thing you

907  
00:49:26,720 --> 00:49:24,840  
can't turn that ring any longer you know

908  
00:49:29,660 --> 00:49:26,730  
you've got it to a certain axial load

909  
00:49:31,850 --> 00:49:29,670  
and they haven't color coded and

910  
00:49:35,750 --> 00:49:31,860  
available in all kinds of materials so

911  
00:49:37,460 --> 00:49:35,760  
that you can get them to use where you

912  
00:49:39,260 --> 00:49:37,470  
want to determine the load and there's

913  
00:49:44,210 --> 00:49:39,270

really no good way of doing it as far as

914

00:49:46,400 --> 00:49:44,220

measuring it now going to inserts which

915

00:49:51,530 --> 00:49:46,410

is a very common thing around here in

916

00:49:54,440 --> 00:49:51,540

the airspace world an insert is actually

917

00:49:57,020 --> 00:49:54,450

it's a special bushing that's threaded

918

00:49:59,510 --> 00:49:57,030

on the inside diameter and locked with

919

00:50:03,680 --> 00:49:59,520

threads or protrusions or a combination

920

00:50:07,700 --> 00:50:03,690

on the outside diameter and installed in

921

00:50:10,820 --> 00:50:07,710

a drilled molded or tapped hole it's

922

00:50:13,070 --> 00:50:10,830

used to provide a strong wear resistant

923

00:50:16,790 --> 00:50:13,080

tapped hole in a softer material

924

00:50:18,760 --> 00:50:16,800

normally than the fastener and you can

925

00:50:22,070 --> 00:50:18,770

also use them to repair stripped threads

926  
00:50:24,380 --> 00:50:22,080  
where you've stripped the threads in a

927  
00:50:27,380 --> 00:50:24,390  
whole rather than going to the next

928  
00:50:31,070 --> 00:50:27,390  
bigger size in taps you can put an

929  
00:50:33,770 --> 00:50:31,080  
insert in without opening the hole up as

930  
00:50:38,150 --> 00:50:33,780  
much in fact one of the places you use

931  
00:50:40,910 --> 00:50:38,160  
them is when people strip the spark plug

932  
00:50:44,570 --> 00:50:40,920  
holes in aluminum engines a lot of the

933  
00:50:46,430 --> 00:50:44,580  
times they use in hela coil or Keynes

934  
00:50:49,040 --> 00:50:46,440  
herders and I pletely use hela coils

935  
00:50:52,730 --> 00:50:49,050  
most the time for that and in general

936  
00:50:54,740 --> 00:50:52,740  
they're the two types the one that is

937  
00:50:56,690 --> 00:50:54,750  
threaded externally and those that are

938  
00:51:00,050 --> 00:50:56,700

locked by some method other than threads

939

00:51:03,310 --> 00:51:00,060

and we'll go into them and you get self

940

00:51:06,110 --> 00:51:03,320

tapping and all that sort of thing too

941

00:51:08,060 --> 00:51:06,120

now the earth space industry uses

942

00:51:09,820 --> 00:51:08,070

inserts and tapped holes and soft

943

00:51:13,430 --> 00:51:09,830

materials in order to

944

00:51:16,370 --> 00:51:13,440

increase the load carrying capability is

945

00:51:18,920 --> 00:51:16,380

pull out and this way you can use a

946

00:51:22,070 --> 00:51:18,930

smaller fastener and put in an insert

947

00:51:23,900 --> 00:51:22,080

and since the insert is normally about

948

00:51:26,990 --> 00:51:23,910

an eighth of an inch bigger in diameter

949

00:51:30,410 --> 00:51:27,000

than the internal thread in it you can

950

00:51:37,750 --> 00:51:30,420

take a 1032 bolt and install it in like

951  
00:51:44,060 --> 00:51:41,240  
here is one of the most common one and

952  
00:51:47,000 --> 00:51:44,070  
the generic name is key insert although

953  
00:51:52,250 --> 00:51:47,010  
some call them a solid threaded bushing

954  
00:51:56,360 --> 00:51:52,260  
or whatever and the insert we usually

955  
00:51:58,910 --> 00:51:56,370  
have external locking tangs that's these

956  
00:52:02,450 --> 00:51:58,920  
things you see here and when you install

957  
00:52:04,370 --> 00:52:02,460  
them after they're threaded in you pound

958  
00:52:07,100 --> 00:52:04,380  
those that there's a tool for pounding

959  
00:52:11,090 --> 00:52:07,110  
those down and they extend actually

960  
00:52:13,190 --> 00:52:11,100  
passed the threads you're the root

961  
00:52:17,120 --> 00:52:13,200  
diameter the threads to give you locking

962  
00:52:20,270 --> 00:52:17,130  
capability the the bigger diameters will

963  
00:52:22,190 --> 00:52:20,280

have four of those on them whereas the

964

00:52:23,840 --> 00:52:22,200

smaller ones will have to and of course

965

00:52:26,000 --> 00:52:23,850

you can get them that are not locking at

966

00:52:28,630 --> 00:52:26,010

all that you use some other method of

967

00:52:32,090 --> 00:52:28,640

triangle up the external thread on them

968

00:52:34,640 --> 00:52:32,100

now they are very labor-intensive to

969

00:52:38,690 --> 00:52:34,650

install so you don't install them unless

970

00:52:42,710 --> 00:52:38,700

you have to here is the other type the

971

00:52:47,690 --> 00:52:42,720

Gila coil which is I believe now owned

972

00:52:50,060 --> 00:52:47,700

by Black & Decker i think is the owner

973

00:52:55,220 --> 00:52:50,070

of the patent but they're also called a

974

00:52:57,230 --> 00:52:55,230

wire thread and it's usually made of

975

00:53:01,570 --> 00:52:57,240

stainless steel and has a diamond-shaped

976

00:53:03,890 --> 00:53:01,580

cross section that will actually form

977

00:53:06,110 --> 00:53:03,900

internal and external threads when

978

00:53:07,910 --> 00:53:06,120

install and it's like like taking a

979

00:53:10,280 --> 00:53:07,920

spring if you will and winding it down

980

00:53:12,110 --> 00:53:10,290

into a hole and the Diamonds section

981

00:53:14,410 --> 00:53:12,120

part on the back goes into the existing

982

00:53:17,930 --> 00:53:14,420

threads and then the diamond section on

983

00:53:20,330 --> 00:53:17,940

the inside is your thread diameter that

984

00:53:23,059 --> 00:53:20,340

you put your fastener in now they're

985

00:53:26,269 --> 00:53:23,069

usually coated to deter her

986

00:53:28,640 --> 00:53:26,279

ocean and seizing and you can get them

987

00:53:30,380 --> 00:53:28,650

both in locking and unlocking you see if

988

00:53:32,660 --> 00:53:30,390

you look at this this is the non locking

989

00:53:34,969 --> 00:53:32,670

here and this is a locking you actually

990

00:53:38,569 --> 00:53:34,979

have some deform coils down in here in

991

00:53:40,459 --> 00:53:38,579

this installment Tang which you may not

992

00:53:42,769 --> 00:53:40,469

may or may not be able to see on here

993

00:53:46,969 --> 00:53:42,779

it's broken off after installation now

994

00:53:50,749 --> 00:53:46,979

well the the difference between the Gila

995

00:53:57,130 --> 00:53:50,759

coil and the key insert the Keen cert is

996

00:54:00,380 --> 00:53:57,140

only available in one length for a size

997

00:54:02,779 --> 00:54:00,390

the Gila coils you can get them in

998

00:54:06,589 --> 00:54:02,789

different lengths you can get them up to

999

00:54:10,309 --> 00:54:06,599

from 1 D 2 3 D length where D is the

1000

00:54:12,799 --> 00:54:10,319

diameter of the fastener and another

1001  
00:54:16,849 --> 00:54:12,809  
thing of course you need a to open the

1002  
00:54:19,219 --> 00:54:16,859  
hole up less where you put a Gila coil

1003  
00:54:21,949 --> 00:54:19,229  
in so if you're repairing stripped

1004  
00:54:27,099 --> 00:54:21,959  
threads in an area where you don't have

1005  
00:54:30,620 --> 00:54:27,109  
a lot of room you can recap the whole

1006  
00:54:32,269 --> 00:54:30,630  
just slightly and get it opened up

1007  
00:54:40,870 --> 00:54:32,279  
enough that you can put a Gila coil in

1008  
00:54:53,269 --> 00:54:45,799  
here's a kind of a more rare tape this

1009  
00:54:57,980 --> 00:54:53,279  
is a locking tape insert in which you

1010  
00:55:00,529 --> 00:54:57,990  
have the split beam nut machined on the

1011  
00:55:05,599 --> 00:55:00,539  
bottom of it remember I showed you the

1012  
00:55:08,749 --> 00:55:05,609  
slip split beam lock nut earlier and so

1013  
00:55:12,470 --> 00:55:08,759

that you have the locking capability but

1014

00:55:14,269 --> 00:55:12,480

of course you are have a longer insert

1015

00:55:16,039 --> 00:55:14,279

because of this thing having to be

1016

00:55:19,460 --> 00:55:16,049

installed because this is not threaded

1017

00:55:22,220 --> 00:55:19,470

into the hole and these are made

1018

00:55:24,319 --> 00:55:22,230

primarily for aerospace usage out of

1019

00:55:29,029 --> 00:55:24,329

either eight to eighty six or inconel

1020

00:55:31,609 --> 00:55:29,039

718 and since you have less external

1021

00:55:33,859 --> 00:55:31,619

thread you have to be careful in soft

1022

00:55:36,380 --> 00:55:33,869

materials to make sure that you don't

1023

00:55:39,799 --> 00:55:36,390

exceed the pullout allowable when you

1024

00:55:42,200 --> 00:55:39,809

install a bolt in them because the

1025

00:55:46,880 --> 00:55:42,210

because of the split beam increasing the

1026

00:55:51,499 --> 00:55:46,890

overall length and here is one that

1027

00:55:55,640 --> 00:55:51,509

solves some problems but it also creates

1028

00:55:58,099 --> 00:55:55,650

some others the floating insert of

1029

00:56:00,529 --> 00:55:58,109

course if you're using and i'll be

1030

00:56:02,589 --> 00:56:00,539

covering us later on with if you're

1031

00:56:07,269 --> 00:56:02,599

using counter sunk or flathead fasteners

1032

00:56:11,089 --> 00:56:07,279

the countersink tries to sulfa line

1033

00:56:13,279 --> 00:56:11,099

fastener if you're going into a rigid

1034

00:56:15,230 --> 00:56:13,289

pepto now you have the two of them

1035

00:56:17,509 --> 00:56:15,240

working against each other which is not

1036

00:56:21,470 --> 00:56:17,519

too good well this solves that problem

1037

00:56:23,990 --> 00:56:21,480

in that the insert is in you have

1038

00:56:25,999 --> 00:56:24,000

actually an insert in the bottom of this

1039

00:56:28,819 --> 00:56:26,009

one so that it's externally threaded

1040

00:56:30,710 --> 00:56:28,829

just like the regular teen cert then you

1041

00:56:35,089 --> 00:56:30,720

have this little jobby that floats down

1042

00:56:38,630 --> 00:56:35,099

in here and so this will give you some

1043

00:56:43,190 --> 00:56:38,640

self-alignment when when using

1044

00:56:46,130 --> 00:56:43,200

countersunk fasteners but by putting all

1045

00:56:50,839 --> 00:56:46,140

of this in it it since this has to float

1046

00:56:53,629 --> 00:56:50,849

inside the main king cert you have a

1047

00:56:57,649 --> 00:56:53,639

smaller diameter

1048

00:57:00,239 --> 00:56:57,659

internally for a given diameter

1049

00:57:04,199 --> 00:57:00,249

externally so therefore you're losing

1050

00:57:07,049 --> 00:57:04,209

some to put that floating capability in

1051  
00:57:10,939 --> 00:57:07,059  
you're losing some so you might wind up

1052  
00:57:13,919 --> 00:57:10,949  
having to go to a larger diameter insert

1053  
00:57:18,709 --> 00:57:13,929  
externally then you nor normally would

1054  
00:57:22,169 --> 00:57:18,719  
use now here's the self-tapping inserts

1055  
00:57:24,749 --> 00:57:22,179  
this is usually a self or so solid

1056  
00:57:27,089 --> 00:57:24,759  
bushing with either tapered external

1057  
00:57:31,379 --> 00:57:27,099  
threads like a self-tapping screw like

1058  
00:57:35,519 --> 00:57:31,389  
this or you can have and you can have

1059  
00:57:39,539 --> 00:57:35,529  
them also solid with a nighlok pelletier

1060  
00:57:42,479 --> 00:57:39,549  
for locking them or you can have one

1061  
00:57:45,929 --> 00:57:42,489  
that they use in plastic quite a bit

1062  
00:57:50,299 --> 00:57:45,939  
what they call a speed cert and this is

1063  
00:57:53,119 --> 00:57:50,309

used I think for like in electrical

1064

00:57:58,459 --> 00:57:53,129

circuit boards and stuff like that it

1065

00:58:03,509 --> 00:57:58,469

you drill a hole and you actually can

1066

00:58:07,699 --> 00:58:03,519

push self tap the thing by deforming the

1067

00:58:14,759 --> 00:58:07,709

plastic without generating any shavings

1068

00:58:18,029 --> 00:58:14,769

so we will continue next with the Sun