

## Fastener Torque

### Torque Definitions (Cont'd)

Free Running Torque (No Load Torque) - Torque required to overcome kinetic friction between mating threads. It can be measured in either the loosening or tightening direction. Free running torque does not include torque required to overcome a self-locking feature or to increase or decrease the axial load in the fastener. Under normal conditions, free running torque is negligible.

1  
00:01:12,040 --> 00:01:08,860  
okay all right we'll continue with tap

2  
00:01:14,200 --> 00:01:12,050  
threads and in case you're wondering

3  
00:01:16,630 --> 00:01:14,210  
what page you were you're on those of

4  
00:01:23,230 --> 00:01:16,640  
you who have joined us for this session

5  
00:01:28,090 --> 00:01:23,240  
this page should be page 926 and now

6  
00:01:31,719 --> 00:01:28,100  
tapping as done with either by hand or

7  
00:01:35,320 --> 00:01:31,729  
by machine and the bulk of the metal

8  
00:01:37,210 --> 00:01:35,330  
those is taken out with the tap drill of

9  
00:01:39,010 --> 00:01:37,220  
course which has a diameter equal to or

10  
00:01:42,280 --> 00:01:39,020  
slightly greater than the root diameter

11  
00:01:45,400 --> 00:01:42,290  
the thread and of course that we covered

12  
00:01:51,550 --> 00:01:45,410  
the number of tempered threads and so on

13  
00:01:53,109 --> 00:01:51,560

and then the bottom tap one of the

14

00:01:56,890 --> 00:01:53,119

things I wanted to mention there is that

15

00:01:59,109 --> 00:01:56,900

I guess in some cases you have to even

16

00:02:01,240 --> 00:01:59,119

take a they have the hundred and twenty

17

00:02:02,859 --> 00:02:01,250

degree cone and I think on the bottom of

18

00:02:04,480 --> 00:02:02,869

them and you have to grind it off I

19

00:02:06,160 --> 00:02:04,490

think sometimes if you really want to

20

00:02:11,130 --> 00:02:06,170

get all the way down to the bottom of

21

00:02:14,170 --> 00:02:11,140

the hole now here's Acme threads and

22

00:02:15,550 --> 00:02:14,180

those are kind of an oddball type but

23

00:02:18,520 --> 00:02:15,560

nevertheless they've been around since

24

00:02:22,390 --> 00:02:18,530

the 1800s and they're used for

25

00:02:26,250 --> 00:02:22,400

transmitting power unlike on jacks and

26  
00:02:29,530 --> 00:02:26,260  
reversing motions on machinery in fact

27  
00:02:32,680 --> 00:02:29,540  
those of you who've ever leveled a house

28  
00:02:35,860 --> 00:02:32,690  
or something with a house jack they are

29  
00:02:39,759 --> 00:02:35,870  
Acme threads they're kind of a square

30  
00:02:43,660 --> 00:02:39,769  
cut tape thread and scissors Jack's

31  
00:02:47,020 --> 00:02:43,670  
sometimes have Acme threads on them they

32  
00:02:49,539 --> 00:02:47,030  
have a general-purpose fit class of two

33  
00:02:51,539 --> 00:02:49,549  
G 3G and 4G with two G being the

34  
00:02:54,340 --> 00:02:51,549  
sloppiest and four G the tightest and

35  
00:02:56,080 --> 00:02:54,350  
they have a series of diameters and

36  
00:02:58,210 --> 00:02:56,090  
threads that are to be used whenever

37  
00:03:00,910 --> 00:02:58,220  
possible and they call it centralizing

38  
00:03:05,020 --> 00:03:00,920

for the tolerances and have the three

39

00:03:07,000 --> 00:03:05,030

three classes and the two see of course

40

00:03:08,650 --> 00:03:07,010

is the the worst and the four C's the

41

00:03:10,590 --> 00:03:08,660

best depending on what you want as far

42

00:03:15,819 --> 00:03:10,600

as backlash or anything like that goes

43

00:03:16,440 --> 00:03:15,829

and the same tolerance designations are

44

00:03:22,979 --> 00:03:16,450

used for both

45

00:03:24,660 --> 00:03:22,989

internal external threads now here they

46

00:03:32,750 --> 00:03:24,670

are as you can see they're kind of a

47

00:03:36,630 --> 00:03:32,760

square type thread very thick stubby and

48

00:03:38,190 --> 00:03:36,640

transmit a lot of power and in this case

49

00:03:39,840 --> 00:03:38,200

they really don't have much of a radius

50

00:03:41,340 --> 00:03:39,850

in the bottom because they make them so

51  
00:03:43,259 --> 00:03:41,350  
strong if they figure that they'll carry

52  
00:03:46,589 --> 00:03:43,269  
a carry the load and of course there's

53  
00:03:48,870 --> 00:03:46,599  
no there's no impact loads normally on

54  
00:03:50,880 --> 00:03:48,880  
these because it's something that you're

55  
00:03:54,600 --> 00:03:50,890  
turning so slowly that you don't

56  
00:03:56,910 --> 00:03:54,610  
generate any impact loading then we go

57  
00:03:59,160 --> 00:03:56,920  
to stub acne it's about the same thing

58  
00:04:04,890 --> 00:03:59,170  
as the other one except that it has a

59  
00:04:09,150 --> 00:04:04,900  
shorter height on the threads and the

60  
00:04:12,150 --> 00:04:09,160  
seat this is the one I believe no it

61  
00:04:14,850 --> 00:04:12,160  
isn't either I was thinking one of them

62  
00:04:18,390 --> 00:04:14,860  
with a English and the Americans have a

63  
00:04:24,270 --> 00:04:18,400

different set up on it but they stub

64

00:04:28,500 --> 00:04:24,280

acne is the regular is 0.5 pitch while

65

00:04:31,020 --> 00:04:28,510

the stub is 0.3 and if you turn over you

66

00:04:32,760 --> 00:04:31,030

can see the difference on the next table

67

00:04:37,409 --> 00:04:32,770

you see it really just has shorter

68

00:04:38,940 --> 00:04:37,419

threads on it in in this direction and

69

00:04:40,770 --> 00:04:38,950

of course all the different thread

70

00:04:43,320 --> 00:04:40,780

geometries and everything are on there

71

00:04:45,330 --> 00:04:43,330

and the pitch diameter and all that you

72

00:04:48,659 --> 00:04:45,340

can look up at your own leisure when you

73

00:04:55,230 --> 00:04:48,669

feel that do you need something to help

74

00:04:57,600 --> 00:04:55,240

your insomnia ah buttress threads they

75

00:04:59,310 --> 00:04:57,610

have been around a long time too and

76  
00:05:02,090 --> 00:04:59,320  
they're kind of special and they're used

77  
00:05:05,400 --> 00:05:02,100  
where loading is in one direction

78  
00:05:08,130 --> 00:05:05,410  
typical examples are airplane propeller

79  
00:05:11,040 --> 00:05:08,140  
hubs columns were hydraulic presses and

80  
00:05:13,260 --> 00:05:11,050  
breech assemblies of large guns they

81  
00:05:15,840 --> 00:05:13,270  
have a flat angle on the the loading

82  
00:05:18,330 --> 00:05:15,850  
side of only 7 degrees from the

83  
00:05:22,219 --> 00:05:18,340  
perpendicular and in a pressure angle of

84  
00:05:26,339 --> 00:05:22,229  
45 degrees and this is the one that the

85  
00:05:29,320 --> 00:05:26,349  
British in the Americans differ on the

86  
00:05:35,380 --> 00:05:29,330  
height of the threads

87  
00:05:39,180 --> 00:05:35,390  
point four pitch and 6/10 pitch but with

88  
00:05:42,780 --> 00:05:39,190

us prefers the point four and the

89

00:05:45,100 --> 00:05:42,790

British believe the use of the point six

90

00:05:46,680 --> 00:05:45,110

now I'm sorry Americans use the point

91

00:05:52,120 --> 00:05:46,690

six and the British use the point four

92

00:05:54,610 --> 00:05:52,130

but anyway a guy pointed out an example

93

00:05:58,330 --> 00:05:54,620

of these to me here while back that they

94

00:06:01,120 --> 00:05:58,340

had a press in their plant that they had

95

00:06:03,190 --> 00:06:01,130

to fix and he found that it had these

96

00:06:06,610 --> 00:06:03,200

odd ball threads on it called buttress

97

00:06:08,020 --> 00:06:06,620

threads and he knew that I was into

98

00:06:10,270 --> 00:06:08,030

fasteners he said you ever hear a

99

00:06:12,070 --> 00:06:10,280

butter threads down there I've heard of

100

00:06:13,750 --> 00:06:12,080

them they're not very common and you see

101

00:06:15,970 --> 00:06:13,760

there aren't kind of odd here here's

102

00:06:18,340 --> 00:06:15,980

that seven degree angle on the pressure

103

00:06:22,450 --> 00:06:18,350

face of them here now this is this is

104

00:06:27,240 --> 00:06:22,460

two different pictures from a an suspect

105

00:06:31,000 --> 00:06:27,250

I believe one shows threads with a

106

00:06:35,200 --> 00:06:31,010

radius up here the other one shows

107

00:06:38,020 --> 00:06:35,210

threads with no radius and they have

108

00:06:42,070 --> 00:06:38,030

their use and the the thing about this

109

00:06:44,650 --> 00:06:42,080

this guy found out with his press if you

110

00:06:48,940 --> 00:06:44,660

want to fix them these are normally

111

00:06:51,460 --> 00:06:48,950

machined cut on there's no no taps no

112

00:06:55,030 --> 00:06:51,470

dice no nothing for them you have to fix

113

00:06:58,540 --> 00:06:55,040

them yourself drain them in place now if

114

00:07:01,300 --> 00:06:58,550

we go to cross-sectional areas for third

115

00:07:03,160 --> 00:07:01,310

calculation you have different cross

116

00:07:06,640 --> 00:07:03,170

sectional areas for tension and shear

117

00:07:08,620 --> 00:07:06,650

stress calculations if a fastener is

118

00:07:10,390 --> 00:07:08,630

loaded in shear with no threads in the

119

00:07:12,250 --> 00:07:10,400

shear plane of the hole and the full

120

00:07:15,190 --> 00:07:12,260

shank area can be used for the shear

121

00:07:17,530 --> 00:07:15,200

stress calculations for tensile stress

122

00:07:19,210 --> 00:07:17,540

you use a minimum area through the

123

00:07:22,710 --> 00:07:19,220

threaded portion of fastener but it's

124

00:07:25,060 --> 00:07:22,720

it's not a circle with a diameter of

125

00:07:28,810 --> 00:07:25,070

equal to the minor diameter because

126  
00:07:30,100 --> 00:07:28,820  
since you have a root on one side and

127  
00:07:32,440 --> 00:07:30,110  
thread on the other side you get

128  
00:07:36,070 --> 00:07:32,450  
slightly better benefit than that on the

129  
00:07:38,080 --> 00:07:36,080  
diameter so so you get an effective

130  
00:07:41,020 --> 00:07:38,090  
diameter this slightly larger and there

131  
00:07:42,710 --> 00:07:41,030  
is a formula for calculating it there

132  
00:07:46,880 --> 00:07:42,720  
are a number of formulas for

133  
00:07:50,720 --> 00:07:46,890  
that goes but here is a common one in

134  
00:07:53,000 --> 00:07:50,730  
which n is the threads per inch in the

135  
00:07:55,490 --> 00:07:53,010  
English system and D is the shank

136  
00:07:57,290 --> 00:07:55,500  
diameter so you have this is your

137  
00:07:59,510 --> 00:07:57,300  
correction factor here for the fact

138  
00:08:02,450 --> 00:07:59,520

you're not using the full diameter of it

139

00:08:04,820 --> 00:08:02,460

and then for metric fasteners you have

140

00:08:07,070 --> 00:08:04,830

this for the correction factor where P

141

00:08:09,110 --> 00:08:07,080

is is the thread pitch in millimeters

142

00:08:12,830 --> 00:08:09,120

and D is the shank diameter in

143

00:08:14,570 --> 00:08:12,840

millimeters so and in the appendices

144

00:08:17,960 --> 00:08:14,580

which you people don't have but we'll be

145

00:08:21,440 --> 00:08:17,970

getting later we have a derivation of

146

00:08:26,720 --> 00:08:21,450

this tension formula for calculating the

147

00:08:28,880 --> 00:08:26,730

cross sectional areas now here's a

148

00:08:32,089 --> 00:08:28,890

little handy-dandy formula for

149

00:08:34,459 --> 00:08:32,099

calculating thread pullout and this is

150

00:08:36,890 --> 00:08:34,469

one that I've never seen in a textbook I

151  
00:08:40,790 --> 00:08:36,900  
got it from some of the people I worked

152  
00:08:43,850 --> 00:08:40,800  
with at Martin Marietta it's for

153  
00:08:47,810 --> 00:08:43,860  
sheering off threads in a hole where

154  
00:08:50,810 --> 00:08:47,820  
normally when you tap into a hole the

155  
00:08:54,380 --> 00:08:50,820  
material you're tapping into is weaker

156  
00:08:57,710 --> 00:08:54,390  
than the fastener so you're concerned

157  
00:08:59,840 --> 00:08:57,720  
about how long the thread engagement you

158  
00:09:04,540 --> 00:08:59,850  
have to have keep from pulling the thing

159  
00:09:07,760 --> 00:09:04,550  
out so this this formula helps you to

160  
00:09:10,579 --> 00:09:07,770  
conservatively arrive at that you have

161  
00:09:14,000 --> 00:09:10,589  
pi times a mean diameter and the mean

162  
00:09:16,760 --> 00:09:14,010  
diameter is usually a pitch diameter and

163  
00:09:19,010 --> 00:09:16,770

you have an allowable for your material

164

00:09:22,430 --> 00:09:19,020

in shear whatever it is if you're

165

00:09:26,180 --> 00:09:22,440

working with yield you put in the shear

166

00:09:27,860 --> 00:09:26,190

yield allowable and if it's ultimate you

167

00:09:30,020 --> 00:09:27,870

put in the ultimate allowable then the

168

00:09:32,300 --> 00:09:30,030

length of engagement now that length of

169

00:09:36,260 --> 00:09:32,310

engagement is a length of full thread

170

00:09:39,950 --> 00:09:36,270

engagement the denominator has the 3 in

171

00:09:42,490 --> 00:09:39,960

it if you were going to be totally

172

00:09:46,280 --> 00:09:42,500

theoretical about it you had a perfectly

173

00:09:48,440 --> 00:09:46,290

mated threads then that bigger could go

174

00:09:50,510 --> 00:09:48,450

down as low as 2 because actually if you

175

00:09:52,940 --> 00:09:50,520

visualize it for a moment what you're

176

00:09:56,519 --> 00:09:52,950

doing you're pulling out a little

177

00:09:59,009 --> 00:09:56,529

cylindrical shell and if you

178

00:10:02,399 --> 00:09:59,019

things exactly at the pitch diameter so

179

00:10:05,399 --> 00:10:02,409

the the external internal thread were

180

00:10:07,229 --> 00:10:05,409

the same then you would be splitting

181

00:10:08,909 --> 00:10:07,239

that little shell between the two of

182

00:10:10,709 --> 00:10:08,919

them so this factor could go all the way

183

00:10:15,179 --> 00:10:10,719

down to two but since threads don't make

184

00:10:18,599 --> 00:10:15,189

that way the three is put in SA fudge

185

00:10:22,769 --> 00:10:18,609

factors I have mentioned mentioned here

186

00:10:27,029 --> 00:10:22,779

and there are some other methods given

187

00:10:32,129 --> 00:10:27,039

in h28 mill handbook h28 for calculating

188

00:10:33,509 --> 00:10:32,139

pull out and once again you can some of

189

00:10:35,369 --> 00:10:33,519

them are a lot more complicated than

190

00:10:37,639 --> 00:10:35,379

what I've done here what I've done if

191

00:10:41,489 --> 00:10:37,649

you have a chance to do it will work so

192

00:10:45,709 --> 00:10:41,499

you can go ahead and go with it now

193

00:10:49,679 --> 00:10:45,719

moving into the fatigue resistant bolt

194

00:10:51,839 --> 00:10:49,689

section of course people usually don't

195

00:10:55,409 --> 00:10:51,849

even think about that and it gets them

196

00:10:59,249 --> 00:10:55,419

in trouble but if you have cyclic

197

00:11:02,249 --> 00:10:59,259

loading on a joint then you need to

198

00:11:05,849 --> 00:11:02,259

minimize the stress risers created

199

00:11:08,099 --> 00:11:05,859

during the manufacturing cycle and some

200

00:11:11,609 --> 00:11:08,109

of these are the threads thread run out

201  
00:11:16,249 --> 00:11:11,619  
thread Phillip radius and work hardening

202  
00:11:20,489 --> 00:11:16,259  
through forming of the bolts so you also

203  
00:11:23,759 --> 00:11:20,499  
have to monitor the installation the

204  
00:11:25,549 --> 00:11:23,769  
bolt closely to minimize the cycling

205  
00:11:28,919 --> 00:11:25,559  
modes and of course one of the things

206  
00:11:31,859 --> 00:11:28,929  
that you do is this is one of the cases

207  
00:11:37,349 --> 00:11:31,869  
in which Murphy can tighten them up

208  
00:11:40,469 --> 00:11:37,359  
tight because with a particular knit to

209  
00:11:44,489 --> 00:11:40,479  
be as tight as possible because it cuts

210  
00:11:47,219 --> 00:11:44,499  
down on the cyclic loading now one of

211  
00:11:49,649 --> 00:11:47,229  
the things you can use of course is the

212  
00:11:54,599 --> 00:11:49,659  
cold fasteners with cold rolled threads

213  
00:11:56,789 --> 00:11:54,609

because that gives you the residual

214

00:12:01,229 --> 00:11:56,799

compressive stresses in the thread

215

00:12:03,989 --> 00:12:01,239

surfaces and it gives them more

216

00:12:08,219 --> 00:12:03,999

particular resistance because the TIG

217

00:12:10,020 --> 00:12:08,229

only works in tension so as long as you

218

00:12:12,720 --> 00:12:10,030

keep things in compression

219

00:12:15,510 --> 00:12:12,730

you're right it's just like with glass

220

00:12:17,430 --> 00:12:15,520

they don't worry about cracks and glass

221

00:12:19,020 --> 00:12:17,440

if it's in compression because doesn't

222

00:12:20,240 --> 00:12:19,030

do anything it's just in tension well

223

00:12:23,880 --> 00:12:20,250

it's the same same way here if you

224

00:12:25,380 --> 00:12:23,890

fatigue is compression compression is

225

00:12:29,460 --> 00:12:25,390

fine but tensions where it gets you in

226

00:12:32,370 --> 00:12:29,470

trouble so some of these fasteners as I

227

00:12:35,190 --> 00:12:32,380

mentioned earlier you actually have to

228

00:12:36,510 --> 00:12:35,200

cold roll the threads in order to get it

229

00:12:39,150 --> 00:12:36,520

up the strength that you want it so

230

00:12:41,100 --> 00:12:39,160

that's a good fatigue bolt also the J

231

00:12:42,870 --> 00:12:41,110

threads are better than regular threads

232

00:12:45,720 --> 00:12:42,880

in fatigue because they have the larger

233

00:12:49,040 --> 00:12:45,730

radius then here's one of the other

234

00:12:51,360 --> 00:12:49,050

problems that you can run into that

235

00:12:54,990 --> 00:12:51,370

people every once in a while forget

236

00:12:58,620 --> 00:12:55,000

about is the elongation limits on

237

00:13:01,320 --> 00:12:58,630

materials one of the rules of thumb on

238

00:13:04,680 --> 00:13:01,330

designing of fasteners is don't use a

239

00:13:09,390 --> 00:13:04,690

material at a strength level that has an

240

00:13:12,590 --> 00:13:09,400

elongation below 10% because when you

241

00:13:15,960 --> 00:13:12,600

get down below 10% your stress risers

242

00:13:19,590 --> 00:13:15,970

become much more important as a matter

243

00:13:21,750 --> 00:13:19,600

of fact h-11 tool steel which is used

244

00:13:23,460 --> 00:13:21,760

for high strength fasteners you can get

245

00:13:25,770 --> 00:13:23,470

in trouble and some of the aerospace

246

00:13:27,630 --> 00:13:25,780

companies are backing off on using it at

247

00:13:30,030 --> 00:13:27,640

the real high strength because of that

248

00:13:32,070 --> 00:13:30,040

because it goes down about a 7 or 8

249

00:13:33,930 --> 00:13:32,080

percent elongation and when you get down

250

00:13:39,510 --> 00:13:33,940

that low then you can get brittle

251  
00:13:43,829 --> 00:13:39,520  
failures now J threads as I mentioned

252  
00:13:47,329 --> 00:13:43,839  
they're our batter and using countersunk

253  
00:13:50,370 --> 00:13:47,339  
coursers under the heads to minimize the

254  
00:13:53,430 --> 00:13:50,380  
washer contact with the Phillip radius

255  
00:13:56,970 --> 00:13:53,440  
and then if you really want to get

256  
00:14:00,950 --> 00:13:56,980  
sticky and have a super-duper for taking

257  
00:14:04,920 --> 00:14:00,960  
tight bolt you can undercut the shank

258  
00:14:07,230 --> 00:14:04,930  
down to the same diameter as the minor

259  
00:14:09,690 --> 00:14:07,240  
diameter the threads and this does away

260  
00:14:12,480 --> 00:14:09,700  
with your stress concentration on your

261  
00:14:14,100 --> 00:14:12,490  
thread run out because you know having a

262  
00:14:16,560 --> 00:14:14,110  
run out there because you just have a

263  
00:14:19,110 --> 00:14:16,570

smooth shank and when the thread runs

264

00:14:22,590 --> 00:14:19,120

out it runs out on top of the thing more

265

00:14:23,319 --> 00:14:22,600

or less so so that a undercut diameter

266

00:14:26,169 --> 00:14:23,329

fastener

267

00:14:29,079 --> 00:14:26,179

is better in fatigue than one a regular

268

00:14:35,710 --> 00:14:29,089

fastener where the shank diameter is

269

00:14:40,150 --> 00:14:35,720

normally equal to the major diameter of

270

00:14:46,720 --> 00:14:40,160

the threads now the hardness of nut less

271

00:14:53,049 --> 00:14:46,730

than bolt hardness that one can be very

272

00:14:56,169 --> 00:14:53,059

much a problem in some cases since the

273

00:14:59,019 --> 00:14:56,179

bolt load is initially reacted on the

274

00:15:01,210 --> 00:14:59,029

first one or two threads and then has to

275

00:15:04,840 --> 00:15:01,220

deform something in order to spread it

276

00:15:07,619 --> 00:15:04,850

out you want your nut to be softer than

277

00:15:12,699 --> 00:15:07,629

the bolt so you can spread your load out

278

00:15:16,059 --> 00:15:12,709

and a rule of thumb is that the maximum

279

00:15:18,009 --> 00:15:16,069

hardness of the nut should not exceed

280

00:15:20,949 --> 00:15:18,019

the minimum hardness of the bolt and

281

00:15:24,009 --> 00:15:20,959

that's even stretching it normally you

282

00:15:27,639 --> 00:15:24,019

would want it to be for instance a

283

00:15:30,759 --> 00:15:27,649

hundred and sixty ksi bolt you use a 125

284

00:15:34,629 --> 00:15:30,769

145 nut on it in order to distribute the

285

00:15:36,039 --> 00:15:34,639

load now this court case that I

286

00:15:39,329 --> 00:15:36,049

mentioned to you earlier the chair

287

00:15:44,499 --> 00:15:39,339

failure that was the thing that caused

288

00:15:46,749 --> 00:15:44,509

that chair to fail was that they this

289

00:15:50,169 --> 00:15:46,759

furniture manufacturers don't have too

290

00:15:51,699 --> 00:15:50,179

many fatigue engineers on the job they

291

00:15:53,350 --> 00:15:51,709

go out up the hardware store buy

292

00:15:55,269 --> 00:15:53,360

whatever's cheapest and they bought the

293

00:15:57,729 --> 00:15:55,279

bolts from one place and the nuts from

294

00:16:02,169 --> 00:15:57,739

another place and this deformed thread

295

00:16:03,970 --> 00:16:02,179

nut in deforming it they had actually

296

00:16:07,629 --> 00:16:03,980

worked hardened it to where it was

297

00:16:10,389 --> 00:16:07,639

harder than the bolt so what it did when

298

00:16:12,879 --> 00:16:10,399

they put it on it just stripped the

299

00:16:16,269 --> 00:16:12,889

threads the boldest that was going on

300

00:16:18,639 --> 00:16:16,279

and then in a matter of about six months

301

00:16:20,079 --> 00:16:18,649

this guy is brand new chair fell apart

302

00:16:22,929 --> 00:16:20,089

and set him for a ride

303

00:16:27,790 --> 00:16:22,939

so he sued the furniture company and

304

00:16:30,850 --> 00:16:27,800

that's where I got in on it but

305

00:16:37,180 --> 00:16:30,860

here's a desirable joint loading diagram

306

00:16:39,970 --> 00:16:37,190

now you want a stiffness fastener joint

307

00:16:41,410 --> 00:16:39,980

stiffness ratio of five or higher and

308

00:16:43,780 --> 00:16:41,420

we'll go through some of the things on

309

00:16:47,260 --> 00:16:43,790

calculating joint stiffness fastener

310

00:16:52,690 --> 00:16:47,270

stiffness and so on to minimize the

311

00:16:54,940 --> 00:16:52,700

cyclic loading on the fastener and

312

00:16:56,530 --> 00:16:54,950

coming back again I keep repeating this

313

00:16:59,050 --> 00:16:56,540

one but it's worth repeating avoid

314

00:17:03,100 --> 00:16:59,060

capped holes if you can don't use them

315

00:17:04,810 --> 00:17:03,110

unless you have to I was on a design

316

00:17:07,810 --> 00:17:04,820

review here one time in which this young

317

00:17:09,490 --> 00:17:07,820

engineer came up with a design and he

318

00:17:12,370 --> 00:17:09,500

had heard that when you used aluminum

319

00:17:15,370 --> 00:17:12,380

you were supposed to use inserts so

320

00:17:17,170 --> 00:17:15,380

instead of bolting through he put

321

00:17:18,820 --> 00:17:17,180

through holes in butt tap them for

322

00:17:22,500 --> 00:17:18,830

inserts because after all you're

323

00:17:24,880 --> 00:17:22,510

supposed to use inserts in aluminum but

324

00:17:28,900 --> 00:17:24,890

if you have a chance to use through

325

00:17:31,420 --> 00:17:28,910

bolting that is the most efficient most

326  
00:17:33,670 --> 00:17:31,430  
trouble-free way of doing it regardless

327  
00:17:36,100 --> 00:17:33,680  
of what what you're bolting in all right

328  
00:17:41,410 --> 00:17:36,110  
now the tap holes are cut rather than

329  
00:17:44,830 --> 00:17:41,420  
rolled and the radius of a tap Pole is

330  
00:17:47,260 --> 00:17:44,840  
not measured normally if you want it

331  
00:17:49,600 --> 00:17:47,270  
measured it's a lot of trouble so you

332  
00:17:51,970 --> 00:17:49,610  
could get all sorts of undetected stress

333  
00:17:53,410 --> 00:17:51,980  
risers because think had it from a

334  
00:17:57,130 --> 00:17:53,420  
practical standpoint you've got a

335  
00:17:58,900 --> 00:17:57,140  
quarter inch hole inspector is gonna go

336  
00:18:00,340 --> 00:17:58,910  
up and look down in it and say yep

337  
00:18:01,630 --> 00:18:00,350  
there's all there it looks alright to me

338  
00:18:06,240 --> 00:18:01,640

and that's about the amount of

339

00:18:09,670 --> 00:18:06,250

inspection you'll get on it now use a

340

00:18:12,730 --> 00:18:09,680

lot of small diameter bolts if you can

341

00:18:16,600 --> 00:18:12,740

in order to give you a more elastic

342

00:18:20,050 --> 00:18:16,610

system because the that gives you a

343

00:18:24,250 --> 00:18:20,060

better ratio of bolts joint stiffness to

344

00:18:27,220 --> 00:18:24,260

fastener stiffness and of course that

345

00:18:30,370 --> 00:18:27,230

kicks a labour cost up so you have to

346

00:18:34,230 --> 00:18:30,380

wait to see which what you're going to

347

00:18:36,970 --> 00:18:34,240

do in order to make the joint survive

348

00:18:39,130 --> 00:18:36,980

now the other thing you you have to do

349

00:18:40,830 --> 00:18:39,140

is consider the thermal loading and the

350

00:18:42,630 --> 00:18:40,840

joint remember I mentioned

351

00:18:46,560 --> 00:18:42,640

earlier about using Belleville washers

352

00:18:48,570 --> 00:18:46,570

to give you a longer spring constant if

353

00:18:52,710 --> 00:18:48,580

you will and a bolted joint to take the

354

00:18:55,110 --> 00:18:52,720

thermal cycling and particularly if the

355

00:18:59,039 --> 00:18:55,120

bolt and the joint materials are

356

00:19:01,680 --> 00:18:59,049

different then you have to watch it

357

00:19:04,560 --> 00:19:01,690

closely we had a problem on the center

358

00:19:07,830 --> 00:19:04,570

vehical when they were using good old 80

359

00:19:10,230 --> 00:19:07,840

to 86 bolts on aluminum flanges the only

360

00:19:13,440 --> 00:19:10,240

thing is they tighten them up Terk them

361

00:19:15,690 --> 00:19:13,450

down at room temperature then when they

362

00:19:18,360 --> 00:19:15,700

tanked up with liquid hydrogen and

363

00:19:23,789 --> 00:19:18,370

liquid oxygen the temperature went down

364

00:19:27,840 --> 00:19:23,799

to something like minus 300 the aluminum

365

00:19:31,500 --> 00:19:27,850

shrink and it started leaking because

366

00:19:34,049 --> 00:19:31,510

the bolts got loose so they like to

367

00:19:35,669 --> 00:19:34,059

never hit a happy balance on that of

368

00:19:36,990 --> 00:19:35,679

getting bolts the fact they had to get

369

00:19:39,330 --> 00:19:37,000

higher strength bolts and they could

370

00:19:41,130 --> 00:19:39,340

crank the torque up so that the thing

371

00:19:43,409 --> 00:19:41,140

would be alright at room temperature and

372

00:19:45,510 --> 00:19:43,419

still not leak at the cryogenic

373

00:19:47,570 --> 00:19:45,520

temperature so this is a this is a

374

00:19:50,130 --> 00:19:47,580

problem you have to be careful about

375

00:19:52,769 --> 00:19:50,140

then here's the other thing that that

376

00:19:54,630 --> 00:19:52,779

you should do this is one of the few

377

00:19:57,690 --> 00:19:54,640

places that I agree with some of the

378

00:20:00,269 --> 00:19:57,700

automotive companies on is turcica

379

00:20:03,750 --> 00:20:00,279

fasteners close to yield point if it's a

380

00:20:06,480 --> 00:20:03,760

fatigue joint and if you do enough

381

00:20:08,940 --> 00:20:06,490

testing to determine where it is then

382

00:20:12,120 --> 00:20:08,950

you can torque up to 90 to 95% of yield

383

00:20:15,870 --> 00:20:12,130

and the higher preload decreases the

384

00:20:20,039 --> 00:20:15,880

cyclic loading and I have some figures

385

00:20:23,159 --> 00:20:20,049

here to indicate this if you want to

386

00:20:27,779 --> 00:20:23,169

leaf back and forth between 10 7 and 10

387

00:20:29,940 --> 00:20:27,789

8 the or I'll tell you what if you will

388

00:20:34,200 --> 00:20:29,950

go to the next page with the the graph

389

00:20:37,769 --> 00:20:34,210

there and and then bets it can keep hers

390

00:20:43,680 --> 00:20:37,779

where it is there we go now we work back

391

00:20:48,810 --> 00:20:43,690

and forth on here here is the initial

392

00:20:50,610 --> 00:20:48,820

loading here is yield so we're so here's

393

00:20:52,240 --> 00:20:50,620

the initial loading before putting

394

00:20:56,950 --> 00:20:52,250

external load on the thing

395

00:20:59,649 --> 00:20:56,960

now when you put the load on the cyclic

396

00:21:04,360 --> 00:20:59,659

loading on the fastener is just the part

397

00:21:06,310 --> 00:21:04,370

between here and here so if as you'll

398

00:21:09,039 --> 00:21:06,320

see when I show the the next one of

399

00:21:11,230 --> 00:21:09,049

these where I deliberately put the two

400

00:21:14,500 --> 00:21:11,240

points closer together you get lost what

401  
00:21:16,330 --> 00:21:14,510  
les cycling then this is the clamping

402  
00:21:20,380 --> 00:21:16,340  
load remaining when you go all the way

403  
00:21:22,299 --> 00:21:20,390  
up to yield now this represents the

404  
00:21:25,240 --> 00:21:22,309  
stiffness of the bolt and this

405  
00:21:28,570 --> 00:21:25,250  
represents the stiffness of the joint so

406  
00:21:30,940 --> 00:21:28,580  
if you get a better ratio between the

407  
00:21:33,960 --> 00:21:30,950  
two and lean those lines over a little

408  
00:21:36,940 --> 00:21:33,970  
bit you get less cyclic loading on the

409  
00:21:39,070 --> 00:21:36,950  
bolt when you apply an external load now

410  
00:21:40,750 --> 00:21:39,080  
if you go over here we're torque above

411  
00:21:43,750 --> 00:21:40,760  
yield because here's a yield point

412  
00:21:46,120 --> 00:21:43,760  
there's above yield then on this one we

413  
00:21:48,340 --> 00:21:46,130

really applied two loads that took it

414

00:21:53,440 --> 00:21:48,350

way above yield and failed it it

415

00:22:03,399 --> 00:21:53,450

separated so now if you look at the ten

416

00:22:05,740 --> 00:22:03,409

point nine there I put the the initial

417

00:22:08,440 --> 00:22:05,750

preload and yield are fairly close

418

00:22:11,919 --> 00:22:08,450

together so you see the cyclic loading

419

00:22:14,919 --> 00:22:11,929

is just the between here so therefore

420

00:22:19,060 --> 00:22:14,929

you get less cyclic loading with the

421

00:22:21,610 --> 00:22:19,070

higher torque on the fasteners now this

422

00:22:25,740 --> 00:22:21,620

figure was over torqued

423

00:22:28,360 --> 00:22:25,750

if you notice it's kind of Wiggly here

424

00:22:30,789 --> 00:22:28,370

that's the over Turk trying to scan it

425

00:22:37,049 --> 00:22:30,799

into the scanner and it wouldn't scan in

426

00:22:47,020 --> 00:22:41,430

okay moving on now to fastener torque

427

00:22:48,700 --> 00:22:47,030

which is 11:1 now determination of

428

00:22:51,549 --> 00:22:48,710

torque values is one of the most

429

00:22:55,180 --> 00:22:51,559

difficult and controversial aspects of

430

00:22:58,180 --> 00:22:55,190

fastener design and if you tuck to

431

00:23:00,610 --> 00:22:58,190

Murphy he says if tight is good a little

432

00:23:02,230 --> 00:23:00,620

tighter is better but it doesn't always

433

00:23:08,919 --> 00:23:02,240

work out that way Murphy's a guy that

434

00:23:12,580 --> 00:23:08,929

runs the wrenches but the variables

435

00:23:14,440 --> 00:23:12,590

involved the joint material strength the

436

00:23:17,350 --> 00:23:14,450

coefficient of friction between mating

437

00:23:19,840 --> 00:23:17,360

surfaces the effect of friction between

438

00:23:23,440 --> 00:23:19,850

the bolt head and nut or its mating

439

00:23:25,720 --> 00:23:23,450

surface and the effect of coatings and

440

00:23:27,669 --> 00:23:25,730

lubricants on the friction coefficients

441

00:23:30,100 --> 00:23:27,679

themselves because the amount of

442

00:23:36,370 --> 00:23:30,110

lubricant you put on changes it all

443

00:23:38,230 --> 00:23:36,380

together now the percentage of bolt

444

00:23:41,310 --> 00:23:38,240

tensile strength that you want for

445

00:23:45,430 --> 00:23:41,320

preload that is something that is

446

00:23:48,970 --> 00:23:45,440

difficult one of our guys just to show

447

00:23:52,560 --> 00:23:48,980

you how how things can vary one of our

448

00:23:56,560 --> 00:23:52,570

guys had some a stainless steel bolt nut

449

00:23:58,810 --> 00:23:56,570

assembly that had been locks cleaned now

450

00:24:01,360 --> 00:23:58,820

locks cleaned is like ultrasonically

451  
00:24:05,680 --> 00:24:01,370  
cleaning your jewelry or something like

452  
00:24:07,930 --> 00:24:05,690  
that it is clean clean and he was

453  
00:24:11,110 --> 00:24:07,940  
required to have it that clean so he

454  
00:24:13,270 --> 00:24:11,120  
went to assemble it he had used up his

455  
00:24:18,039 --> 00:24:13,280  
allowable torque before you got it

456  
00:24:20,799 --> 00:24:18,049  
seated because dry dry clean stainless

457  
00:24:23,020 --> 00:24:20,809  
on dry clean stainless has a real high

458  
00:24:24,850 --> 00:24:23,030  
coefficient of friction so this just

459  
00:24:28,840 --> 00:24:24,860  
shows you what you can do going to an

460  
00:24:31,120 --> 00:24:28,850  
extreme now the other thing is what is

461  
00:24:34,570 --> 00:24:31,130  
the distribution of total torque to

462  
00:24:36,610 --> 00:24:34,580  
tension shear and friction you know when

463  
00:24:40,029 --> 00:24:36,620

you twerk up a fastener that you have a

464

00:24:41,890 --> 00:24:40,039

certain torque value applied but you

465

00:24:43,779 --> 00:24:41,900

don't know how much of it went into

466

00:24:48,039 --> 00:24:43,789

tension how much of it went into shear

467

00:24:50,169 --> 00:24:48,049

and and how much of it has lost the

468

00:24:52,690 --> 00:24:50,179

friction but it all has to be accounted

469

00:24:56,200 --> 00:24:52,700

or then the other thing is the relative

470

00:24:58,840 --> 00:24:56,210

spring rates the bolts and nuts and the

471

00:25:00,609 --> 00:24:58,850

joints themselves and then accounting

472

00:25:03,430 --> 00:25:00,619

for the running torque of the locking

473

00:25:06,159 --> 00:25:03,440

devices all those different methods of

474

00:25:09,129 --> 00:25:06,169

locking themselves have at what is

475

00:25:12,999 --> 00:25:09,139

called a running torque that has to be

476

00:25:14,859 --> 00:25:13,009

accounted for now head friction if the

477

00:25:16,539 --> 00:25:14,869

fastener is tightened from the head the

478

00:25:20,499 --> 00:25:16,549

bearing surface for the bottom of the

479

00:25:23,200 --> 00:25:20,509

head becomes a big part of the friction

480

00:25:25,930 --> 00:25:23,210

load that's why that having a smooth

481

00:25:29,639 --> 00:25:25,940

washer hardened washer under the head is

482

00:25:32,619 --> 00:25:29,649

a good idea even if you don't

483

00:25:35,200 --> 00:25:32,629

necessarily have to have it it's good

484

00:25:36,970 --> 00:25:35,210

because it gives you a hardened surface

485

00:25:39,539 --> 00:25:36,980

that will have a lower coefficient of

486

00:25:43,690 --> 00:25:39,549

friction than the joint material itself

487

00:25:46,359 --> 00:25:43,700

plus the washer will deter or prevent

488

00:25:48,669 --> 00:25:46,369

embedment of the head where the joint

489

00:25:49,980 --> 00:25:48,679

material is softer than the boat which

490

00:25:53,320 --> 00:25:49,990

is usually the case

491

00:25:56,560 --> 00:25:53,330

now if head friction locking is desired

492

00:25:59,350 --> 00:25:56,570

then you can maximize that head friction

493

00:26:02,379 --> 00:25:59,360

use remember earlier I covered the

494

00:26:04,869 --> 00:26:02,389

serrated head with that you could use

495

00:26:07,720 --> 00:26:04,879

without a washer or don't use any

496

00:26:10,539 --> 00:26:07,730

lubricant on the thing and then then of

497

00:26:13,299 --> 00:26:10,549

course you will use up more of your

498

00:26:14,980 --> 00:26:13,309

torque on friction and have less in it

499

00:26:22,330 --> 00:26:14,990

and axial load which you have to account

500

00:26:27,789 --> 00:26:22,340

for nut friction pretty much the same

501  
00:26:30,789 --> 00:26:27,799  
thing you can you can go either way you

502  
00:26:33,639 --> 00:26:30,799  
can maximize it or minimize it by using

503  
00:26:35,769 --> 00:26:33,649  
lubricants and stuff like that and the

504  
00:26:37,659 --> 00:26:35,779  
nut usually contains a locking device

505  
00:26:39,879 --> 00:26:37,669  
it's easier to install a locking device

506  
00:26:43,539 --> 00:26:39,889  
on a nut normally than it is on the

507  
00:26:47,109 --> 00:26:43,549  
bolts so most of the nuts carry the

508  
00:26:49,239 --> 00:26:47,119  
locking device so the running torque the

509  
00:26:51,519 --> 00:26:49,249  
locking device and I'll go through

510  
00:26:54,310 --> 00:26:51,529  
definitions on it but the running torque

511  
00:26:57,609 --> 00:26:54,320  
is the amount that it takes just to seek

512  
00:27:02,010 --> 00:26:57,619  
the thing down to the surface and it's

513  
00:27:08,340 --> 00:27:02,020

usually a small fraction of the total

514

00:27:13,770 --> 00:27:08,350

now the k-factor people say T equals

515

00:27:17,340 --> 00:27:13,780

2/10 F D and that 2/10 is used

516

00:27:20,610 --> 00:27:17,350

religiously well at 2/10 is this budge

517

00:27:24,240 --> 00:27:20,620

factor which has this formula right here

518

00:27:27,090 --> 00:27:24,250

and for those of you who have a copy my

519

00:27:29,430 --> 00:27:27,100

fastener manual I'd I had the right

520

00:27:33,360 --> 00:27:29,440

calculations in the manual but I had the

521

00:27:35,430 --> 00:27:33,370

wrong terminology I had a Greek sigh for

522

00:27:37,350 --> 00:27:35,440

this this angle here it should have been

523

00:27:39,240 --> 00:27:37,360

lambda according to the formula and I

524

00:27:42,510 --> 00:27:39,250

the calculations were done right the

525

00:27:44,730 --> 00:27:42,520

terminology was wrong in it but anyway

526

00:27:51,330 --> 00:27:44,740

this is this is the formula that you use

527

00:27:53,460 --> 00:27:51,340

for calculating that K factor now the D

528

00:27:55,890 --> 00:27:53,470

sub M is the mean thread diameter which

529

00:28:00,480 --> 00:27:55,900

you use pitch diameter for lambda is the

530

00:28:05,419 --> 00:28:00,490

thread lead angle and mu here is the

531

00:28:12,510 --> 00:28:09,500

alpha is the thread angle in this case

532

00:28:15,720 --> 00:28:12,520

since you have a 60 degree angle it's

533

00:28:17,190 --> 00:28:15,730

half of that which is 30 and u sub c is

534

00:28:19,740 --> 00:28:17,200

the friction coefficient between the

535

00:28:21,780 --> 00:28:19,750

bolt head or nut and the clamping

536

00:28:24,180 --> 00:28:21,790

surface so if you throw all those

537

00:28:26,370 --> 00:28:24,190

together and you're able to determine

538

00:28:28,470 --> 00:28:26,380

them well enough that you feel that you

539

00:28:30,630 --> 00:28:28,480

have some confidence in them then you

540

00:28:36,180 --> 00:28:30,640

run a calculation and get an actual

541

00:28:42,150 --> 00:28:36,190

value for that k factor now I did some

542

00:28:44,450 --> 00:28:42,160

calculations using these coefficients of

543

00:28:46,950 --> 00:28:44,460

friction and in this case I used

544

00:28:50,900 --> 00:28:46,960

identical ones although you could have

545

00:28:54,450 --> 00:28:50,910

different ones that doesn't for the

546

00:28:57,540 --> 00:28:54,460

between threads and between the bolt or

547

00:29:00,960 --> 00:28:57,550

or nut and look at the variation that

548

00:29:04,740 --> 00:29:00,970

you can get with the variation in

549

00:29:07,710 --> 00:29:04,750

friction coefficient you see the the K

550

00:29:12,450 --> 00:29:07,720

factor the point two that we use is

551  
00:29:15,090 --> 00:29:12,460  
actually a little bit high because it

552  
00:29:20,940 --> 00:29:15,100  
would be somewhere in here would be

553  
00:29:25,580 --> 00:29:20,950  
a more realistic value however one of

554  
00:29:29,490 --> 00:29:25,590  
the objections to using zinc plating is

555  
00:29:33,149 --> 00:29:29,500  
that the friction coefficient with zinc

556  
00:29:37,200 --> 00:29:33,159  
can vary enough that that value can go

557  
00:29:43,320 --> 00:29:37,210  
anywhere from point forward up to almost

558  
00:29:45,149 --> 00:29:43,330  
1 so now when you do this then most of

559  
00:29:47,759 --> 00:29:45,159  
the torque that you're applying is going

560  
00:29:52,789 --> 00:29:47,769  
into overcoming friction and your axial

561  
00:29:59,700 --> 00:29:55,830  
here are some torque definitions and

562  
00:30:04,590 --> 00:29:59,710  
these are courtesy of sae AS 1310 and

563  
00:30:08,399 --> 00:30:04,600

marshall standard 486 and some of them

564

00:30:11,610 --> 00:30:08,409

have been cleaned up slightly to make

565

00:30:14,639 --> 00:30:11,620

them a little more readable because

566

00:30:17,909 --> 00:30:14,649

they've gotten kind of out of hand

567

00:30:21,690 --> 00:30:17,919

so just for torque itself it's of course

568

00:30:24,090 --> 00:30:21,700

it's a force times a distance and you

569

00:30:25,590 --> 00:30:24,100

have a moment arm which is the length of

570

00:30:27,149 --> 00:30:25,600

your torque wrench and then of course

571

00:30:30,029 --> 00:30:27,159

that you put on it and if you have a

572

00:30:31,440 --> 00:30:30,039

torque wrench it'll it'll vary or we'll

573

00:30:33,299 --> 00:30:31,450

register the amount of torque that

574

00:30:34,919 --> 00:30:33,309

you're putting on or if you have the one

575

00:30:37,259 --> 00:30:34,929

of the old do-it-yourselfers it has a

576

00:30:39,659 --> 00:30:37,269

needle on it and you measure it by

577

00:30:41,999 --> 00:30:39,669

deflecting the rod and that one is a

578

00:30:43,769 --> 00:30:42,009

plus or minus 40 percent depending on

579

00:30:45,330 --> 00:30:43,779

whether you can hold it in place long

580

00:30:48,930 --> 00:30:45,340

enough to read it while you're doing the

581

00:30:50,340 --> 00:30:48,940

turkey the applied torque is the torque

582

00:30:52,619 --> 00:30:50,350

transmitted to the fastener of the

583

00:30:54,629 --> 00:30:52,629

installation tool and then you the

584

00:30:56,070 --> 00:30:54,639

running or prevailing torque is the

585

00:31:05,909 --> 00:30:56,080

amount to overcome the locking device

586

00:31:11,159 --> 00:31:08,649

and here are some other definitions the

587

00:31:14,169 --> 00:31:11,169

double torque or retorque

588

00:31:17,289 --> 00:31:14,179

to seek materials being joined where you

589

00:31:21,779 --> 00:31:17,299

had interferences or sheet gaps or form

590

00:31:25,840 --> 00:31:21,789

in place gaskets and stuff like that and

591

00:31:27,729 --> 00:31:25,850

also where you turn around one time in a

592

00:31:30,759 --> 00:31:27,739

circle of bolts and then you need to go

593

00:31:32,710 --> 00:31:30,769

back and check them the the no load

594

00:31:34,749 --> 00:31:32,720

torque is the torque required to

595

00:31:36,820 --> 00:31:34,759

overcome kinetic friction between mating

596

00:31:39,159 --> 00:31:36,830

threads without a locking device and

597

00:31:40,960 --> 00:31:39,169

that is usually unless you have threads

598

00:31:45,129 --> 00:31:40,970

that are damaged or something that is

599

00:31:48,669 --> 00:31:45,139

usually next to nothing then the

600

00:31:50,830 --> 00:31:48,679

installation torque design torque

601  
00:31:56,560 --> 00:31:50,840  
applied the tightening direction and

602  
00:32:01,210 --> 00:31:56,570  
includes kinetic static friction self

603  
00:32:03,340 --> 00:32:01,220  
locking features and required to apply a

604  
00:32:06,009 --> 00:32:03,350  
desired axial load to the fastener

605  
00:32:08,619 --> 00:32:06,019  
assembly so its measured in the

606  
00:32:10,810 --> 00:32:08,629  
tightening direction only and of course

607  
00:32:14,109 --> 00:32:10,820  
the the thing that is usually in

608  
00:32:17,289 --> 00:32:14,119  
determinants are not indeterminate but

609  
00:32:20,590 --> 00:32:17,299  
hard to determine is how much actually a

610  
00:32:24,399 --> 00:32:20,600  
load do you really get for a given

611  
00:32:26,200 --> 00:32:24,409  
torque and here's limiting torque and so

612  
00:32:28,599 --> 00:32:26,210  
on which you can read through these

613  
00:32:30,779 --> 00:32:28,609

multiple torque required to see parts

614

00:32:36,789 --> 00:32:30,789

where you have heavy interferences and

615

00:32:39,099 --> 00:32:36,799

assembly and one of these has to do with

616

00:32:41,080 --> 00:32:39,109

where if you're torquing fasteners on a

617

00:32:42,789 --> 00:32:41,090

flange or if you're torquing the lug

618

00:32:45,869 --> 00:32:42,799

bolts on your car or something you know

619

00:32:49,739 --> 00:32:45,879

you always talk 180 degrees apart and

620

00:32:53,320 --> 00:32:49,749

after you get them snug down so that you

621

00:32:55,060 --> 00:32:53,330

get the effect of the adjacent fastener

622

00:32:56,320 --> 00:32:55,070

to the one that you're talking down to

623

00:32:59,409 --> 00:32:56,330

make sure you're going to tighten down

624

00:33:01,989 --> 00:32:59,419

because if you if you tighten tighten

625

00:33:03,970 --> 00:33:01,999

them down and then tighten one down the

626

00:33:07,269 --> 00:33:03,980

one next to it will have a slight amount

627

00:33:10,840 --> 00:33:07,279

of loosening due to the give of the

628

00:33:13,119 --> 00:33:10,850

flange itself so you have to go back and

629

00:33:16,239 --> 00:33:13,129

recheck them back to guy by the name of

630

00:33:18,460 --> 00:33:16,249

George Bible formerly of the University

631

00:33:22,060 --> 00:33:18,470

of Akron came up with a

632

00:33:25,510 --> 00:33:22,070

pewter eyes program on dealing with

633

00:33:27,880 --> 00:33:25,520

large flanges and we're talking near

634

00:33:32,860 --> 00:33:27,890

six-foot flanges or something like that

635

00:33:35,620 --> 00:33:32,870

on the iterative process for doing the

636

00:33:38,049 --> 00:33:35,630

Turks on them to get them all Turk down

637

00:33:40,419 --> 00:33:38,059

within satisfactory limits and gave a

638

00:33:43,120 --> 00:33:40,429

presentation one time at the voting

639

00:33:46,510 --> 00:33:43,130

Technology Council now here's the

640

00:33:49,270 --> 00:33:46,520

seating torque and that's just to bring

641

00:33:51,360 --> 00:33:49,280

the bearing faces into a seated position

642

00:33:54,340 --> 00:33:51,370

and then the the break loose torque

643

00:33:55,899 --> 00:33:54,350

torque required to loosen the fastener

644

00:33:57,909 --> 00:33:55,909

from its installed position there's

645

00:34:01,510 --> 00:33:57,919

various other definitions that get too

646

00:34:03,580 --> 00:34:01,520

confusing and Harold Casper and I went

647

00:34:06,669 --> 00:34:03,590

through them and eliminated some of them

648

00:34:08,379 --> 00:34:06,679

that created too much confusion now

649

00:34:13,000 --> 00:34:08,389

here's the big question what part

650

00:34:16,780 --> 00:34:13,010

tension and that's the most

651  
00:34:18,760 --> 00:34:16,790  
unpredictable one and the clamp load in

652  
00:34:21,550 --> 00:34:18,770  
general only represents something like

653  
00:34:23,099 --> 00:34:21,560  
10 to 25% of the applied torque because

654  
00:34:26,379 --> 00:34:23,109  
the rest of it is used to overcome

655  
00:34:30,550 --> 00:34:26,389  
friction and various other things in the

656  
00:34:33,720 --> 00:34:30,560  
joint so but the thing that you've got

657  
00:34:36,490 --> 00:34:33,730  
to look at is just because you put a

658  
00:34:38,290 --> 00:34:36,500  
certain amount of torque into a fastener

659  
00:34:41,169 --> 00:34:38,300  
and it doesn't have a lot of axial load

660  
00:34:45,030 --> 00:34:41,179  
on it doesn't mean that that torque went

661  
00:34:47,290 --> 00:34:45,040  
away it's still in there and shir

662  
00:34:49,629 --> 00:34:47,300  
somewhere it has to be accounted for so

663  
00:34:51,970 --> 00:34:49,639

that's why you got to be careful on over

664

00:34:55,210 --> 00:34:51,980

torquing stuff and you got to combine

665

00:34:58,359 --> 00:34:55,220

stresses and check them all against the

666

00:35:02,109 --> 00:34:58,369

total strength of the fastener so and of

667

00:35:05,710 --> 00:35:02,119

course this is the thing here that the

668

00:35:07,359 --> 00:35:05,720

von Mises stresses can be calculated and

669

00:35:14,500 --> 00:35:07,369

compared to yield and ultimate strength

670

00:35:18,010 --> 00:35:14,510

of the material so or for those of you

671

00:35:20,680 --> 00:35:18,020

who feel academically inclined you could

672

00:35:22,720 --> 00:35:20,690

use a Mohr circle and take share in

673

00:35:25,120 --> 00:35:22,730

tension and plot them out and get all

674

00:35:29,650 --> 00:35:25,130

that sort of thing but stress ratios

675

00:35:32,390 --> 00:35:29,660

work better so and their artwork values

676

00:35:34,760 --> 00:35:32,400

and these are tongue-in-cheek not

677

00:35:36,799 --> 00:35:34,770

one's for both inch and metric fasteners

678

00:35:43,220 --> 00:35:36,809

in the appendices which you would get

679

00:35:44,930 --> 00:35:43,230

layer clerk accuracies it's only as good

680

00:35:48,079 --> 00:35:44,940

as the type of measuring device in the

681

00:35:50,210 --> 00:35:48,089

operator and of all these methods the

682

00:35:53,000 --> 00:35:50,220

worst one of all is the impact wrench

683

00:35:57,799 --> 00:35:53,010

Joe Greenslade who is a writer

684

00:35:59,720 --> 00:35:57,809

in the fastener world put out an article

685

00:36:03,170 --> 00:35:59,730

here sometime back then I got a chuckle

686

00:36:03,769 --> 00:36:03,180

out of he believe it was titled impact

687

00:36:09,620 --> 00:36:03,779

wrench

688

00:36:11,870 --> 00:36:09,630

the engineers worst enemy because the

689

00:36:15,650 --> 00:36:11,880

impact wrenches that these garages use

690

00:36:18,079 --> 00:36:15,660

are never calibrated probably and they

691

00:36:20,420 --> 00:36:18,089

put them on real good and tight and then

692

00:36:22,849 --> 00:36:20,430

you need a truck breaker bar to get your

693

00:36:26,210 --> 00:36:22,859

lug nuts loose on your car when you go

694

00:36:31,609 --> 00:36:26,220

to take it off so so that's the worst

695

00:36:34,160 --> 00:36:31,619

one and if a perk wrench is used to

696

00:36:37,640 --> 00:36:34,170

apply torque the applied torque should

697

00:36:40,390 --> 00:36:37,650

be at least 70% a full scale of the

698

00:36:43,700 --> 00:36:40,400

wrench in other words don't use a

699

00:36:45,380 --> 00:36:43,710

hundred and seventy five foot pound

700

00:36:48,079 --> 00:36:45,390

torque wrench with a number eight

701  
00:36:49,400 --> 00:36:48,089  
fastener because there's no accuracy

702  
00:36:51,260 --> 00:36:49,410  
there just like it is with any other

703  
00:36:55,730 --> 00:36:51,270  
reading if you're doing instrumentation

704  
00:36:59,930 --> 00:36:55,740  
you try to get say 70% of full scale in

705  
00:37:01,910 --> 00:36:59,940  
the range of your actual measurements

706  
00:37:06,710 --> 00:37:01,920  
that you're making because you don't

707  
00:37:08,420 --> 00:37:06,720  
since the tolerances are a percentage

708  
00:37:10,339 --> 00:37:08,430  
you won't you do not want to be

709  
00:37:12,470 --> 00:37:10,349  
measuring in the bottom 10% of your

710  
00:37:16,370 --> 00:37:12,480  
scale when you're making readings on

711  
00:37:21,099 --> 00:37:16,380  
anything now

712  
00:37:24,019 --> 00:37:21,109  
here is a table with approximate values

713  
00:37:29,210 --> 00:37:24,029

for Terk measuring methods versus the

714

00:37:33,500 --> 00:37:29,220

accuracy and cost now you see the feel

715

00:37:36,079 --> 00:37:33,510

there in which the guy just says well

716

00:37:39,250 --> 00:37:36,089

I've been doing this for years so this

717

00:37:43,339 --> 00:37:39,260

is about what this should have on it

718

00:37:45,260 --> 00:37:43,349

cheap way of doing it and a lot of it if

719

00:37:46,309 --> 00:37:45,270

you've been I've been feeling those

720

00:37:50,660 --> 00:37:46,319

joints for years like

721

00:37:53,269 --> 00:37:50,670

that a lot of times it will suffice I

722

00:37:55,969 --> 00:37:53,279

don't use a perk branch on my car unless

723

00:37:57,620 --> 00:37:55,979

there's a specified value called for

724

00:37:58,729 --> 00:37:57,630

like a tie rod end or something like

725

00:38:00,589 --> 00:37:58,739

that where you have to go to a high

726

00:38:03,410 --> 00:38:00,599

torque value then I get out the turqu

727

00:38:06,890 --> 00:38:03,420

wrench otherwise I don't an impact

728

00:38:09,319 --> 00:38:06,900

wrench and it's it's been probably even

729

00:38:12,890 --> 00:38:09,329

worse than that but that's the value

730

00:38:14,509 --> 00:38:12,900

that some of us had agreed to before the

731

00:38:15,939 --> 00:38:14,519

torque wrench that actually gives you a

732

00:38:19,819 --> 00:38:15,949

reading

733

00:38:22,029 --> 00:38:19,829

about plus or minus 25 turn of the nut

734

00:38:27,979 --> 00:38:22,039

now that's a method which I will cover

735

00:38:29,749 --> 00:38:27,989

later which is fairly accurate as long

736

00:38:31,130 --> 00:38:29,759

as you want to use it but you probably

737

00:38:34,069 --> 00:38:31,140

wouldn't want to use it because you go

738

00:38:37,099 --> 00:38:34,079

above yield on the passenger then these

739

00:38:39,829 --> 00:38:37,109

load indicating washers they give pretty

740

00:38:43,029 --> 00:38:39,839

good accuracy but of course the amount

741

00:38:46,039 --> 00:38:43,039

of labor involved runs the cost up

742

00:38:47,839 --> 00:38:46,049

remember I covered those the the one

743

00:38:49,430 --> 00:38:47,849

that had the little bumps on it and the

744

00:38:52,910 --> 00:38:49,440

other one that had the little internal

745

00:38:56,660 --> 00:38:52,920

bushing that you compressed fastener

746

00:39:00,229 --> 00:38:56,670

elongation now that could be used if you

747

00:39:02,930 --> 00:39:00,239

are say bolting a flange and you have a

748

00:39:05,390 --> 00:39:02,940

guy there with a scale an accurate scale

749

00:39:08,420 --> 00:39:05,400

he can actually measure fastener

750

00:39:11,089 --> 00:39:08,430

elongation velocity subtracts out the

751

00:39:14,299 --> 00:39:11,099

dead part that didn't expand on it and

752

00:39:17,539 --> 00:39:14,309

get some idea as to where he's at on it

753

00:39:21,680 --> 00:39:17,549

but then you can go to string gauges now

754

00:39:26,809 --> 00:39:21,690

strain gauges are real accurate but the

755

00:39:28,729 --> 00:39:26,819

only thing is how do you do it how do

756

00:39:30,650 --> 00:39:28,739

you put strain gauges on a bolt etre

757

00:39:34,789 --> 00:39:30,660

installing down in the hole it's kind of

758

00:39:37,400 --> 00:39:34,799

hard to do so so what what you normally

759

00:39:39,559 --> 00:39:37,410

do with the strain gauge is is if you're

760

00:39:42,170 --> 00:39:39,569

really interested in finding exactly

761

00:39:43,819 --> 00:39:42,180

what you want you put them on one of the

762

00:39:46,189 --> 00:39:43,829

bolts and test it under the same

763

00:39:48,489 --> 00:39:46,199

conditions as nearly as you can to

764

00:39:51,259 --> 00:39:48,499

duplicate the actual installation and

765

00:39:54,559 --> 00:39:51,269

get a quick reading from that and then

766

00:39:56,989 --> 00:39:54,569

use that torque reading on the bolt

767

00:39:59,690 --> 00:39:56,999

you're gonna install then of course the

768

00:40:02,000 --> 00:39:59,700

other thing was these direct

769

00:40:06,020 --> 00:40:02,010

and indicating bolts which is kind of a

770

00:40:12,380 --> 00:40:06,030

strain gauge type setup so I will cover

771

00:40:17,030 --> 00:40:12,390

some of those in further texture now

772

00:40:21,470 --> 00:40:17,040

perks draping that is used a lot by the

773

00:40:23,780 --> 00:40:21,480

aerospace companies for after you have

774

00:40:27,470 --> 00:40:23,790

decided the final torque value on a

775

00:40:29,359 --> 00:40:27,480

fastener you actually just take a marker

776

00:40:33,710 --> 00:40:29,369

of some kind they used to use a paint

777

00:40:38,960 --> 00:40:33,720

now we use a blue sharpie pen to mark

778

00:40:42,440 --> 00:40:38,970

across the head or the nut straight

779

00:40:46,550 --> 00:40:42,450

across onto the surrounding surface now

780

00:40:49,640 --> 00:40:46,560

this is a visual indication if the thing

781

00:40:51,260 --> 00:40:49,650

switches position on you because it will

782

00:40:57,170 --> 00:40:51,270

show up because the two marks don't line

783

00:40:59,060 --> 00:40:57,180

up anymore and that is a very common

784

00:41:01,430 --> 00:40:59,070

thing in the aerospace world that way

785

00:41:03,290 --> 00:41:01,440

you can look in later and see whether

786

00:41:07,250 --> 00:41:03,300

anything has changed on your

787

00:41:10,690 --> 00:41:07,260

installation now joint relaxation that's

788

00:41:13,670 --> 00:41:10,700

not what you're going to after today

789

00:41:16,579 --> 00:41:13,680

it's defined it's the unloading of a

790

00:41:19,400 --> 00:41:16,589

fastener after its final torque due to a

791

00:41:21,770 --> 00:41:19,410

number of contributing factors and here

792

00:41:24,559 --> 00:41:21,780

are some of the major factors embedment

793

00:41:27,589 --> 00:41:24,569

of the washer the head or the nut in the

794

00:41:29,540 --> 00:41:27,599

joint material yielding of a high spot

795

00:41:32,710 --> 00:41:29,550

or blemish on the head nut or washer

796

00:41:35,599 --> 00:41:32,720

joint surface after final tightening and

797

00:41:37,670 --> 00:41:35,609

untwisting of a fastener from initial

798

00:41:39,380 --> 00:41:37,680

torsion where the shank had an

799

00:41:41,329 --> 00:41:39,390

interference bit in the hole so you

800

00:41:45,200 --> 00:41:41,339

cranked it down but a lot of that went

801  
00:41:51,349 --> 00:41:45,210  
in to putting some torsional twist into

802  
00:41:53,809 --> 00:41:51,359  
the fastener and so after the thing

803  
00:41:56,839 --> 00:41:53,819  
settles down it kind of makes its way

804  
00:41:59,329 --> 00:41:56,849  
back creeps back to a equilibrium

805  
00:42:01,670 --> 00:41:59,339  
position and in doing so that will

806  
00:42:03,829 --> 00:42:01,680  
lessen the load on the fastener itself

807  
00:42:11,660 --> 00:42:03,839  
and then creep of the joint material

808  
00:42:18,990 --> 00:42:14,220  
then here's the other thing I mentioned

809  
00:42:21,030 --> 00:42:19,000  
on the like the lug nuts on your car a

810  
00:42:22,859 --> 00:42:21,040  
failure of the Installer to wreak torque

811  
00:42:24,960 --> 00:42:22,869  
a pattern of fasteners after initial

812  
00:42:26,579 --> 00:42:24,970  
installation to come compensate for

813  
00:42:28,950 --> 00:42:26,589

effects of adjacent fasteners to each

814

00:42:31,049 --> 00:42:28,960

other because when you compress the

815

00:42:34,049 --> 00:42:31,059

surface next to the the fastener you

816

00:42:35,520 --> 00:42:34,059

talked before then it changes the load

817

00:42:39,750 --> 00:42:35,530

on that fastener you got to go back to

818

00:42:41,309 --> 00:42:39,760

return also here's here's one here's why

819

00:42:45,030 --> 00:42:41,319

I don't like to go up to the yield point

820

00:42:47,130 --> 00:42:45,040

on fasteners inadvertently exceeding the

821

00:42:48,809 --> 00:42:47,140

yield point of the fastener during the

822

00:42:51,000 --> 00:42:48,819

initial turkeying process now there

823

00:42:53,579 --> 00:42:51,010

you're in real trouble in fact that's

824

00:42:56,460 --> 00:42:53,589

what they did on that first time around

825

00:42:57,900 --> 00:42:56,470

on that Center volt problems talked

826

00:42:59,309 --> 00:42:57,910

about with the cryogenic temperatures

827

00:43:01,559 --> 00:42:59,319

they say well we just increase the

828

00:43:03,150 --> 00:43:01,569

torque so they increased the torque and

829

00:43:04,950 --> 00:43:03,160

they were yielding some of the fasteners

830

00:43:06,990 --> 00:43:04,960

when they checked them again they were

831

00:43:09,000 --> 00:43:07,000

down to something like 40% of the

832

00:43:12,089 --> 00:43:09,010

initial load so they had to go to higher

833

00:43:13,890 --> 00:43:12,099

strength fasteners then the other thing

834

00:43:15,690 --> 00:43:13,900

is critical joints should be inspected

835

00:43:17,430 --> 00:43:15,700

for relaxation a few hours after

836

00:43:19,079 --> 00:43:17,440

installation you go through and check

837

00:43:23,069 --> 00:43:19,089

them with the same torque and see if any

838

00:43:26,130 --> 00:43:23,079

of them have loosened up any now here's

839

00:43:28,760 --> 00:43:26,140

the turn of the nut process and this is

840

00:43:31,500 --> 00:43:28,770

used in the construction business

841

00:43:35,460 --> 00:43:31,510

because it's something that visually you

842

00:43:38,880 --> 00:43:35,470

can do particularly with a big boat you

843

00:43:41,130 --> 00:43:38,890

tighten the nut above yields so what you

844

00:43:45,329 --> 00:43:41,140

do is you taken it to what you think is

845

00:43:46,620 --> 00:43:45,339

about 75% of ultimate load then put a

846

00:43:50,190 --> 00:43:46,630

mark on it

847

00:43:53,670 --> 00:43:50,200

then turn the nut an additional 180

848

00:43:56,250 --> 00:43:53,680

degrees this brings a bolt stress up

849

00:43:58,859 --> 00:43:56,260

above yield but below ultimate providing

850

00:44:03,510 --> 00:43:58,869

the material is ductile so that yield an

851  
00:44:06,359 --> 00:44:03,520  
ultimate are far enough apart now that

852  
00:44:08,270 --> 00:44:06,369  
is not used in the aerospace world

853  
00:44:11,789 --> 00:44:08,280  
because you don't risk stuff like that

854  
00:44:15,599 --> 00:44:11,799  
aerospace torque values usually are 50

855  
00:44:18,539 --> 00:44:15,609  
to 75 percent of yield depending on the

856  
00:44:22,520 --> 00:44:18,549  
application as to whether you have much

857  
00:44:25,079 --> 00:44:22,530  
tension on the joint or none and so on

858  
00:44:25,710 --> 00:44:25,089  
so that because you still have to check

859  
00:44:28,859 --> 00:44:25,720  
for both

860  
00:44:32,630 --> 00:44:28,869  
shiron axial load now tightening the

861  
00:44:35,070 --> 00:44:32,640  
fastener beyond its yield is risky

862  
00:44:39,000 --> 00:44:35,080  
because it's so difficult to determine

863  
00:44:43,470 --> 00:44:39,010

where yield is this is why that if you

864

00:44:45,780 --> 00:44:43,480

go look at the definition of yield for a

865

00:44:48,180 --> 00:44:45,790

material in a something like mil

866

00:44:51,530 --> 00:44:48,190

handbook 5 you'll find that it's based

867

00:44:55,500 --> 00:44:51,540

on two-tenths of a percent permanent set

868

00:44:57,140 --> 00:44:55,510

because you don't know the track yield

869

00:44:59,640 --> 00:44:57,150

unless you have the thing on a machine

870

00:45:03,030 --> 00:44:59,650

until after you've exceeded it because

871

00:45:07,080 --> 00:45:03,040

you're still going up on your elasticity

872

00:45:09,089 --> 00:45:07,090

curve and until you pick out from the

873

00:45:13,470 --> 00:45:09,099

straight line you don't know you're

874

00:45:16,140 --> 00:45:13,480

above yield so as I mentioned earlier

875

00:45:18,599 --> 00:45:16,150

the the usual reason for going up close

876

00:45:22,710 --> 00:45:18,609

to the yield is to minimize the fatigue

877

00:45:24,570 --> 00:45:22,720

effects on fasteners but unless you have

878

00:45:26,580 --> 00:45:24,580

done an awful lot of testing it's not a

879

00:45:36,050 --> 00:45:26,590

good idea to go up to the yield point on

880

00:45:39,890 --> 00:45:36,060

a faster now on joint stiffness we have

881

00:45:42,300 --> 00:45:39,900

alluded to it many times up to now and

882

00:45:44,579 --> 00:45:42,310

and we covered the joint loading

883

00:45:46,320 --> 00:45:44,589

diagrams and now we look just look at

884

00:45:51,300 --> 00:45:46,330

the joint itself as we tighten the

885

00:45:54,510 --> 00:45:51,310

fasteners John Bickford actually has

886

00:45:55,980 --> 00:45:54,520

used a spring type analogy on this which

887

00:45:58,200 --> 00:45:55,990

makes it easier to understand because

888

00:45:59,730 --> 00:45:58,210

you take a piece here that has three

889

00:46:01,530 --> 00:45:59,740

different cross sections it's three

890

00:46:04,290 --> 00:46:01,540

different Springs with the three

891

00:46:07,650 --> 00:46:04,300

different spring constants and so you

892

00:46:18,710 --> 00:46:07,660

can think of a joint or a fastener that

893

00:46:26,900 --> 00:46:18,720

way and here is another one with the

894

00:46:37,219 --> 00:46:31,410

next page I thought I thought we'd had a

895

00:46:40,349 --> 00:46:37,229

stop a glitch during things okay alright

896

00:46:41,849 --> 00:46:40,359

well so the alright that this one's 101

897

00:46:45,479 --> 00:46:41,859

but just leave that not for anyway

898

00:46:48,749 --> 00:46:45,489

here is here's another thing that kind

899

00:46:51,269 --> 00:46:48,759

of shows you here the concept again of a

900

00:46:53,579 --> 00:46:51,279

large spring representing the joint and

901  
00:46:55,049 --> 00:46:53,589  
a fasteners a little little tiny spring

902  
00:46:59,670 --> 00:46:55,059  
that's trying to compress the big one

903  
00:47:02,309 --> 00:46:59,680  
and of course do keep the fasteners out

904  
00:47:05,190 --> 00:47:02,319  
of trouble you want their stiffness

905  
00:47:07,829 --> 00:47:05,200  
ratio to to the joint to be a pretty

906  
00:47:09,779 --> 00:47:07,839  
large differential and there's there's

907  
00:47:11,130 --> 00:47:09,789  
just showing clamping force all right

908  
00:47:13,469 --> 00:47:11,140  
now you can leave yours up over there

909  
00:47:17,039 --> 00:47:13,479  
and we'll go to the next one here and

910  
00:47:22,279 --> 00:47:17,049  
which we look at a boat remember in

911  
00:47:27,509 --> 00:47:22,289  
school you had calculating the expansion

912  
00:47:29,940 --> 00:47:27,519  
our tensile elongation on a rod and the

913  
00:47:33,509 --> 00:47:29,950

Delta L or change in length was just PL

914

00:47:37,140 --> 00:47:33,519

over AE where P is the axial load ELLs

915

00:47:39,059 --> 00:47:37,150

of the elastic length and a is the rock

916

00:47:43,849 --> 00:47:39,069

cross-section and ease the modulus of

917

00:47:48,569 --> 00:47:43,859

elasticity and so if you apply this to a

918

00:47:51,299 --> 00:47:48,579

a bolt you can calculate these Delta

919

00:47:53,309 --> 00:47:51,309

ELLs for different cross sections and

920

00:47:57,059 --> 00:47:53,319

their lengths and John Bickford uses an

921

00:47:58,680 --> 00:47:57,069

extreme here on the next page in which

922

00:48:01,489 --> 00:47:58,690

he took a bolt that had been machined

923

00:48:06,359 --> 00:48:01,499

all over the place and he calculated a

924

00:48:09,959 --> 00:48:06,369

delta L based on all these different L

925

00:48:13,589 --> 00:48:09,969

over a ratios since since P and E are

926  
00:48:17,519 --> 00:48:13,599  
constant so that that is how you can

927  
00:48:20,670 --> 00:48:17,529  
arrive at a joint stiffness value for

928  
00:48:22,259 --> 00:48:20,680  
the bolt now I mean the stiffness from

929  
00:48:25,799 --> 00:48:22,269  
the bolt but now when you go to the

930  
00:48:29,999 --> 00:48:25,809  
joint there's where the authors disagree

931  
00:48:33,150 --> 00:48:30,009  
and there's all sorts of things so here

932  
00:48:35,900 --> 00:48:33,160  
are three different types of models if

933  
00:48:37,920 --> 00:48:35,910  
you will that are used to calculate

934  
00:48:41,250 --> 00:48:37,930  
joint stiffness

935  
00:48:44,120 --> 00:48:41,260  
the spear although it was listed I

936  
00:48:46,950 --> 00:48:44,130  
couldn't find any equations for it the

937  
00:48:51,570 --> 00:48:46,960  
cylinder is used a lot and the cone is

938  
00:48:53,490 --> 00:48:51,580

used a lot and there are various ways of

939

00:48:55,200 --> 00:48:53,500

calculating the stiffness now what I'm

940

00:48:58,050 --> 00:48:55,210

talking about is if you look at these

941

00:49:06,740 --> 00:48:58,060

the hole here represents the hole where

942

00:49:10,050 --> 00:49:06,750

the bolt would go through okay

943

00:49:12,690 --> 00:49:10,060

now John Bickford uses the cylindrical

944

00:49:15,330 --> 00:49:12,700

model with a modification for eccentric

945

00:49:19,050 --> 00:49:15,340

loading at or near the edge of the joint

946

00:49:23,340 --> 00:49:19,060

and that is if you are wanting to use a

947

00:49:28,110 --> 00:49:23,350

circle and the bolt is close enough to

948

00:49:29,940 --> 00:49:28,120

the edge that you can't get the diameter

949

00:49:31,830 --> 00:49:29,950

circle you want you can put in a fudge

950

00:49:34,800 --> 00:49:31,840

factor for the fact that you're closer

951  
00:49:39,240 --> 00:49:34,810  
to the edge then you should be and this

952  
00:49:41,160 --> 00:49:39,250  
brings up another standard which is used

953  
00:49:43,680 --> 00:49:41,170  
a lot in the industrial world but

954  
00:49:48,060 --> 00:49:43,690  
difficult to obtain so I found out is

955  
00:49:51,570 --> 00:49:48,070  
the German standard Vern Dutch your

956  
00:49:54,240 --> 00:49:51,580  
engineer or other otherwise known as VDI

957  
00:49:56,940 --> 00:49:54,250  
since nobody could pronounce it that is

958  
00:49:59,010 --> 00:49:56,950  
a standard for doing calculations on

959  
00:50:01,170 --> 00:49:59,020  
fasteners that are loading the joint

960  
00:50:06,570 --> 00:50:01,180  
stiffness and all that type of thing and

961  
00:50:07,680 --> 00:50:06,580  
I have a copy of it but I had to get it

962  
00:50:11,810 --> 00:50:07,690  
through the back door because the

963  
00:50:18,000 --> 00:50:15,210

sigelei who wrote a lot of books on

964

00:50:20,820 --> 00:50:18,010

engineering uses the cone frustum model

965

00:50:23,310 --> 00:50:20,830

with a cone angle 45 degrees measured

966

00:50:25,920 --> 00:50:23,320

from the bolt center line and then nasa

967

00:50:27,210 --> 00:50:25,930

langley had had another set up using a

968

00:50:29,220 --> 00:50:27,220

straight cylinder with three different

969

00:50:31,710 --> 00:50:29,230

equations depending on the minimum edge

970

00:50:36,780 --> 00:50:31,720

distance of the shortest side of the

971

00:50:42,720 --> 00:50:36,790

joint then another guy of the name of

972

00:50:45,150 --> 00:50:42,730

alexander blake uses a cone angle with

973

00:50:49,070 --> 00:50:45,160

angle determined by a line drawn from

974

00:50:51,660 --> 00:50:49,080

the outer edge of the flat of the head

975

00:50:54,270 --> 00:50:51,670

to the centerline of the clamp

976  
00:50:56,730 --> 00:50:54,280  
joint so this is the clamp joint here to

977  
00:51:01,950 --> 00:50:56,740  
here and there's a centerline but for

978  
00:51:06,270 --> 00:51:01,960  
the cone comes to and then using all of

979  
00:51:13,049 --> 00:51:06,280  
this stuff all of these measurements to

980  
00:51:16,049 --> 00:51:13,059  
calculate a joint stiffness and he comes

981  
00:51:21,480 --> 00:51:16,059  
up with a nice nice little equation here

982  
00:51:23,640 --> 00:51:21,490  
and this is for a particular angle of 45

983  
00:51:26,490 --> 00:51:23,650  
degrees I believe here no I'm sorry this

984  
00:51:27,569 --> 00:51:26,500  
is the shig Lee method on the cone we

985  
00:51:30,450 --> 00:51:27,579  
have the other one I guess in the

986  
00:51:32,819 --> 00:51:30,460  
appendix but you can have you have an

987  
00:51:35,069 --> 00:51:32,829  
equation there that you can use to

988  
00:51:36,539 --> 00:51:35,079

calculate the joint stiffness so that

989

00:51:38,579 --> 00:51:36,549

you can compare it to your fastener

990

00:51:45,150 --> 00:51:38,589

stiffness to decide whether you're in

991

00:51:49,200 --> 00:51:45,160

trouble or not now as far as the joint

992

00:51:52,500 --> 00:51:49,210

stiffness calculations go here's one of

993

00:51:54,630 --> 00:51:52,510

the bad parts about it the affect of

994

00:51:56,609 --> 00:51:54,640

adjacent fasteners on joint compression

995

00:52:02,130 --> 00:51:56,619

is not accounted for in any of these so

996

00:52:05,180 --> 00:52:02,140

these are all empirical and the there

997

00:52:07,680 --> 00:52:05,190

they're only an indicator then

998

00:52:09,780 --> 00:52:07,690

unsymmetrical loading under a fastener

999

00:52:11,130 --> 00:52:09,790

due to edge distance or cutouts is not

1000

00:52:12,990 --> 00:52:11,140

accounted for in other words you're

1001  
00:52:17,520 --> 00:52:13,000  
using a perfect cone or a perfect

1002  
00:52:21,120 --> 00:52:17,530  
cylinder and then if the bolt and joint

1003  
00:52:23,880 --> 00:52:21,130  
materials are different the stiffness

1004  
00:52:26,760 --> 00:52:23,890  
calculations must account for the

1005  
00:52:32,849 --> 00:52:26,770  
different moduli of elasticity for the

1006  
00:52:35,010 --> 00:52:32,859  
materials now so so you're in in a

1007  
00:52:40,730 --> 00:52:35,020  
little bit of trouble there on getting

1008  
00:52:43,680 --> 00:52:40,740  
these however things could be worse here

1009  
00:52:46,109 --> 00:52:43,690  
are some of the things you can do first

1010  
00:52:48,120 --> 00:52:46,119  
try just a simple cylinder with a radius

1011  
00:52:52,380 --> 00:52:48,130  
equal to the shortest edge distance the

1012  
00:52:54,930 --> 00:52:52,390  
fasteners this is called the barrett

1013  
00:52:57,890 --> 00:52:54,940

theory of least work don't do any more

1014

00:53:00,510 --> 00:52:57,900

than you have to to show something good

1015

00:53:02,970 --> 00:53:00,520

if this stiffness is satisfactory

1016

00:53:04,540 --> 00:53:02,980

compared to the fastener don't go any

1017

00:53:06,820 --> 00:53:04,550

further go with it

1018

00:53:09,460 --> 00:53:06,830

if the simple cylinder is not

1019

00:53:11,350 --> 00:53:09,470

satisfactory add a washer with a

1020

00:53:13,090 --> 00:53:11,360

diameter larger than the fastener head

1021

00:53:17,430 --> 00:53:13,100

to kind of spread out the radius on your

1022

00:53:19,930 --> 00:53:17,440

cylinder then check it for that and

1023

00:53:22,120 --> 00:53:19,940

check the compressive stress under the

1024

00:53:24,490 --> 00:53:22,130

head contact area to make sure that the

1025

00:53:30,400 --> 00:53:24,500

compressive yield will not occur under

1026  
00:53:34,720 --> 00:53:30,410  
the maximum clamping load and then if

1027  
00:53:38,820 --> 00:53:34,730  
all else fails go do the calculations if

1028  
00:53:42,040 --> 00:53:38,830  
it is critical enough now in most cases

1029  
00:53:44,830 --> 00:53:42,050  
you are not critical enough that you

1030  
00:53:47,260 --> 00:53:44,840  
would have to go to a lot of lengths on

1031  
00:53:49,420 --> 00:53:47,270  
the difference between the fastener

1032  
00:53:52,420 --> 00:53:49,430  
stiffness and joint stiffness only a

1033  
00:53:54,730 --> 00:53:52,430  
rare case is now one of the things that

1034  
00:54:00,730 --> 00:53:54,740  
you want to be aware of is don't use a

1035  
00:54:02,890 --> 00:54:00,740  
big fat fastener on a thin joint because

1036  
00:54:04,390 --> 00:54:02,900  
chances are then the fastener is going

1037  
00:54:07,510 --> 00:54:04,400  
to be stiffer than the joint and you're

1038  
00:54:09,880 --> 00:54:07,520

gonna have trouble you've been in

1039

00:54:12,940 --> 00:54:09,890

trouble on it but you can you can check

1040

00:54:15,790 --> 00:54:12,950

them and see what you've got and if if

1041

00:54:17,890 --> 00:54:15,800

your ratio is not too bad even for

1042

00:54:20,860 --> 00:54:17,900

taking that short cut method say 5 or

1043

00:54:25,540 --> 00:54:20,870

something between fastener and joint go

1044

00:54:27,900 --> 00:54:25,550

with it and it should be alright now

1045

00:54:30,370 --> 00:54:27,910

indirect reading of fastener tension

1046

00:54:32,380 --> 00:54:30,380

this question is asked how can I

1047

00:54:33,790 --> 00:54:32,390

determine the exact tension I have on a

1048

00:54:38,020 --> 00:54:33,800

fastener for a given torque

1049

00:54:40,570 --> 00:54:38,030

well the direct reading is possible but

1050

00:54:43,690 --> 00:54:40,580

it's not economically feasible for most

1051  
00:54:46,660 --> 00:54:43,700  
assemblies the technology is there that

1052  
00:54:50,440 --> 00:54:46,670  
you can't afford it so the usual

1053  
00:54:52,270 --> 00:54:50,450  
compromise is to test fasteners under

1054  
00:54:55,360 --> 00:54:52,280  
the closest actual installation

1055  
00:54:58,030 --> 00:54:55,370  
conditions that you can come up with and

1056  
00:54:59,980 --> 00:54:58,040  
determine a torque value then use that

1057  
00:55:03,580 --> 00:54:59,990  
torque value for your production

1058  
00:55:09,760 --> 00:55:03,590  
assemblies and so we'll cover a couple

1059  
00:55:13,390 --> 00:55:09,770  
of the upper three here of the direct

1060  
00:55:17,549 --> 00:55:13,400  
tension measurements now this one an

1061  
00:55:19,839 --> 00:55:17,559  
ultrasonic that's a good one

1062  
00:55:23,469 --> 00:55:19,849  
transducers mounted to the head of the

1063  
00:55:26,019 --> 00:55:23,479

boat but as the bullet elongates the

1064

00:55:28,089 --> 00:55:26,029

travel time for the sound you know the

1065

00:55:30,759 --> 00:55:28,099

way ultrasonics work you bounce it off

1066

00:55:32,829 --> 00:55:30,769

of the back surface and back so if you

1067

00:55:35,829 --> 00:55:32,839

increase the length of the thing it

1068

00:55:38,229 --> 00:55:35,839

takes longer for thee for the ultrasonic

1069

00:55:40,329 --> 00:55:38,239

wave to get there and back so that is a

1070

00:55:42,700 --> 00:55:40,339

you can get a direct correlation between

1071

00:55:44,319 --> 00:55:42,710

the elongation of the boat which knowing

1072

00:55:48,999 --> 00:55:44,329

the cross-sectional area will give you

1073

00:55:52,539 --> 00:55:49,009

the stress well that's a very good thing

1074

00:55:54,009 --> 00:55:52,549

but the major drawback to it is you've

1075

00:55:56,620 --> 00:55:54,019

got to have the smooth surface to attach

1076

00:56:00,640 --> 00:55:56,630

it to because if you remember even if

1077

00:56:02,170 --> 00:56:00,650

you go in and have your heart checked or

1078

00:56:05,380 --> 00:56:02,180

something like that that they use an

1079

00:56:08,200 --> 00:56:05,390

ultrasonic fluid that they put on on

1080

00:56:10,630 --> 00:56:08,210

your body so that because you've got to

1081

00:56:12,279 --> 00:56:10,640

have a medium for it to go through so

1082

00:56:15,069 --> 00:56:12,289

you have to have a nice smooth surface

1083

00:56:17,319 --> 00:56:15,079

and then you have to have some sort of a

1084

00:56:22,089 --> 00:56:17,329

gel on there to put your transducer on

1085

00:56:23,979 --> 00:56:22,099

get it to hold so now what do you do if

1086

00:56:28,319 --> 00:56:23,989

you got a socket head Bowl you don't

1087

00:56:34,509 --> 00:56:31,479

then once the bolt is calibrated for a

1088

00:56:36,339 --> 00:56:34,519

zero load you have to disconnect the

1089

00:56:37,930 --> 00:56:36,349

transducer in order to Terk the bolt

1090

00:56:40,690 --> 00:56:37,940

down to the load you want so that you

1091

00:56:43,870 --> 00:56:40,700

can measure it again so this one is is a

1092

00:56:51,299 --> 00:56:43,880

good method but it's not really

1093

00:56:57,519 --> 00:56:55,599

neck next one is direct scaling now that

1094

00:56:59,920 --> 00:56:57,529

we had mentioned that earlier in which

1095

00:57:02,049 --> 00:56:59,930

where both ends of the installed bolt

1096

00:57:03,759 --> 00:57:02,059

are accessible such as pipe flange you

1097

00:57:05,890 --> 00:57:03,769

can actually measure the bolt and

1098

00:57:10,180 --> 00:57:05,900

subtract out the dead areas that are on

1099

00:57:12,670 --> 00:57:10,190

the the outside of the nut the heads and

1100

00:57:16,539 --> 00:57:12,680

so on and use the elongation there of

1101

00:57:18,579 --> 00:57:16,549

the boat to arrive at a load then of

1102

00:57:21,249 --> 00:57:18,589

course these direct tension indicating

1103

00:57:24,789 --> 00:57:21,259

washers that we covered in the washer

1104

00:57:26,559 --> 00:57:24,799

section those are used successfully in

1105

00:57:28,839 --> 00:57:26,569

the construction business because you

1106

00:57:30,850 --> 00:57:28,849

take a feeler gauge and inspect keep

1107

00:57:37,980 --> 00:57:30,860

talking until you get a gap of a certain

1108

00:57:45,430 --> 00:57:42,340

then we have this test machine by Ralph

1109

00:57:48,520 --> 00:57:45,440

shoberg of RS Technologies Farmington

1110

00:57:52,090 --> 00:57:48,530

Hills Michigan aides are one of my

1111

00:57:55,960 --> 00:57:52,100

fellow compadres on the lecture circuit

1112

00:57:57,460 --> 00:57:55,970

on fasteners and he has a machine that

1113

00:58:01,180 --> 00:57:57,470

will actually you can throw a bolt in it

1114

00:58:03,910 --> 00:58:01,190

and it will tell you for a given bolt

1115

00:58:07,030 --> 00:58:03,920

the exact amount that you have

1116

00:58:09,400 --> 00:58:07,040

pretension the exact amount for head

1117

00:58:12,700 --> 00:58:09,410

friction the exact amount for nut

1118

00:58:15,040 --> 00:58:12,710

friction but the only thing is it'll

1119

00:58:16,540 --> 00:58:15,050

tell you for that bolt it won't tell you

1120

00:58:19,180 --> 00:58:16,550

about your total installation so what

1121

00:58:22,990 --> 00:58:19,190

you have to do is take a bolt that

1122

00:58:24,850 --> 00:58:23,000

you're going to use and decide what you

1123

00:58:27,010 --> 00:58:24,860

want to load it to put it in the machine

1124

00:58:29,020 --> 00:58:27,020

and determine what perk it takes to give

1125

00:58:32,800 --> 00:58:29,030

you that stress and then use that for

