



1
00:00:14,450 --> 00:00:12,830
hi folks my name is Tobias frico I'm an

2
00:00:18,260 --> 00:00:14,460
engineer from Airbus defense in space

3
00:00:22,310 --> 00:00:18,270
and my profession is quality engineer so

4
00:00:25,880 --> 00:00:22,320
I'm in charge of this baby here it's the

5
00:00:27,859 --> 00:00:25,890
STA and I need to make sure that all the

6
00:00:31,150 --> 00:00:27,869
province gets off which occurred during

7
00:00:34,100 --> 00:00:31,160
the assembly and integration phase so

8
00:00:37,549 --> 00:00:34,110
problems like lines are not proper

9
00:00:39,470 --> 00:00:37,559
welded or a school's broke or maybe it's

10
00:00:43,069 --> 00:00:39,480
the wrong part on the wrong position so

11
00:00:45,619 --> 00:00:43,079
this is main task we need to make sure