

36
UNCLASSIFIED

Incident 270 -- near own rails, Iowa -- 12 August 1947

There is clearly nothing abnormal in this accident, apparently it just occurred with out other locomotive derailling.

One possible cause was, however, the "big class" motor, and the fact that the trees "spun around on top as if they were in a vacuum" could this, then, have been a rapidly travelling atmospheric eddy?

UNCLASSIFIED

UNCLASSIFIED